

End-of-Sale and End-of-Life Announcement for the Cisco MGX 8800 Series Legacy Cards

EOL5067

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco MGX 8800 Series Legacy Cards. The last day to order the affected product is September 30, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 in EoL product bulletin.

Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco MGX 8800 Series Legacy Cards. Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Cisco MGX 8800 Series Legacy Cards

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 31, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 31, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 31, 2007
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	October 31, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 31, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	January 31, 2011
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	October 31, 2012

HW = Hardware
 OS SW = Operating System Software
 App SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
MGX-12IN1-8S	8 Port V.35 and X.21 back card for MGX-FRSM-HS2/B	There is currently no replacement product available for this product.	
MGX-12IN1-8S=	8 Port V.35 and X.21 back card for MGX-FRSM-HS2/B	There is currently no replacement product available for this product.	
MGX-FRSM-HS2/B	Frame Service Module, Serial Interface	There is currently no replacement product available for this product.	
MGX-FRSM-HS2/B=	Frame Service Module, Serial Interface	There is currently no replacement product available for this product.	

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
MGX-MMF-FE	Fast Ethernet Back Card for the RPM, MMF connector	There is currently no replacement product available for this product.	
MGX-MMF-FE=	Fast Ethernet Back Card for the RPM, MMF connector	There is currently no replacement product available for this product.	
MGX-RJ45-4E/B	4 port Ethernet Back Card for the RPM—revision B	MGX-RJ45-5-ETH	Auto-sensing 5 E/FE port back card for RPM-PR
MGX-RJ45-4E/B=	4 port Ethernet Back Card for the RPM—revision B	MGX-RJ45-5-ETH=	Auto-sensing 5 E/FE port back card for RPM-PR
MGX-RJ45-FE	Fast Ethernet Back Card for the RPM, RJ45 connector	MGX-RJ45-5-ETH	Auto-sensing 5 E/FE port back card for RPM-PR
MGX-RJ45-FE=	Fast Ethernet Back Card for the RPM, RJ45 connector	MGX-RJ45-5-ETH=	Auto-sensing 5 E/FE port back card for RPM-PR
MGX-RJ48-8E1	Eight Port E1 Back Card with RJ48 Connectors	There is currently no replacement product available for this product.	
MGX-RJ48-8E1=	Eight Port E1 Back Card with RJ48 Connectors	There is currently no replacement product available for this product.	
MGX-SCSI2-2HSSI/B	Two port HSSI back card, SCSI-2 connectors	There is currently no replacement product available for this product.	
MGX-SCSI2-2HSSI/B=	Two port HSSI back card, SCSI-2 connectors	There is currently no replacement product available for this product.	

Product Migration Options

The recommended replacement for the Cisco MGX 8800 Series Legacy Cards is the Cisco MGX Card with Part Number MGX-RJ45-5-ETH.

Customers using cards with part numbers MGX-RJ45-4E and FE are encouraged to migrate to the card with part number MGX-RJ45-5-ETH. Information about this product can be found at:

<http://www.cisco.com/en/US/products/hw/switches/ps1938/ps1935/index.html>

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_high_level_listing.html

For More Information

For more information about the Cisco MGX 8800 Series Legacy Cards, visit http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html, contact your local account representative, or send an e-mail to [Enter Cisco alias].

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-4413 (TTS) (8087)
Fax: 408 527-0888

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Central Tower
Singapore 068972
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6617 7798

Europe Headquarters
Cisco Systems International BV
Hautferbergweg
1101 CL Amsterdam
The Netherlands
www.euro.cisco.com
Tel: +31 20 800 020 0701
Fax: +31 20 20 887 1 100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCNA, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc. Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc. and Access Registrar, Aironet, BPA, Catalyst, CCNA, CCIE, CDE, CCI, CCNA, CCNI, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Certified, the Cisco Systems logo, Cisco Unity, EtherSuite, EtherSet, Eze Switch, Fast Step, Follow Me, iLearning, HomeShare, iGig, iGigDrive, iGigStack, iGigLink, Internet Quotient, IOS, iThru, iTV, IQ, iShare, the IQ logo, IQ Net, iRoadshow, iShareCard, iQuick Start, iLightStream, iLinkage, iMeeting Place, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RepM-X, SeriesShare, SlideCast, SLAX, iPort, SpeedWire, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (08123)