



END-OF-LIFE NOTICE, NO. 2329

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO uBR925 CABLE ACCESS ROUTER

Cisco Systems® announces the End-of-Life of the Cisco® uBR925 Cable Access Router. The last day to order the Cisco uBR925 Cable Access Router is April 30, 2004. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until April 30, 2005. Table 1 describes End-of-Life milestones, definitions, and dates for the Cisco uBR925 Cable Access Router.

Table 1. End-of-Life Milestones and Dates for the Cisco uBR925 Cable Access Router

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the End-of-Sale and End-of-Life of a product is distributed to the general public.	October 31, 2003
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 30, 2004
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	July 30, 2004
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	April 30, 2005
End of Routine Failure Analysis Date	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	April 30, 2005
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 30, 2005
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	January 30, 2009
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2009

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
UBR925-SINGLE-1PK	UBR925—Single Unit in a Box
UBR925-MULTI-5PK	UBR925—Multipack of 5 in one Box

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco uBR925 Cable Access Router is the Cisco uBR905 Cable Access Router (Table 3). The Cisco uBR905 Cable Access Router is identical to the Cisco uBR925 Cable Access Router with the exception that it has no FXS telephony ports and no USB interface. All data-only router functionality is identical to the Cisco uBR925 Cable Access Router.

Table 3. Product Comparisons

Feature	Cisco uBR925 Cable Access Router	Cisco uBR905 Cable Access Router
DOCSIS® bridge-mode	DOCSIS-compliant cable modem mode	This functionality is identical in the Cisco uBR905 and uBR925.
Routing mode including NAT and RIPv2	Advanced cable modem-router allowing small business Internet access	This functionality is identical in the Cisco uBR905 and uBR925.
Easy VPN	Easy teleworker and branch office VPNs	This functionality is identical in the Cisco uBR905 and uBR925.
Two FXS ports	Voice-over-IP functionality for SMBs and teleworkers	This functionality is not available on the Cisco uBR905. Customers may accomplish this functionality by using an IP Phone or ATA device behind the Cisco uBR905, depending upon customer requirements and application.
USB port	USB support for Windows 98 and Windows 2000	This functionality is not available on the Cisco uBR905. Customers should instead use the Cisco uBR905 Ethernet interface.

DOCSIS 1.0 Software Support

Customers requiring DOCSIS 1.0 software for the Cisco uBR925 Cable Access Router should use versions of Cisco IOS® Software Release 12.3. Software releases from this train will be supported as per the software support dates listed above.

DOCSIS 1.1 Software Support

Customers requiring DOCSIS 1.1 software for the Cisco uBR925 Cable Access Router should use versions of Cisco IOS Release 12.3 BC. Software releases from this train will be supported as per the software support dates listed above.

ADDITIONAL INFORMATION

For more information about Cisco products, please contact your Cisco account manager or Cisco Channels Partner.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive EoL/EoS information, please go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

DOCSIS is a registered trademark of Cable Television Laboratories, Inc. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

