



PRODUCT BULLETIN NO. **EOL5076**

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE **CISCO PIX FIREWALL OS VERSION 4.4**

Cisco Systems® announces the end-of-sale and end-of life dates for the [Cisco PIX Firewall OS Version 4.4](#). The last day to order the affected product is [June 26, 2002](#). Customers with active service contracts will continue to receive support from the [Cisco Technical Assistance Center \(TAC\)](#) as shown in [Table 1](#) in [EoL product bulletin](#). [Table 1](#) describes the end-of-life milestones, definitions, and dates for the Cisco PIX Firewall OS Version 4.4.

Table 1. End-of-Life Milestones and Dates for the [Cisco PIX Firewall OS Version 4.4](#).

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 26, 2002
Last Date of Support: OS SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 26, 2002

HW = Hardware OS SW = Operating System Software App SW = Application Software

PRODUCT MIGRATION OPTIONS

512-KB/2-MB FLASH MEMORY UPGRADE

Customers with Cisco PIX "Classic," 10000, 510, and select 520 Firewall units must upgrade these units to a minimum of 16 MB in order to run the 5.2 software train. The Cisco part number PIX-FLASH-16MB= meets these requirements.

Cisco PIX 515 and 525 Firewall units ship with 16 MB of Flash and are not affected. PIX 520 Firewalls manufactured after February of 2000, with serial numbers 18025677 and higher, are not affected. The Cisco PIX 506 has 8 MB of Flash memory, which works correctly with Version 5.2 of the software.

8-/16-MB RAM UPGRADE

Cisco PIX "Classic," 10000, and 510 Firewall units must be upgraded to a minimum of 32-MB RAM in order to run Cisco PIX Firewall Version 5.2 of the software. Cisco part number PIX-MEM-UPG-128= meets these requirements for the "Classic" and 10000 units; Cisco part number PIX-MEM-5XX-128= meets these requirements for the 510 Firewall units.

Customers with Cisco PIX 501, 506, 506E, 515, 515E, 52x, 525, or 535 Firewall units are not affected.

FOR MORE INFORMATION

For more information about the [Cisco PIX Firewall OS Version 4.4](#), visit http://www.cisco.com/en/US/products/hw/vpndevc/ps2030/prod_eol_notices_list.html or contact your local account representative.



For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA
95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA
95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital
Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)

Printed in the USA