

Cisco 12000 Series Line Cards with Part Numbers POC48E/POS-1550-SC and FC, and POC48E/POS-SR-SC and FC End-of-Life Announcement



Cisco Systems is announcing the end of life for the four-port OC-12/STM-4 line cards with Part Numbers POC48E/POS-1550-SC and FC, POC48E/POS-SR-SC and FC. The same functionality and feature set is available on the new OC48E/POS-1550-SC and FC, OC48E/POS-SR-SC and FC.

Models Covered by This End-of-Life Announcement

Product Number	Product Description
Cisco 12000 Series Products	
POC48E/POS-1550-SC	One-port OC-48c/STM-16c SONET/SDH with Enhanced Upgrade 1550 nm LR with SC
POC48E/POS-1550-FC	One-port OC-48c/STM-16c SONET/SDH with Enhanced Upgrade 1550 nm LR with FC
POC48E/POS-SR-SC	One-port OC-48c/STM-16c SONET/SDH with Enhanced Upgrade—1310 nm SR with SC
POC48E/POS-SR-FC	One-port OC-48c/STM-16c SONET/SDH with Enhanced Upgrade—1310 nm SR with FC

Key Dates:

Milestone	TTM OC-48 Versions
FCS Date	10/04/1998
End-of-sales on TTM OC-48	10/04/1999
End-of-contract Renewals	10/01/2002
End-of-support	10/01/2000

End-of-Sales for TTM OC-48

The first production versions of the OC-48 POS line card known as TTM OC-48 are not orderable after October 4, 1999.

Upgrade

Customers that have purchased TTM OC48 POS line cards have one year from the end-of-sale announcement to upgrade, for free, to Performance-based (Perf) OC48 line cards. An active program will be in place for the year-long period, where customers will have the option to automatically receive free upgrades. The upgrades will only be authorized if a TTM OC48 POS sales order can be referred to.

After October 2000, upgrades to Perf OC48 POS need to use the standard Technology Migration Plan (TMP) credit program.

Calculations for credits or trade-in values can be found by using the TMP calculator found at:

<http://www.cisco.com/go/tradein>

End-of-Contract Renewals

Service contracts on these products will not be renewed after October 2002.

End-of-Support

The TTM line cards will be supported by Cisco TAC until October 2002, but no changes to the functionality of the line card, or enhancements can be made under any conditions. If issues with the TTM OC48 card arise and additional capabilities are necessary or there are issues with existing functionality, then the card needs to be upgraded to the Perf OC48 POS line card.

If you have questions or need more information, please contact your Cisco account representative.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems Europe
11, Rue Camille Desmoulins
92782 Issy-les-Moulineaux
Cedex 9
France
www-europe.cisco.com
Tel: 33 1 58 04 60 00
Fax: 33 1 58 04 61 00

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the

Cisco Web site at www.cisco.com/go/offices

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia
Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru
Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa
Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2001, Cisco Systems, Inc. All rights reserved. AccessPath, AtmDirector, Browse with Me, CCIP, CCSI, CD-PAC, *CiscoLink*, the Cisco *Powered* Network logo, Cisco Systems Networking Academy, the Cisco Systems Networking Academy logo, Cisco Unity, Fast Step, Follow Me Browsing, FormShare, FrameShare, IGX, Internet Quotient, IP/VC, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, MGX, the Networkers logo, ScriptBuilder, ScriptShare, SMARTnet, TransPath, Voice LAN, Wavelength Router, and WebViewer are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn and Discover All That's Possible are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, FastHub, FastSwitch, GigaStack, IOS, IP/TV, LightStream, MICA, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0110R)