



Cisco IOS Packaging Image Removal Program for Cisco 1000, 1005, 3000, 7000 Series Routers; and RSP7000

Cisco IOS® Image Removal is part of the company-wide Cisco IOS Packaging initiatives. The goal of this program is to simplify the Cisco IOS Software image selection process by removing older images from Cisco.com. It will also direct engineering efforts to high-volume images, thus increasing the stability and reliability of Cisco IOS Software.

This product bulletin serves as notification for the discontinuation of Cisco IOS Software Images for Cisco 1000, 1005, 3000, and 7000 Series Routers, and the RSP7000 platform. As for Cisco IOS Software Release 12.2, the images pertaining to these platforms will no longer be available.

A select number of Cisco IOS Software images have been identified as the migration path for the above-mentioned platforms. This is intended to assist any remaining customers who still use old images on these platforms. These identified images, listed below, will be available on Cisco.com until the end of 2003.

Cisco IOS Software
Release 11.1—1 Image
[/cisco/ios/11.1/11.1.24b/1000/c1000-rboot-mz.111-24b.bin](#)

Cisco IOS Software
Release 11.2—2 Images
[/cisco/ios/11.2/11.2.9/1005/c1005-bnsy56-mz.112-9.bin](#)
[/cisco/ios/11.2/11.2.9/1000/c1000-bnsy56-mz.112-9.bin](#)

Cisco IOS Software
Release 11.3—15 Images
[/cisco/ios/11.3/11.3.11c/1000/c1000-bnsy-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1000/c1000-bnsy40-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1000/c1000-bnsy56-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1000/c1000-bny-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1000/c1000-ny-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1000/c1000-y-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1005/c1005-bnsy-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1005/c1005-bnsy40-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1005/c1005-bnsy56-mz.113-11c.bin](#)
[/cisco/ios/11.3/11.3.11c/1005/c1005-bny-mz.113-11c.bin](#)



/cisco/ios/11.3/11.3.11c/1005/c1005-nqy-mz.113-11c.bin
/cisco/ios/11.3/11.3.11c/1005/c1005-ny-mz.113-11c.bin
/cisco/ios/11.3/11.3.11c/1005/c1005-qy-mz.113-11c.bin
/cisco/ios/11.3/11.3.11c/1005/c1005-y-mz.113-11c.bin
/cisco/ios/11.3/11.3.11c/1005/c1005-y2-mz.113-11c.bin

Cisco IOS Software Release 12.0—24 Images

/cisco/ios/12.0/12.0.7T2/1000/c1000-bnsy-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1000/c1000-bny-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1000/c1000-y-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.23/1000/c1000-bnsy-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1000/c1000-bnsy40-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1000/c1000-bnsy56-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1000/c1000-bny-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1000/c1000-ny-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1000/c1000-y-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-bnsy-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-bnsy40-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-bnsy56-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-bny-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-nqy-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-ny-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-qy-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-y-mz.120-23.bin
/cisco/ios/12.0/12.0.23/1005/c1005-y2-mz.120-23.bin
/cisco/ios/12.0/12.0.7T2/1005/c1005-bnsy-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1005/c1005-bny-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1005/c1005-nqy-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1005/c1005-qy-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1005/c1005-y-mz.120-7.T2.bin
/cisco/ios/12.0/12.0.7T2/1005/c1005-y2-mz.120-7.T2.bin

Cisco IOS Software Release 12.1—6 Images

/cisco/ios/12.1/12.1.8c/1000/c1000-y-mz.121-8c.bin

/cisco/ios/12.1/12.1.9/1000/c1000-y-mz.121-9.bin

/cisco/ios/12.1/12.1.9a/1000/c1000-y-mz.121-9a.bin

/cisco/ios/12.1/12.1.8c/1005/c1005-y-mz.121-8c.bin

/cisco/ios/12.1/12.1.9/1005/c1005-y-mz.121-9.bin

/cisco/ios/12.1/12.1.9a/1005/c1005-y-mz.121-9a.bin

Effective December 2002, all other Cisco IOS Software Images for Cisco 1000, 1005, 3000, and 7000 Series Routers, and the RSP7000 platform will no longer be available.

For additional information regarding Cisco IOS Software release dates and milestones, including the most recent schedules governing End of Sales and End of Life for all software trains and images, please refer to Cisco IOS Software Release Dates and Milestones, Product Bulletin No. 367:

http://www.cisco.com/warp/public/cc/pd/iosw/iore/prodlit/367_pp.htm

All the Cisco IOS Software images referred to in this document will remain in the ftp server for one quarter. They can be site published by the Technical Assistance Center (TAC) based on archive in /auto/release/XXX.

For questions regarding this product bulletin, please contact Cisco IOS Software Product Management.



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
Capital Tower
168 Robinson Road
#22-01 to #29-01
Singapore 068912
www.cisco.com
Tel: +65 317 7777
Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Web site at www.cisco.com/go/offices**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992-2002, Cisco Systems, Inc. All rights reserved. CCIP, the Cisco Arrow logo, the Cisco Powered Network mark, the Cisco Systems Verified logo, Cisco Unity, Follow Me Browsing, FormShare, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0208R) ETMG/10.02