

Release Notes for the Cisco RV0xx Series V3 Multi-WAN VPN Routers Firmware Version 4.2.3.07

November 2015

This document describes the resolved and known issues in the Cisco RV0xx Series V3 Multi-WAN VPN Routers firmware version 4.2.3.07.

Contents

[Changes Since Firmware Version 4.2.3.06, page 2](#)

[Related Information, page 3](#)

Changes Since Firmware Version 4.2.3.06

Resolved Issues

The following issues were resolved in firmware version 4.2.3.07:

Ref Number	Description
CSCuw38521	SSL error for weak ephemeral DH key.

Known Issues

The following caveats are carried over from firmware version 4.2.3.06:

Ref Number	Description
CSCug30363	The router is unable to block HTTP traffic on proxy servers. Workaround: No workaround.
CSCtx08218	The router does not expand its dynamic IP range when the subnet mask value is decremented, for example, when the mask is changed from 255.255.255.252 to 255.255.255.248. Workaround: Manually change the IP address range on the DHCP > DHCP Setup page.

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Cisco Small Business Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco Small Business RV Series Routers	www.cisco.com/go/smallbizrouters
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2014 Cisco Systems, Inc. All rights reserved.

OL-32110-01