

Release Notes for Cisco RV130W Router Firmware Version 1.0.3.44

October 2018

This document describes known and resolved issues in the Cisco RV130W
Firmware Version 1.0.3.44

Contents

- [Resolved Issues](#)
- [Related Information](#)

Resolved Issues

Caveats Resolved in Release 1.0.3.44

Number	Description
CSCvj50355	The use of an apostrophe in the Pre-Shared Key field in the IPsec VPN Server setup section leads to page corruption. Workaround: Do not use or include any apostrophe character in the pre-shared key(s).
CSCvd19265	RV130x-WB: HTTPS sites intermittently not loading. Solution: Fixed
CSCvh02816	RV130 - Adding IKE Policy with IP address / FQDN combination is not possible, there is an error. Solution: Fixed
CSCuz56638	Block Access Rule block traffic that should be allowed. Solution: Fixed
CSCvh67990	Upgrade dnsmasq version (1.10) to avoid DNS Cache Poisoning. Solution: Fixed

Enhancements

The RV130x series routers support has algorithm SHA2-256 in IPsec certification.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp

Cisco Firmware Downloads	www.cisco.com/go/software Select a link to download firmware for Cisco Small Business Products. No login is required.
Product Documentation	
Cisco RV Series Routers	www.cisco.com/go/smallbizrouters

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2018 Cisco Systems, Inc. All rights reserved.