

Release Notes for the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.0.17

June 2016

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version 1.0.0.17.

Enhancements

Support Japanese Online Help

Known Issues

The following table lists the known issues in firmware version 1.0.0.15:

Ref Number	Description
CSCux49554	<p>When using MAC OS connect to CiscoSB-Setup, a page pops up but fails to login.</p> <p>Workaround Please use different OS clients to connect to CiscoSB-Setup.</p>

Release Notes

Resolved Issues

CSCuy62078 Low performance on WAP571E-K-K9.

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP571 and WAP571E	www.cisco.com/go/500_wap_resources
Regulatory Compliance and Safety Information	http://www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap571_571E/RCSI/EU-RCSI_WAP571.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2016 Cisco Systems, Inc. All rights reserved.