

Release Notes for Cisco WAP571/571E Wireless-AC Dual Radio Access Points Firmware Version (1.0.0.17-1.0.0.12)

Contents

This document includes the following topics:

- [Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.17, on page 1](#)
- [Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.16, on page 2](#)
- [Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.15, on page 3](#)
- [Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.14, on page 5](#)
- [Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.12, on page 5](#)
- [Related Information on page 7](#)

Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.17

Jan 2016

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.0.17.

Release Notes

New Features and Enhancements

Support Japanese Online Help.

Known Issues

The following table lists the known issues in firmware version 1.0.0.15:

Ref Number	Description
CSCux49554	Symptom: When using MAC OS connect to CiscoSB-Setup, a page pops up but fails to login. Workaround: Please use different OS clients to connect to CiscoSB-Setup.

Resolved Issues

The following table lists the resolved issues in firmware version 1.0.0.15:

Ref Number	Description
CSCuy62078	Symptom: Low performance on WAP571E-K-K9.

Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.16

May 2016

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.0.16.

New Features and Enhancements

Support Japanese GUI and power table

Known Issues

The following table lists the known issues in firmware version 1.0.0.15:

Ref Number	Description
CSCux49554	Symptom: When using MAC OS connect to CiscoSB-Setup, a page pops up but fails to login. Workaround: Please use different OS clients to connect to CiscoSB-Setup.

Resolved Issues

The following table lists the resolved issues in firmware version 1.0.0.16:

Ref Number	Description
CSCuy62078	Symptom: Low performance on WAP571E-K-K9.

Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.15

March 2016

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.0.15.

Release Notes

Known Issues

The following table lists the known issues in firmware version 1.0.0.15:

Ref Number	Description
CSCux49554	Symptom: When using MAC OS connect to CiscoSB-Setup, a page pops up but fails to login. Workaround: Please use different OS clients to connect to CiscoSB-Setup.

Resolved Issues

The following table lists the resolved issues in firmware version 1.0.0.15:

Ref Number	Description
CSCuy62078	Symptom: Low performance on WAP571E-K-K9.

Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.14

March 2016

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.0.14.

Known Issues

The following table lists the known issues in firmware version 1.0.0.14:

Ref Number	Description
CSCux49554	<p>Symptom: When using MAC OS connect to CiscoSB-Setup, a page pops up but fails to login.</p> <p>Workaround: Please use different OS clients to connect to CiscoSB-Setup.</p>

Resolved Issues

The following table lists the resolved issues in firmware version 1.0.0.14::

Ref Number	Description
CSCux65561	<p>Symptom: WAP571E-E-K9 does not support WGB mode for radio1.</p>

Cisco WAP571/571E Wireless-AC Dual Radio Access Points, Firmware Version 1.0.0.12

December 2015

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.0.12.

Release Notes

Known Issues

The following table lists the known issues in firmware version 1.0.0.12:

Ref Number	Description
CSCux26136	<p data-bbox="683 516 1495 590">Symptom: Spectrum Analysis page can not work normally via Bonjour address access.</p> <p data-bbox="683 611 1479 684">Workaround: Spectrum Analysis can be configured via GUI. Currently Bonjour is not supported.</p>

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/sbsc
Cisco Small Business Firmware Downloads	<p>www.cisco.com/go/smallbizfirmware</p> <p>Select a link to download firmware for Cisco Small Business Products. No login is required.</p> <p>Downloads for all other Cisco Small Business products, including Network Storage Systems, are available in the Download area on Cisco.com at www.cisco.com/go/software (registration/login required).</p>
Cisco Small Business Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP571 and WAP571E	www.cisco.com/go/500_wap_resources
Regulatory Compliance and Safety Information	http://www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap571_571E/RCSI/EU-RCSI_WAP571.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2020 Cisco Systems, Inc. All rights reserved.

78-20374-05