

Release Notes for the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version 1.0.1.11

Nov 2017

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version 1.0.1.11.

Enhancements

Support of new EU regulation

Resolved Issues

The following issues have been fixed in firmware version 1.0.1.11

- CSCvf96820 - Key Reinstallation attacks against WPA protocol

Known Issues

The following table lists the known issues in firmware version 1.0.0.10:

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly. Workaround None

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	http://www.cisco.com/go/sbsc
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP571 and WAP571E	www.cisco.com/go/500_wap_resources
Regulatory Compliance and Safety Information	http://www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap571_571E/RCSI/EU-RCSI_WAP571.pdf
Warranty Information	www.cisco.com/go/warranty

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2017 Cisco Systems, Inc. All rights reserved.