

## Update on Labels for Transceiver Modules

PB631278

In order to protect customers and help them to identify genuine Cisco® transceivers, Cisco is introducing new security features on the labels attached to products from Transceiver Module Group.

These features are already implemented on the following product IDs:

- WS-G5484
- WS-G5486
- GLC-SX-MM
- GLC-LH-SM
- GLC-T

And those will be deployed between September and December 2010 on:

- X2-10GB-SR
- X2-10GB-LRM
- X2-10GB-LR
- SFP-10G-SR
- SFP-10G-LRM
- SFP-10G-LR

### For More Information

For more information about Cisco Transceiver Modules, visit

[http://www.cisco.com/en/US/products/hw/modules/ps5455/prod\\_module\\_series\\_home.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/prod_module_series_home.html).

You might also find links to all transceiver module installation guides at

[http://www.cisco.com/en/US/products/hw/modules/ps5455/prod\\_installation\\_guides\\_list.html](http://www.cisco.com/en/US/products/hw/modules/ps5455/prod_installation_guides_list.html).

If you have further questions or suggestions, contact your local account representative.



---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)