

# End-of-Sale and End-of-Life Announcement for the Cisco MDS NX-OS 8.4(2f), 9.2(1), 9.2(1a)



# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	7
For more information	7

## Overview

### EOL15704

Cisco announces the end-of-sale and end-of-life dates for the Cisco MDS NX-OS 8.4(2f), 9.2(1), 9.2(1a). The last day to order the affected product(s) is October 23, 2025. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

## End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco MDS NX-OS 8.4(2f), 9.2(1), 9.2(1a)

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	July 23, 2025
<b>End-of-Sale Date: OS SW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 23, 2025
<b>Last Ship Date: OS SW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	January 23, 2026
<b>End of SW Maintenance Releases Date: OS SW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	October 23, 2026
<b>End of Vulnerability/Security Support: OS SW</b>	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	October 23, 2026
<b>End of New Service Attachment Date: OS SW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	October 23, 2026
<b>End of Service Contract Renewal Date: OS SW</b>	The last date to extend or renew a service contract for the product.	September 30, 2028
<b>Last Date of Support: OS SW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 30, 2029

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>M91S6K9-8.4.2F</b>	MDS 9132T NX-OS version 8.4(2)F	M91S6K9-9.4.3A	MDS 9132T NX-OS version 9.4.3A	-
<b>M91S6K9-NPE-8.4.2F</b>	MDS 9132T 32G FC NX-OS NPE Software Rel. 8.4(2)F	M91S6K9-N9.4.3A	MDS 9132T 32G FC NX-OS NPE Software Rel. 9.4.3A	-
<b>M9148S6K9-8.4.2F</b>	MDS 9148T NX-OS version 8.4(2)F	M9148S6K9-9.4.3A	MDS 9148T NX-OS version 9.4.3A	-
<b>M9148S6K9NPE8.4.2F</b>	MDS 9148T 16G FC NX-OS NPE Software Rel. 8.4(2)F	M9148S6K9-N9.4.3A	MDS 9148T NX-OS version 9.4.3A	-
<b>M92S7K9-8.4.2F</b>	MDS 9220i 32G FCIP Switch NX-OS version 8.4.2F	M92S7K9-9.4.3A	MDS 9220i 32G FCIP Switch NX-OS version 9.4.3A	-
<b>M92S7K9-NPE-8.4.2F</b>	MDS 9220i 32G FCIP Switch, NX-OS NPE SW Release 8.4.2F	M92S7K9-N9.4.3A	MDS 9220i 32G FCIP Switch, NX-OS NPE SW Release 9.4.3A	-
<b>M93S2K9-8.4.2F</b>	MDS 9396T NX-OS version 8.4(2)F	M93S2K9-9.4.3A	MDS 9396T NX-OS version 9.4.3A	-
<b>M93S2K9-NPE-8.4.2F</b>	Cisco MDS 9396T 32G FC NPE Software version 8.4(2)F	M93S2K9-N9.4.3A	Cisco MDS 9396T 32G FC NPE Software version 9.4.3A	-
<b>M97S4K9-8.4.2F</b>	MDS 9700 NX-OS Software Release 8.4(2)F for booting on Sup-4	M97S4K9-9.4.3A	MDS 9700 NX-OS Software Release 9.4.3A for booting on Sup-4	-
<b>M97S4K9-NPE-8.4.2F</b>	MDS 9700 NX-OS NPE version 8.4(2)F for Sup-4	M97S4K9-N9.4.3A	Restricted Use: MDS 9700 NX-OS NPE version 9.4.3A for Sup-4	-
<b>M91S6K9-9.2.1A</b>	MDS 9132T NX-OS version 9.2.1(A)	M91S6K9-9.4.3A	MDS 9132T NX-OS version 9.4.3A	-
<b>M91S6K9-NPE-9.2.1A</b>	MDS 9132T 32G FC NX-OS NPE Software Rel. 9.2.1(A)	M91S6K9-N9.4.3A	MDS 9132T 32G FC NX-OS NPE Software Rel. 9.4.3A	-
<b>M91S5K9-9.2.1A</b>	MDS 9148S NX-OS version 9.2.1(A)	M91S5K9-9.3.2	MDS 9148S NX-OS version 9.3.2	-
<b>M91S5K9-NPE-9.2.1A</b>	Cisco MDS 9148S 16G FC - NPE Software Image 9.2.1(A)	M91S5K9-N9.3.2	Cisco MDS 9148S 16G FC - NPE Software Image 9.3.2	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>M9148S6K9-9.2.1A</b>	MDS 9148T NX-OS version 9.2.1(A)	M9148S6K9-9.4.3A	MDS 9148T NX-OS version 9.4.3A	-
<b>M92S5K9-9.2.1A</b>	MDS 9250i NX-OS version 9.2.1(A)	M92S5K9-9.4.1	MDS 9250i NX-OS version 9.4.1	-
<b>M92S5K9-NPE-9.2.1A</b>	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 9.2.1(A)	M92S5K9-N9.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 9.4.1	-
<b>M92S7K9-9.2.1A</b>	MDS 9220i 32G FCIP Switch NX-OS version 9.2.1(A)	M92S7K9-9.4.3A	MDS 9220i 32G FCIP Switch NX-OS version 9.4.3A	-
<b>M92S7K9-NPE-9.2.1A</b>	MDS 9220i 32G FCIP Switch, NX-OS NPE SW Release 9.2.1(A)	M92S7K9-N9.4.3A	MDS 9220i 32G FCIP Switch, NX-OS NPE SW Release 9.4.3A	-
<b>M93S1K9-9.2.1A</b>	MDS 9396S NX-OS version 9.2.1(A)	M93S1K9-9.3.2	MDS 9396S NX-OS version 9.3.2	-
<b>M93S1K9-NPE-9.2.1A</b>	Cisco MDS 9396S 16G NXOS NPE Software Image 9.2.1(A)	M93S1K9-N9.3.2	Cisco MDS 9396S 16G NXOS NPE Software Image 9.3.2	-
<b>M93S2K9-NPE-9.2.1A</b>	Cisco MDS 9396T 32G FC NPE Software version 9.2.1(A)	M93S2K9-N9.4.3A	Cisco MDS 9396T 32G FC NPE Software version 9.4.3A	-
<b>M97S3K9-9.2.1A</b>	MDS 9700 NX-OS Software Release 9.2.1(A for booting on Sup-1	M97S3K9-9.3.2	MDS 9700 NX-OS Software Release 9.3.2 for booting on Sup-1	-
<b>M97S3K9-NPE-9.2.1A</b>	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 9.2.1(A)	M97S3K9-N9.3.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 9.3.1	-
<b>M97S4K9-9.2.1A</b>	MDS 9700 NX-OS Software Release 9.2.1(A)for booting on Sup-4	M97S4K9-9.4.3A	MDS 9700 NX-OS Software Release 9.4.3A for booting on Sup-4	-
<b>M97S4K9-NPE-9.2.1A</b>	MDS 9700 NX-OS NPE version 9.2.1(A) for Sup-4	M97S4K9-N9.4.3A	Restricted Use: MDS 9700 NX-OS NPE version 9.4.3A for Sup-4	-
<b>M92S7K9-9.2.1</b>	MDS 9220i 32G FCIP Switch NX-OS version 9.2.1	M92S7K9-9.4.3A	MDS 9220i 32G FCIP Switch NX-OS version 9.4.3A	-
<b>M92S7K9-NPE-9.2.1</b>	MDS 9220i 32G FCIP Switch, NX-OS NPE SW Release 9.2.1	M92S7K9-N9.4.3A	MDS 9220i 32G FCIP Switch, NX-OS NPE SW Release 9.4.3A	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
<b>M92S5K9-9.2.1</b>	MDS 9250i NX-OS version 9.2.1	M92S5K9-9.4.1	MDS 9250i NX-OS version 9.4.1	-
<b>M92S5K9-NPE-9.2.1</b>	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 9.2.1	M92S5K9-N9.4.1	MDS 9250i Supervisor/Fabric-3, NX-OS NPE SW Release 9.4.1	-
<b>M97S3K9-9.2.1</b>	MDS 9700 NX-OS Software Release 9.2.1 for booting on Sup-1	M97S3K9-9.3.2	MDS 9700 NX-OS Software Release 9.3.2 for booting on Sup-1	-
<b>M97S3K9-NPE-9.2.1</b>	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 9.2.1	M97S3K9-N9.3.1	MDS 9700 Sup-1/Fab-1, NX-OS NPE SW Release 9.3.1	-
<b>M97S4K9-9.2.1</b>	MDS 9700 NX-OS Software Release 9.2.1 for booting on Sup-4	M97S4K9-9.4.3A	MDS 9700 NX-OS Software Release 9.4.3A for booting on Sup-4	-
<b>M97S4K9-NPE-9.2.1</b>	MDS 9700 NX-OS NPE version 9.2.1 for Sup-4	M97S4K9-N9.4.3A	Restricted Use: MDS 9700 NX-OS NPE version 9.4.3A for Sup-4	-
<b>M91S6K9-9.2.1</b>	MDS 9132T NX-OS version 9.2.1	M91S6K9-9.4.3A	MDS 9132T NX-OS version 9.4.3A	-
<b>M91S6K9-NPE-9.2.1</b>	MDS 9132T 32G FC NX-OS NPE Software Rel. 9.2.1	M91S6K9-N9.4.3A	MDS 9132T 32G FC NX-OS NPE Software Rel. 9.4.3A	-
<b>M91S5K9-9.2.1</b>	MDS 9148S NX-OS version 9.2.1	M91S5K9-9.3.2	MDS 9148S NX-OS version 9.3.2	-
<b>M91S5K9-NPE-9.2.1</b>	Cisco MDS 9148S 16G FC - NPE Software Image 9.2.1	M91S5K9-N9.3.2	Cisco MDS 9148S 16G FC - NPE Software Image 9.3.2	-
<b>M93S1K9-NPE-9.2.1</b>	Cisco MDS 9396S 16G NXOS NPE Software Image 9.2.1	M93S1K9-N9.3.2	Cisco MDS 9396S 16G NXOS NPE Software Image 9.3.2	-
<b>M93S2K9-9.2.1</b>	MDS 9396T NX-OS version 9.2.1	M93S2K9-9.4.3A	MDS 9396T NX-OS version 9.4.3A	-
<b>M93S2K9-NPE-9.2.1</b>	Cisco MDS 9396T 32G FC NPE Software version 9.2.1	M93S2K9-N9.4.3A	Cisco MDS 9396T 32G FC NPE Software version 9.4.3A	-
<b>M9148S6K9-9.2.1</b>	MDS 9148T NX-OS version 9.2.1	M9148S6K9-9.4.3A	MDS 9148T NX-OS version 9.4.3A	-

---

## Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

[https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco MDS NX-OS 8.4(2f), 9.2(1), 9.2(1a) through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to:

<https://www.cisco.com/c/en/us/products/remanufactured.html>.

## For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)