

## Annnonce d'arrêt de commercialisation et de fin de vie de Logiciel Cisco MDS 9000 NX-OS v. 5.x

### EOL10370

Cisco annonce la date d'arrêt de commercialisation et de fin de vie de Logiciel Cisco MDS 9000 NX-OS v. 5.x. Les clients ont jusqu'au 13 novembre 2015 pour commander les produits concernés. Le centre d'assistance technique de Cisco (TAC) continuera de prendre en charge les clients dont les contrats de service sont en cours, comme illustré dans le tableau 1 du bulletin de fin de vie des produits. Le tableau 1 décrit les étapes et donne les définitions et les dates relatives aux produits concernés. Le tableau 2 répertorie les numéros de référence des pièces du produit qui est l'objet du présent avis. Pour les clients dont les contrats de service et d'assistance sont en cours et qui ont été payés, la prise en charge se fera selon les modalités desdits contrats.

**Tableau 1.** Étapes et dates relatives à la fin de vie de Logiciel Cisco MDS 9000 NX-OS v. 5.x

| Étape  | Définition   | Date             |
|--|--|------------------|
| <b>Date d'annonce de fin de vie</b>                                      | Date à laquelle le document annonçant la fin de commercialisation et la fin de vie d'un produit est diffusé au grand public.   | 15 mai 2015      |
| <b>Date de fin de commercialisation</b>                                  | Date limite de commande du produit auprès des points de vente Cisco. Passée cette date, le produit ne sera plus en vente.  | 13 novembre 2015 |
| <b>Dernière date de livraison: OS SW</b>                                 | Date limite jusqu'à laquelle une livraison pourra être demandée à Cisco et/ou ses sous-traitants. La date de livraison réelle dépend du délai d'exécution.   | 11 février 2016  |
| <b>Date de la dernière version de maintenance: OS SW</b>                 | Dernière date à laquelle les équipes techniques de Cisco peuvent proposer une version de maintenance finale ou un correctif. Après cette date, les équipes techniques de Cisco ne seront plus chargées de développer, réparer, gérer ou tester les logiciels du produit.                           | 12 novembre 2016 |
| <b>Date de dernière modification des contrats de service: OS SW</b>      | Pour les équipements et les logiciels non couverts par un contrat de service et d'assistance, dernière date à laquelle il est possible de commander un nouveau contrat de service et d'assistance, ou d'ajouter un équipement et/ou un logiciel à un contrat de service et d'assistance existant.  | 12 novembre 2016 |
| <b>Date de l'arrêt des renouvellements de contrats de service: OS SW</b> | Date limite pour prolonger ou reconduire un contrat de service pour le produit.  | 8 février 2020   |
| <b>Date de fin d'assistance : OS SW</b>                                  | La date jusqu'à laquelle le client peut bénéficier d'une assistance et de réparations du produit selon les modalités du contrat de service ou les conditions générales de la garantie. Après cette date, le produit ne fait plus l'objet de services d'assistance et est considéré comme obsolète. | 30 novembre 2020 |

HW = Matériel

OS SW = Système d'exploitation

App. SW = Logiciel d'application

**Tableau 2.** Numéros de référence des pièces du produit affecté par le présent avis

| Numéro de référence de la pièce du produit en fin de commercialisation | Description du produit                                       | Numéro de référence de la pièce de remplacement pour le produit | Description du produit de remplacement                      | Informations complémentaires |
|--|--|---|---|------------------------------|
| <b>M91S2K9-5.0.1A</b>  | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.0(1A) | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.0.1A</b>  | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.0(1A) | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S2K9-5.0.4</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.0(4)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.0.4</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.0(4)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S2K9-5.2.1</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(1)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.2.1</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(1)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S2K9-5.2.1A</b>  | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(1A) | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.2.1A</b>  | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(1A) | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S2K9-5.2.2</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(2)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.2.2</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(2)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S2K9-5.2.6</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.2.6</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S2K9-5.2.8</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S2K9-5.2.8</b>   | MDS 9100 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.0.1A</b>  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.0(1A) | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |

| Numéro de référence de la pièce du produit en fin de commercialisation | Description du produit                                       | Numéro de référence de la pièce de remplacement pour le produit | Description du produit de remplacement                      | Informations complémentaires |
|--|--|---|---|------------------------------|
| <b>M91S3K9-5.0.1A</b>  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.0(1A) | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.0.1B</b>  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.0(1B) | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.0.1B</b>  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.0(1B) | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.0.4</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.0(4)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.0.4</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.0(4)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.2.1</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(1)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.2.1</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(1)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.2.1A</b>  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(1A) | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.2.1A</b>  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(1A) | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.2.2</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(2)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.2.2</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(2)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.2.6</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(6)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.2.6</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(6)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |
| <b>M91S3K9-5.2.8</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(8)  | M91S3K9-6.2.7   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.7  |                              |
| <b>M91S3K9-5.2.8</b>   | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 5.2(8)  | M91S3K9-6.2.9A  | MDS 9100 Supervisor/Fabric-3, NX-OS Software Release 6.2.9A |                              |

| Numéro de référence de la pièce du produit en fin de commercialisation | Description du produit  | Numéro de référence de la pièce de remplacement pour le produit | Description du produit de remplacement                                | Informations complémentaires |
|--|---|---|---|------------------------------|
| <b>M92S2K9-5.0.1A</b>  | MDS 9200<br>Superviseur/structure-2,<br>Logiciel NX-OS version<br>5.0(1A) | M92S2K9-6.2.5A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.5a |                              |
| <b>M92S2K9-5.0.1A</b>  | MDS 9200<br>Superviseur/structure-2,<br>Logiciel NX-OS version<br>5.0(1A) | M92S2K9-6.2.7   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release 6.2.7     |                              |
| <b>M92S2K9-5.0.1A</b>  | MDS 9200<br>Superviseur/structure-2,<br>Logiciel NX-OS version<br>5.0(1A) | M92S2K9-6.2.9A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.9A |                              |
| <b>M92S2K9-5.0.4</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.0(4)     | M92S2K9-6.2.5A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.5a |                              |
| <b>M92S2K9-5.0.4</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.0(4)     | M92S2K9-6.2.7   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release 6.2.7     |                              |
| <b>M92S2K9-5.0.4</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.0(4)     | M92S2K9-6.2.9A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.9A |                              |
| <b>M92S2K9-5.2.1</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(1)     | M92S2K9-6.2.5A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.5a |                              |
| <b>M92S2K9-5.2.1</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(1)     | M92S2K9-6.2.7   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release 6.2.7     |                              |
| <b>M92S2K9-5.2.1</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(1)     | M92S2K9-6.2.9A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.9A |                              |
| <b>M92S2K9-5.2.1A</b>  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(1A)    | M92S2K9-6.2.5A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.5a |                              |
| <b>M92S2K9-5.2.1A</b>  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(1A)    | M92S2K9-6.2.7   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release 6.2.7     |                              |
| <b>M92S2K9-5.2.1A</b>  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(1A)    | M92S2K9-6.2.9A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.9A |                              |
| <b>M92S2K9-5.2.2</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(2)     | M92S2K9-6.2.5A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.5a |                              |
| <b>M92S2K9-5.2.2</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(2)     | M92S2K9-6.2.7   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release 6.2.7     |                              |
| <b>M92S2K9-5.2.2</b>   | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>5.2(2)     | M92S2K9-6.2.9A  | MDS 9200<br>Supervisor/Fabric-2, NX-<br>OS Software Release<br>6.2.9A |                              |

| Numéro de référence de la pièce du produit en fin de commercialisation | Description du produit   | Numéro de référence de la pièce de remplacement pour le produit | Description du produit de remplacement                      | Informations complémentaires |
|--|--|---|---|------------------------------|
| <b>M92S2K9-5.2.6</b>   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)    | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M92S2K9-5.2.6</b>   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)    | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M92S2K9-5.2.6</b>   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)    | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M92S2K9-5.2.8</b>   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)    | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M92S2K9-5.2.8</b>   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)    | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M92S2K9-5.2.8</b>   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)    | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M95S2K9-5.0.1A</b>  | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.0(1A)   | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.0.1A</b>  | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.0(1A)   | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.0.1A</b>  | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.0(1A)   | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M95S2K9-5.0.4</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.0(4)    | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.0.4</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.0(4)    | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.0.4</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.0(4)    | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M95S2K9-5.2.1</b>   | MDS 9500 Supervisor/structure-2, Logiciel NX-OS version 5.2(1) | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.2.1</b>   | MDS 9500 Supervisor/structure-2, Logiciel NX-OS version 5.2(1) | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.2.1</b>   | MDS 9500 Supervisor/structure-2, Logiciel NX-OS version 5.2(1) | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |

| Numéro de référence de la pièce du produit en fin de commercialisation | Description du produit                                       | Numéro de référence de la pièce de remplacement pour le produit | Description du produit de remplacement                      | Informations complémentaires |
|--|--|---|---|------------------------------|
| <b>M95S2K9-5.2.1A</b>  | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(1A) | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.2.1A</b>  | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(1A) | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.2.1A</b>  | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(1A) | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M95S2K9-5.2.2</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(2)  | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.2.2</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(2)  | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.2.2</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(2)  | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M95S2K9-5.2.6</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)  | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.2.6</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)  | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.2.6</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(6)  | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>M95S2K9-5.2.8</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)  | M92S2K9-6.2.5A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.5a |                              |
| <b>M95S2K9-5.2.8</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)  | M92S2K9-6.2.7   | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.7  |                              |
| <b>M95S2K9-5.2.8</b>   | MDS 9500 Supervisor/Fabric-2, NX-OS Software Release 5.2(8)  | M92S2K9-6.2.9A  | MDS 9200 Supervisor/Fabric-2, NX-OS Software Release 6.2.9A |                              |
| <b>SSI-M9K9-504</b>  | Image MDS SSI 5.0(4)   | SSI-M9K9-625  | MDS SSI Image 6.2(5)  |                              |
| <b>SSI-M9K9-504</b>  | Image MDS SSI 5.0(4)   | SSI-M9K9-625A   | Storage Services Interface-version 6.2.5a                   |                              |
| <b>SSI-M9K9-504</b>  | Image MDS SSI 5.0(4)   | SSI-M9K9-627  | Storage Services Interface-version 6.2.7                    |                              |
| <b>SSI-M9K9-504</b>  | Image MDS SSI 5.0(4)   | SSI-M9K9-629A   | Storage Services Interface-version 6.2.9A                   |                              |
| <b>SSI-M9K9-521</b>  | SP AR HW 24X7X2 SV=D9900 DCM,2RU,2/AC,GbE,Co-Pro,ASI         | SSI-M9K9-625  | MDS SSI Image 6.2(5)  |                              |

| Numéro de référence de la pièce du produit en fin de commercialisation | Description du produit                               | Numéro de référence de la pièce de remplacement pour le produit | Description du produit de remplacement    | Informations complémentaires |
|--|--|---|---|------------------------------|
| <b>SSI-M9K9-521</b>  | SP AR HW 24X7X2 SV=D9900 DCM,2RU,2/AC,GbE,Co-Pro,ASI | SSI-M9K9-625A   | Storage Services Interface-version 6.2.5a |                              |
| <b>SSI-M9K9-521</b>  | SP AR HW 24X7X2 SV=D9900 DCM,2RU,2/AC,GbE,Co-Pro,ASI | SSI-M9K9-627  | Storage Services Interface-version 6.2.7  |                              |
| <b>SSI-M9K9-521</b>  | SP AR HW 24X7X2 SV=D9900 DCM,2RU,2/AC,GbE,Co-Pro,ASI | SSI-M9K9-629A   | Storage Services Interface-version 6.2.9A |                              |
| <b>SSI-M9K9-521A</b>   | MDS SSI Image 5.2(1A)                                | SSI-M9K9-625  | MDS SSI Image 6.2(5)                      |                              |
| <b>SSI-M9K9-521A</b>   | MDS SSI Image 5.2(1A)                                | SSI-M9K9-625A   | Storage Services Interface-version 6.2.5a |                              |
| <b>SSI-M9K9-521A</b>   | MDS SSI Image 5.2(1A)                                | SSI-M9K9-627  | Storage Services Interface-version 6.2.7  |                              |
| <b>SSI-M9K9-521A</b>   | MDS SSI Image 5.2(1A)                                | SSI-M9K9-629A   | Storage Services Interface-version 6.2.9A |                              |
| <b>SSI-M9K9-522</b>  | MDS SSI Image 5.2(2)                                 | SSI-M9K9-625  | MDS SSI Image 6.2(5)                      |                              |
| <b>SSI-M9K9-522</b>  | MDS SSI Image 5.2(2)                                 | SSI-M9K9-625A   | Storage Services Interface-version 6.2.5a |                              |
| <b>SSI-M9K9-522</b>  | MDS SSI Image 5.2(2)                                 | SSI-M9K9-627  | Storage Services Interface-version 6.2.7  |                              |
| <b>SSI-M9K9-522</b>  | MDS SSI Image 5.2(2)                                 | SSI-M9K9-629A   | Storage Services Interface-version 6.2.9A |                              |
| <b>SSI-M9K9-526</b>  | MDS SSI Image 5.2(6)                                 | SSI-M9K9-625  | MDS SSI Image 6.2(5)                      |                              |
| <b>SSI-M9K9-526</b>  | MDS SSI Image 5.2(6)                                 | SSI-M9K9-625A   | Storage Services Interface-version 6.2.5a |                              |
| <b>SSI-M9K9-526</b>  | MDS SSI Image 5.2(6)                                 | SSI-M9K9-627  | Storage Services Interface-version 6.2.7  |                              |
| <b>SSI-M9K9-526</b>  | MDS SSI Image 5.2(6)                                 | SSI-M9K9-629A   | Storage Services Interface-version 6.2.9A |                              |
| <b>SSI-M9K9-528</b>  | Image MDS SSI 5.2(8)                                 | SSI-M9K9-625  | MDS SSI Image 6.2(5)                      |                              |
| <b>SSI-M9K9-528</b>  | Image MDS SSI 5.2(8)                                 | SSI-M9K9-625A   | Storage Services Interface-version 6.2.5a |                              |
| <b>SSI-M9K9-528</b>  | Image MDS SSI 5.2(8)                                 | SSI-M9K9-627  | Storage Services Interface-version 6.2.7  |                              |
| <b>SSI-M9K9-528</b>  | Image MDS SSI 5.2(8)                                 | SSI-M9K9-629A   | Storage Services Interface-version 6.2.9A |                              |

---

## Options de migration du produit

Les clients sont encouragés à migrer vers la version 6.x du logiciel Cisco MDS 9000 NX-OS. Pour en savoir plus sur ce produit, consultez : [http://www.cisco.com/c/en/us/products/collateral/storage-networking/mds-9000-nx-os-software-release-6-2/data\\_sheet\\_c78-727495.html](http://www.cisco.com/c/en/us/products/collateral/storage-networking/mds-9000-nx-os-software-release-6-2/data_sheet_c78-727495.html).

En fonction de leur zone géographique, les clients peuvent profiter du programme TMP (Technology Migration Program) pour échanger certains produits et bénéficier d'une remise sur l'achat de nouveaux équipements Cisco. Pour en savoir plus sur le programme TMP Cisco, les clients peuvent contacter leur partenaire Cisco ou l'équipe Cisco responsable de leur compte. Nos partenaires peuvent obtenir des informations complémentaires sur le programme TMP sur Partner Central à l'adresse [http://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Les clients peuvent continuer à acheter des Logiciel Cisco MDS 9000 NX-OS v. 5.x en passant par notre programme de vente d'équipements remis en état et certifiés. Les produits remis en état sont parfois mis en vente en quantité limitée dans certains pays, et ce, jusqu'à la date de fin d'assistance. Les commandes sont traitées dans l'ordre d'arrivée. Pour en savoir plus sur notre programme de vente d'équipements remis en état et certifiés, rendez-vous sur la page <http://www.cisco.com/go/eos>.

Les tarifs de services relatifs aux produits Cisco peuvent être modifiés après la date de fin de commercialisation du produit.

Le programme Reprise et recyclage de Cisco permet aux entreprises de se débarrasser proprement des produits en surplus ayant atteint leur fin de vie utile. Ce programme est accessible à tous les utilisateurs professionnels des produits de marque Cisco et des sociétés affiliées. Pour en savoir plus, consultez : [http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## Pour en savoir plus

Pour en savoir plus sur Logiciel Cisco MDS 9000 NX-OS v. 5.x , rendez-vous sur la page [http://www.cisco.com/c/en/us/products/collateral/storage-networking/mds-9000-nx-os-software-release-6-2/data\\_sheet\\_c78-727495.html](http://www.cisco.com/c/en/us/products/collateral/storage-networking/mds-9000-nx-os-software-release-6-2/data_sheet_c78-727495.html), ou contactez votre conseiller Cisco.

Pour en savoir plus sur la politique de Cisco en matière de produits en fin de vie, rendez-vous sur la page [http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html)

Pour en savoir plus sur les garanties des produits Cisco, rendez-vous sur la page : [http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html)

Pour vous abonner et recevoir des informations sur l'arrêt de la commercialisation et la fin de vie des produits, rendez-vous sur la page : <http://www.cisco.com/cisco/support/notifications.html>



---

## Abonnez-vous au flux RSS des avis de fin de vie et de fin de commercialisation des produits

Pour vous abonner au flux RSS des avis de fin de vie et de fin de commercialisation des produits, enregistrez l'URL suivante dans votre application RSS : [http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml)

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)