



END-OF-LIFE NOTICE, NO. 1823

END-OF-LIFE ANNOUNCEMENT FOR CISCO MGX 8850 SOFTWARE VERSIONS 2.0.13, 2.0.14, 2.0.15, 2.0.16, 2.1.00, 2.1.10, AND 2.1.60

Cisco Systems® is officially announcing the End-of-Sale and End-of-Life (EoS/EoL) for the following Cisco® MGX® 8850 PXM45 Switch Software versions 2.0.13, 2.0.14, 2.0.15, 2.0.16, 2.1.00, 2.1.10, and 2.1.60 with an effective announcement date of June 28, 2002. Cisco customers may continue to receive software support for a longer period as set forth in the milestones and timelines in Table 1.

Cisco MGX 8850 PXM45 Switch Software releases 2.1.75 or later will replace the software release versions affected in this announcement.

In summary, the milestones, their definitions, and effective End-of-Life dates for the Cisco MGX 8850 PXM45 Switch Software are listed in Table 1.

Table 1. Milestones and Effective End-of-Life Dates for Cisco MGX 8850 PXM45 Switching Software

Milestone	Definition	Effective Date
End-of-Life Announcement	The date that the End-of-Sale announcement will be released to the public.	June 28, 2002
End-of-Sale	The last date to enter orders of the product in the Cisco Marketplace "Orderability" Tool.	December 27, 2002
Last Ship Date	The date that Cisco Manufacturing completed/will complete fulfillment and shipment of new equipment purchase orders.	January 27, 2003
End of SW Maintenance Support	The date that Cisco Engineering ceased or will cease considering the repair/maintenance of confirmed operating system software defects or card download software defects within this system configuration.	June 28, 2005
End of service contract renewal date	The date that renewing/extending a service contract for this system will discontinue.	–
Last Date of Support	The date that Cisco Logistics will no longer have any obligation to support the products listed in this Product Bulletin. This includes processing RMA orders for components with this system configuration; it is also the date that the Cisco Technical Assistance Center (TAC) will no longer have any obligation to assist customers with any issues related to this software. Any assistance rendered by Cisco will be on an as-available basis without warranties at the sole discretion of Cisco Systems.	June 28, 2007

1. Not Applicable

Table 2 lists the Cisco MGX 8850 PXM45 Switch Software part numbers that are affected by this EoS/EoL announcement.

Table 2. Cisco MGX 8850 PXM45 Switch Software Part Numbers

Product Number	Product Description	EoS Last Order (Sales) Date	End of Production Last Shipment Date	End of Engineering Hardware Maintenance Date	End of Engineering Software Maintenance Date	Discontinue Contract Renewal Date	End of Support/Product Obsolescence Date
MGX8850-SW-2013	MGX 8850 System Software License—Release (Version 2.0.13)	12/27/2002	1/27/2003	— ¹	6/28/2005	—	6/28/2007
MGX8850-SW-2013CD=	MGX 8850 System Software License—Spare CD (Version 2.0.13)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2014	MGX 8850 System Software License—Release (Version 2.0.14)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2014CD=	MGX 8850 System Software License—Spare CD (Version 2.0.14)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2015	MGX 8850 System Software License—Release (Version 2.0.15)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2015CD=	MGX 8850 System Software License—Spare CD (Version 2.0.15)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2016CD	MGX 8850 System Software Release (Version 2.0.16)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2016CD=	MGX 8850 System Software License—Spare CD (Version 2.0.16)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2100	MGX 8850 System Software Release (Version 2.1.00)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2100CD=	MGX 8850 System Software License—Spare CD (Version 2.1.00)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007
MGX8850-SW-2110	MGX 8850 System Software Release (Version 2.1.10)	12/27/2002	1/27/2003	—	6/28/2005	—	6/28/2007

Product Number	Product Description	EoS Last Order (Sales) Date	End of Production Last Shipment Date	End of Engineering Hardware Maintenance Date	End of Engineering Software Maintenance Date	Discontinue Contract Renewal Date	End of Support/Product Obsolescence Date
MGX8850-SW-2110CD=	MGX 8850 System Software License—Spare CD (Version 2.1.10)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007
MGX8850-SW-2110CD=	MGX 8850 System Software License—Spare CD (Version 2.1.10)	12/27/2002	1/27/2003	–	6/28/2005	–	6/28/2007

1. Not Applicable

ORDERING INFORMATION

December 27, 2002, will be the last date to enter orders for Cisco MGX 8850 PXM45 Switch Software versions 2.0.13, 2.0.14, 2.0.15, 2.0.16, 2.1.00, 2.1.10, and 2.1.60. Support for software will be provided according to the effective dates stated in Table 1.

FOR MORE INFORMATION

Hugues Metayer

Product Manager

Phone: 408 853-8774

E-mail: hmetayer@cisco.com



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

