

Recommended Microsoft Hot Fixes for Cisco MXE 3500

August 2010

Introduction

This bulletin lists the Microsoft hot fixes that we recommend you install on the Cisco MXE 3500 Media Experience Engine.

Required Hardware and Software Levels


This bulletin applies to Release 3.0.0 of the Cisco MXE 3500 Media Experience Engine.

Installation

For each hot fix, click the link to go directly to the Microsoft website and do the following:


1. Read the Microsoft Security Bulletin.
2. Download the hot fix by clicking the link on the Security Bulletin webpage for **Windows Server 2003 Service Pack 2**.
3. Right-click the hot fix.
4. Click **Properties**. The File Property dialog box displays, as shown in Figure 1.

Figure 1. File Property Dialog Box Snapshot



5. Click the **Unblock** button. The Unblock button dims, as shown in Figure 2.
Or:
If the Unblock button is not present, click **Cancel**, and install the hot fix by following the installation procedure that Microsoft provides.
6. Click **OK**. The File Property dialog box closes.
7. Install the hot fix by following the installation procedure that Microsoft provides.

Figure 2. Hot Fix Unblocked Snapshot



Newly Recommended Hot Fixes

We recommend that you apply the following newly available Microsoft hot fixes to the Cisco MXE 3500, running the applicable versions of software:

- **MS10-046** (Knowledge base Article KB2286198)
<http://www.microsoft.com/technet/security/bulletin/MS10-046.aspx>
- **MS10-049** (Knowledge base Article KB980436)
<http://www.microsoft.com/technet/security/bulletin/MS10-049.aspx>
- **MS10-051** (Knowledge base Article KB2079403)
<http://www.microsoft.com/technet/security/bulletin/MS10-051.aspx>
- **MS10-052** (Knowledge base Article KB2115168)
<http://www.microsoft.com/technet/security/bulletin/MS10-052.aspx>
- **MS10-053** (Knowledge base Article KB2183461)
<http://www.microsoft.com/technet/security/bulletin/MS10-053.aspx>
- **MS10-054** (Knowledge base Article KB982214)
<http://www.microsoft.com/technet/security/bulletin/MS10-054.aspx>

-
- **MS10-055** (Knowledge base Article KB982665)
<http://www.microsoft.com/technet/security/bulletin/MS10-055.aspx>
 - **MS10-060** (Knowledge base Article KB2265906)
<http://www.microsoft.com/technet/security/bulletin/MS10-060.aspx>

Hot Fixes Recommended in Prior Bulletins

July-2010

- None

June-2010

- **MS10-033** (Knowledge base Article KB979902)
<http://www.microsoft.com/technet/security/bulletin/MS10-033.aspx>

May-2010

- None

April-2010

- **MS10-019** (Knowledge base Article KB981210)
<http://www.microsoft.com/technet/security/Bulletin/MS10-019.aspx>
- **MS10-020** (Knowledge base Article KB980232)
<http://www.microsoft.com/technet/security/Bulletin/MS10-020.aspx>
- **MS10-026** (Knowledge base Article KB977816)
<http://www.microsoft.com/technet/security/Bulletin/MS10-026.aspx>

March-2010

- **MS10-006** (Knowledge base Article KB978251)
<http://www.microsoft.com/technet/security/Bulletin/MS10-006.aspx>
- **MS10-007** (Knowledge base Article KB975713)
<http://www.microsoft.com/technet/security/bulletin/MS10-007.aspx>
- **MS10-013** (Knowledge base Article KB977935)
<http://www.microsoft.com/technet/security/bulletin/MS10-013.aspx>

Hot Fixes Included in Prior Maintenance Releases

None



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)