Troubleshoot "QSFP28 not detected in inventory" - NCS1004 Software Release 711 and 721

Contents

Introduction
Problem
Isolation of the Issue
Solution

Introduction

This document describes how to identify inventory discrepancies of optics in NCS1004 and offers a solution to address the issue.

Problem

Several ports do not appear in the **show inventory** command output. This issue affects both Cisco and non-Cisco optics and has been observed on various line cards and devices.

Isolation of the Issue

If you use the command show inventory location 0/*, you do not see the information for this optics.

But, if you use the command show controllers optics location R/S/I/P - you see information for optics like PID, Serial number, Name, and more as shown in the image.

```
RP/0/RP0/CPU0: Time 4/wow #show inventory location 0/0
Mon Mar 6 00:40:57.095 UTC
NAME: "0/0", DESCR: "NCS1K4 12x QSFP28 2 Trunk C-Band DWDM card"
PID: NCS1K4-1.2T-K9 , VID: V01, SN: CAT2311B1GX

NAME: "0/0-Optics0/0/0/2", DESCR: "Cisco 100G QSFP28 LR4-S Pluggable Optics Module"
PID: QSFP-100G-LR4-S , VID: V02, SN: FNS23130783

NAME: "0/0-Optics0/0/0/5", DESCR: "Cisco 100G QSFP28 LR4-S Pluggable Optics Module"
PID: QSFP-100G-LR4-S , VID: V02, SN: FNS231305VA

NAME: "0/0-Optics0/0/0/7", DESCR: "Cisco 100G QSFP28 LR4-S Pluggable Optics Module"
PID: QSFP-100G-LR4-S , VID: V02, SN: FNS24270LEN

NAME: "0/0-Optics0/0/0/8", DESCR: "Cisco 100G QSFP28 LR4-S Pluggable Optics Module"
PID: QSFP-100G-LR4-S , VID: V02, SN: FNS23130SUZ

NAME: "0/0-Optics0/0/0/9", DESCR: "Cisco 100G QSFP28 LR4-S Pluggable Optics Module"
PID: QSFP-100G-LR4-S , VID: V02, SN: FNS23130SUZ
```

Update for the location 0/0/0/3 is not seen.

Mon Mar 6 00:47:30.938 UIC

Controller State: Up

Transport Admin State: In Service

Laser State: On LED State: Green

Parameter	High Alarm	Low Alarm	High Warning	Low Warning
Rx Power Threshold(dBm)	12.0	-12.0	0.0	0.0
Tx Power Threshold(dBm)	12.0	-10.1	0.0	0.0
LBC Threshold(mA)	N/A	N/A	0.00	0.00

The details are

shown here

LBC High Threshold = 98 %

Polarization parameters not supported by optics

Total TX Power = 8.26 dBm

Total RX Power = 1.42 dBm

Lar	ne Lase	r Bias	TX P	ower	RX F	ower	Output	Frequency
1	1 7	0.8 %	2.24	dBm	-4.59	dBm	231.39	THZ
2		1.3 %		dBm	-4.51	dBm	230.59	THZ
3	3 7	1.6 %	2.05	dBm	-4.69	dBm	229.79	THZ
4	1 7	0.7 %	2.28	dBm	-4.58	dBm	230.25	THZ

Transceiver Vendor Details

Form Factor : QSFP28
Name : CISCO-FINISAR
Part Number : 10-3146-02
Rev Number : A

Serial Number : FNS23130787
PID : QSFP-100G-LR4-S

VID : V02 Date Code(yy/mm/dd) : 19/03/24

Fiber Connector Type: LC Otn Application Code: Not Set Sonet Application Code: Not Set

Details of the optics are displayed.

Solution

Workaround is to perform issue a warm reload from the admin with the command hw-module location 0/0 reload warm. Software Defect: Cisco bug ID <u>CSCvw73152</u>NCS1004 QSFP28 are not detected in inventory.

Found version: 7.1.1 and 7.2.1

Resolved: 731