

# SG350XG: Configuring DAC Fails on a Switch with Pre-configured 802.1X and RADIUS Settings

## Date Identified

August 19, 2016

## Date Resolved

June 5, 2017

## Product Affected

SG350XG	2.2.0.x	2.3.0.130

## Problem Description

In some cases, if a switch has preconfigured 802.1X or Remote Authentication Dial-In User Service (RADIUS) configurations through the Command Line Interface (CLI) or via the web-based utility, the display or configuration via Device Authorization Control (DAC) may fail.

## Resolution

This issue is fixed when you upgrade to the firmware version 2.3.0.130. To upgrade, click [here](#) for instructions.