



Caveat List

- [Caveat List, on page 1](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1z2, on page 2](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1z1, on page 3](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1z, on page 4](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1y, on page 4](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1x, on page 5](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1w, on page 5](#)
- [Open Caveats for Cisco IOS XE Gibraltar 16.12.1, on page 6](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1z2, on page 7](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1z1, on page 7](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1z, on page 9](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1y, on page 10](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1x, on page 11](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1w, on page 12](#)
- [Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1, on page 13](#)
- [Cisco Bug Search, on page 13](#)

Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats.

The *Open Caveats* section lists open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



Note The *Caveats* section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

Open Caveats for Cisco IOS XE Gibraltar 16.12.1z2

Caveat ID Number	Description
CSCvu22456	CMTS keeps print '%CBR-4-NOCFGFILE: Cannot read modem config file.. Timed out' though CM is online
CSCvu38525	55d1 DS OUT-GROUP IP change is not reflected after the change of VOM-IP
CSCvu38834	mac-address not assigned automatically when creating LED
CSCvu43568	Video sessions going to Pending state on LED reload followed by SUPSO
CSCvw37563	Controller Integrated-Cable NORESOURCE on VIDEO Channels after SUPHA
CSCvw51062	When cyclic-prefix is 1024 while OFDM traffic BW is fully populated, drops are observed
CSCvw84664	Free Classifier Causes Corruption of Free Memory Block & CLC Reload
CSCvw94914	cBR-8 Error Message "Failed to get rpd cfg or ds rf port" error after re-provisioning RPD
CSCvw95451	SNMP traps for upstream ifindex/ifDescr mismatch
CSCvx01761	OFDMA with specific exclusion band configs result in no equalization coefficients sent to modems.
CSCvx02092	docsIf3RxChStatusIfIndex showing inconsistencies returning ifindex for OFDM channel
CSCvx06573	cBR8: missing L2 multicast traffic after line card replacement
CSCvx09826	cached multicast session still contribute traffic on wideband interface
CSCvx15877	Wrong output of 'show controller integrated x/0/x counter rf-channel' (cosmetic issue)
CSCvx16243	cBR-8 Program terminated with signal SIGSEGV, Segmentation fault.
CSCvx19791	per SF DPS grants may be issued for longer than expected
CSCvx23933	CBR8 SUP reload with error "Cannot access memory at address 0xd0d0d0d0d0d0d0d0"
CSCvx23949	CMTS CBR LC Unexpected Reload When Printing Modem Details
CSCvx29857	incorrect value on OID docsIf31CmtsCmUsOfdmaChannelRxPower
CSCvx32657	Avg upstream channel utilization(%data bytes) : 100% when there is no data grants on that channel
CSCvx49498	Standby SUP reload when the veg configuration of an inactive LED is applied
CSCvx62575	'clear cable upstream ofdma mer-fec ..' makes ofdma mer-fec value FFFF FFFF

Caveat ID Number	Description
CSCvx63028	Fixes to channel level OFDMA IUC Uncorr CWDs & InOctets counts.
CSCvx69912	OFDMA RxMER Standard Deviation calculation is incorrect
CSCvx71564	Cable LC reloaded after vdman and veman processes have been heldown
CSCvx76530	After LCSO rpd-cores-ident db not showing proper core function value
CSCvx93204	SUP Reloads after polling Upstream Channel Stats via SNMP query
CSCvx97160	CBR8 ignore partial service TLV if CM sends incorrect vendor specific TLV inside REG-ACK after DBC
CSCvy02299	New JIB number gets allocated for rf-channel belonging to QRG on port un-shut post LCHA
CSCvy10584	Missing information in show cable modem phy ofdm-profile upstream after ISSU upgrade
CSCvy25057	OFDMA RxMER OIDs return value 0
CSCvy30760	cbr8 - after SUP160 switchover, when TRANSCEIVER-6-INSERTED log is printed it causes interfaces flap
CSCvy51108	Dual SUP reload after issuing 'clear cable video snmp-alarm-table' on Active SUP
CSCvy52051	cdman restart because of bus error at ubripc_recv_bg_base_addr_ch_cfg()
CSCvy65140	Linecard restart after clear cable modem all delete
CSCvy78953	OFDMA upstream modems may show more than 2 assigned IUCs in scmph ofdm-profile upstream
CSCvy85973	ACL with Object-group result in pending-issue on reload
CSCvy92928	CBR8/Gen 2 LC - Cable Video traffic marked as DSCP CS1 instead of CS4 when RPD is IPv6
CSCvz25632	Traceback observed during 16.12.1z2 package upgrade

Open Caveats for Cisco IOS XE Gibraltar 16.12.1z1

Caveat ID Number	Description
CSCvw52701	CDM_PKTIO core file at cdm_rng_ios_stats_check
CSCvu22456	CMTS keeps print '%CBR-4-NOCFGFILE: Cannot read modem config file.. Timed out' though CM is online
CSCvu27698	some us channel or us port info were missing when walk mib docsRphyRpdIfRpdToCoreMapCoreIfIndex

Caveat ID Number	Description
CSCvu38525	55d1 DS OUT-GROUP IP change is not reflected after the change of VOM-IP
CSCvu38834	mac-address not assigned automatically when creating LED
CSCvu43568	Video sessions going to Pending state on LED reload followed by SUPSO
CSCvu52279	CBR8 has stale OFDM Channel Descriptor (OCD)
CSCvw94914	Failed to get rpd cfg or ds rf port" error after re-provisioning RPD

Open Caveats for Cisco IOS XE Gibraltar 16.12.1z

Caveat ID Number	Description
CSCvu44042	Long traffic drop time observed during SUPHA due to new active-sup send out first ISIS packet too late.
CSCvu22456	CMTS keeps print '%CBR-4-NOCFGFILE: Cannot read modem config file. Timed out' though CM is online.
CSCvu27698	Some US channel or US port info were missing when walk MIB docsRphyRpdIfRpdToCoreMapCoreIfIndex.
CSCvu38525	55d1 DS OUT-GROUP IP change is not reflected after the change of VOM-IP.
CSCvu38788	Cisco cBR-8: Wrong timeout chosen for DBC for DSA/DSC, should be 45 mSec but takes 3 seconds.
CSCvu38834	MAC address not assigned automatically when creating LED.
CSCvu43568	Video sessions going to Pending state on LED reload followed by SUPSO.
CSCvu52279	Cisco cBR-CSCvu436728 has stale OFDM Channel Descriptor (OCD).

Open Caveats for Cisco IOS XE Gibraltar 16.12.1y

Caveat ID Number	Description
CSCvs91563	The CBR8 COPS process does not send the new host name right away after the hostname change.
CSCvt20371	standby sup reload due to config sync failure at 'power-adjust -3.7.
CSCvt17375	The Cisco cBR-8 router does not classify traffic in DS Service Flows based on RulePriority.
CSCvs98172	Cisco cBR-8 supervisor reload after entering <code>hw-module slot < x > shutdown</code> .

Caveat ID Number	Description
CSCvr27595	docsIfSigQEqualizationData does not work for non-mtc-mode modems.

Open Caveats for Cisco IOS XE Gibraltar 16.12.1x

Caveat ID Number	Description
CSCvp87476	Modems are all no-show when booting a brand new 2x2-RPD in LCHA mode.
CSCvr27595	docsIfSigQEqualizationData does not work.
CSCvr81108	SUP stuck-queue issues on version Cisco IOS-XE Gibraltar 16.10.1d.
CSCvr87889	Missing entries under docsIf3MdNodeStatusMdUsSgId when multiple fiber-nodes per mac-domains.
CSCvr94531	Found OFDM DPS buffer lock-up when keep swapping ofdm-chan-prof between 0 and 8.
CSCvs40419	D31 UMP: Prof Mgmt Downgrade IUC may skip next IUC when IUC-Override configured.
CSCvs42402	Timing offset cable map-advance dynamic 600 600.

Open Caveats for Cisco IOS XE Gibraltar 16.12.1w

Caveat ID Number	Description
CSCvn67318	CLC unable to communicate with SUP.
CSCvo15430	PKO_ERROR, QAM oversubscribed on CBR-CCAP-LC-G2-R line card with more than 448 video QAMs.
CSCvp68713	AUX core is getting flapped between <code>offline</code> and <code>init(12tp)</code> when AUX with static PWs only.
CSCvp87476	Modems are all no-show when booting a brand new 2x2-RPD in LCHA mode.
CSCvq05825	Temperature increase when upgrading from 16.7.3 to 16.10.1d.
CSCvq38886	RPHY Speed Issues - Intel-based modems.
CSCvq47000	Cisco cBR-8 - Active CLC Crash Due to CPUHOG and IPC Overload of Protect.
CSCvq61940	RPHY: D31 OFDMA CMs on CBR-CCAP-LC-G2-R/RPD may stall at <code>init(rc)</code> after MD and ch config change w/ ccm delete.
CSCvr15029	OID <code>dot3adAggPortListPorts</code> does not show interfaces list in LAG for Cisco cBR-8.

Caveat ID Number	Description
CSCvr15095	Cisco cBR-8 16.7.1a - DUC interrupts caused modems to drop offline on a few mac-domains.
CSCvr27595	docsIfSigQEqualizationData does not work.
CSCvr29799	Disabled cm-status messages are re-enabled after reload.

Open Caveats for Cisco IOS XE Gibraltar 16.12.1

Caveat ID Number	Description
CSCvo15430	PKO_ERROR, QAM oversubscribed on CBR-CCAP-LC-G2-R line card with more than 448 video QAMs
CSCvp59007	DPIC ping fail after SUPHA and plug in LC.
CSCvq13279	CBR crashes on configuring DPIC interface with port-channel configuration and SUPHA
CSCvq17199	ExporterHandle and SessionHandle corrupted when IPDR was denied in global config mode
CSCvq35256	cBR8 PTP flapping
CSCvq47000	cBR8 - Active CLC Crash Due to CPUHOG and IPC Overload of Protect
CSCvn16579	CEM reconnection did not sync keys to LED
CSCvn67318	CLC unable to communicate with SUP
CSCvp37177	Sup unexpected reload on show interface stats for interface VideoMON
CSCvp62500	sh cable signal-quality cable x/y/z upstream x cmts can't show CNiR
CSCvq10457	CBR8 may keep multicast streams active while no listeners
CSCvq16616	DPIC link redundancy does not send correct trap when link down
CSCvq40960	cbr8/VIDEO : ECM cache not flushed after last video session terminates
CSCvq49963	cBR8/16.10.1d // Mismatch in serial numbers after linecard replacement
CSCvp50507	gRPC: failed to get right format for ipv6,ipv4 address
CSCvq68404	I-CCAP cBR-8 displays incorrect QAM utilization

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1z2

Caveat ID Number	Description
CSCvw04657	cBR8 Queue ID Pending Drain after DS controller shutdown
CSCvw61725	cBR8 - CLC CDMAN unexpected reload due to Watchdog Timeout
CSCvw89651	cBR8 - Add Functionality/CLI to Disable Enterprise ID (Option 17) Override for DHCPv6 Relay
CSCvw95723	cBR8: Memory leak with WB Resiliency (DS OFDM / DS PROF EV) causes CLC reload
CSCvw96405	%PLATFORM-4-ELEMENT_WARNING: smand [R0/R1] Used memory exceeding warning level of 80%
CSCvx04248	Not enough cdman FPA buffer for messages: cable modems cannot come online
CSCvx24033	PCMM IPv6 Classifiers is not applied to the DOCSIS Service flow.
CSCvy01592	OFDMA modems get stuck on IUC13 after sending O-INIT-RNG-REQ while online
CSCvy04600	Video sessions are in 'off' state due to Source IP mismatch between Supervisor and Cable Line card
CSCvy15202	cBR8 OSPF Inter and Intra Area prefixes are missing after adjusting OSPF max-path from 12 to 16
CSCvy69910	CBR-SUP-SSD missing from "show inventory" and harddisk: inaccessible
CSCvy84535	cable upstream resiliency recover retries didn't work

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1z1

Caveat ID Number	Description
CSCvu81452	cBR8 unexpected reload when configuring interface BDIxxxx
CSCvu92404	cBR8 : Downstream QAMs 'Down' and Not Recovering Back to 'Up' State
CSCvv22836	Unexpected reload at configuration while binding the NDR "viavi-ndr-01" with the NDR-profile "1280"
CSCvr15095	cbr8 - 16.7.1a - DUC interrupts caused modems to drop offline on few mac-domains
CSCvt64355	CBR-8 linecard reload in osc_memcopy function
CSCvu60425	CBR8 - Stby-SUP in N/A state and Continuously Reloading Due to "Act2-lock: timeout getting lock"

Caveat ID Number	Description
CSCVv20830	RP0 veman restart on LED Reload and SUP SO/Reload
CSCVv21785	PKI: Trusted Certificates may not load correctly from NVRAM:
CSCVv46753	Changes in one MD may have an effect in all CM of the line card
CSCVv51471	cBR-8 line card out of free memory, may reload due to process veman fail
CSCVv61493	PMA Automation causing un-correctable errors causing the CM-16 Status messages
CSCVv63712	cbr8 line card went down rarely while executing 'show cable card X/0 ds-mac fcstat'
CSCVw08800	Session create failure intermittently during bootup from LED to LC
CSCVw75070	RF Resiliency CPUHOG: cmts_rf_resil_rp_is_sf_on_interface()
CSCVw80040	cBR8 - 'no upstream...' Under DOCSIS 2.0 LB Group Causes SUP Reload
CSCVw84157	Reload of CLC when upstream flow changes state "cm_instance_t *cminstp = USF_CM(flowp)"
CSCVw97917	cBR8 - with OPSimp config, 'cable enable-trap cmonoff-notification' missing from LC after LC reload
CSCvt68035	SBRL quarantine Flag not dropping after time interval.
CSCvu23476	buffer pool summary, the maxium allocator is mcp_alloc_ipc_tx_msg_once
CSCvu38611	Some modems index are not included in MIB table docsRphyCcapRpdToCmMapStatusEntry
CSCvu38788	CBR8: wrong timeout chosen for DBC for DSA/DSC, should be 45 mSec but takes 3 seconds
CSCvu58795	PNM RxMER tftp file contains inactive subcarriers
CSCvu66542	VGQI-2-RESOURCE_ALLOCATION_ERROR: R0/0 error and Traceback
CSCvu73421	#no ipdr exporter start, can't restart the stuck IPDR session on CBR
CSCvu90440	Text 'create wbfift session get gcp fail' appended to log messages not related to wbfift feature
CSCVv10838	Performing LCHA affects OOB(55d1), without having mulsticast-pool redundant.
CSCVv10984	Standby PIC Daughter Board missing from inventory after Standby SUP Replacement
CSCVv16288	D31-UMP: when cur IUC is not 13, CMs go to /p due to CW par downgrade check and stuck in /p state
CSCVv35737	cBR8 - Optimization of D3.1 SNMP queries when Zero OFDMA modems
CSCVv53441	cBR does not listen on IPDR port after socket is re-initialized following session termination

Caveat ID Number	Description
CSCvv73972	SBRL quarantine Flag not dropping sometimes
CSCvv92716	cBR-8 SNMP ccsCmFlapLastFlapTime returns values only for first init ranging US channel for MTC CMs
CSCvw69986	patch upgrade from 16.12.1z to cbr_patch-16.12.1z-patch1.tar fails, both the SUPs say ACTIVE
CSCvw93501	ccsSpectrum MIB reports incorrect power-level values when noise level > powerlevel
CSCvu22621	Add support for Die Shrink RLDRAM for Cylons

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1z

Caveat ID Number	Description
CSCvt64771	dhcpd failure due to missing <code>if_input</code> resulting in unexpected SUP SO.
CSCvu01759	High CPU due to <code>arp-ha</code> on standby SUP.
CSCvr22961	Unexpected CPP CP server reload during longevity test.
CSCvs64618	Hitron D31 modems reject (offline) in Cisco cBR8 16.12 images with more than 3 DS data profiles configured.
CSCvs98172	Cisco cBR-8 supervisor reload after entering <code>"hw-module slot < x > shutdown"</code> or LC OIR.
CSCvt44821	RPHY - Cisco cBR does not release US controller binding after RPD de-provision.
CSCvt50148	Show Cable Modem Select * - Either null return or long delay.
CSCvt56778	Load-balancing may select wrong TCS after prim channel balancing move when orig TCS included OFDMA.
CSCvt91725	With power-tilt config present and reconfiguration the OFDM channel, modems fall offline after LCHA.
CSCvu18501	Duplicate <code>ifIndex</code> assigned for multiple RPDs for RPD-usport <code>ifEntry</code> .
CSCvu23392	Cisco cBR-8: Out-of-Memory condition leads to CLC unexpected reload.
CSCvu52322	Cisco cBR-8: Do not drop malformed DHCP option 125 packets.
CSCvr27595	<code>docsIfSigQEqualizationData</code> does not work for non-mtc-mode modems.
CSCvr36911	Cisco cBR-8 - facility-alarm showing false <code>"Physical Port Link Down"</code> alarms.
CSCvs15811	Cisco cBR-8/L2VPN: Toggle of PW-Status-TLV causes Backup PW to remain DOWN.
CSCvs54539	Removing the AUX core directly does not remove the Upstream configs at RPD.

Caveat ID Number	Description
CSCVs86812	Logging is not detecting and reporting the input stream error for some sessions.
CSCVs91563	Cisco cBR-8 COPS process does not send the new host name right away after the hostname change.
CSCvt02104	RPHY DS controller profile OFDM config not valid with <code>ofdm-chan-prof</code> ID 256 or greater.
CSCvt11751	Cisco cBR-8 video sessions have non-zero input bitrates and zero output bitrates.
CSCvt15061	Cisco cBR-8 SNMP not responding to <code>ccsCmFlapTable</code> .
CSCvt23285	For a 32 ch BG, Cisco cBR incorrectly uses RCP ID 00 10 00 10 18 (24 ch) in lieu of 00 10 00 10 20 (32 ch).
CSCvt27620	Warning: Dynamic Modulation Profile does not work when US-sharing is enabled in R-PHY.
CSCvt27674	Cisco cBR-8: Standby SUP unable to activate when Primary fails.
CSCvt28555	Cisco cBR-8 - Packet Sequence Number (PSN) in DS EHDR random generated after DBC cause modem stuck.
CSCvt36385	Cisco cBR-8 CPU Process <code>DHCPv6 Relay</code> high after IOS-XE Upgrade and large <code>sv-match-unknown</code> lease queries.
CSCvt60308	<code>show cable upstream service-flow summary</code> counter overflow.
CSCvt65238	Cisco cBR-8: <code>rpd-ds 0 base-power</code> reset upon reload of CMTS.
CSCvt67757	Cisco cBR-8/RPHY: Corrected and uncorrected FEC output shown as all 0 in <code>"show cable hop"</code> .
CSCvu01668	Gate state and reason are swapped in <code>COPS SYNC_REQUEST</code> message.
CSCvu05203	Cisco cBR-8 - <code>rpd-ds 0 rf-channel 0 power-adjust</code> value of -0.5 Displays as 0.5 in <code>show running-config</code> .
CSCvu24232	Observed core file on SUPSO followed by LCSO.
CSCVs32662	Cisco cBR-8 - <code>"cable bonding-group-secondary"</code> on a D30 BG prevents multicast forwarding to D31 modems.
CSCvt36341	vty hung when issue <code>#show run int bundle *</code> .

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1y

Caveat ID Number	Description
CSCvr79254	SUP SO triggered by large OFDM profile set when querying <code>show cable rpd config downstream remote</code> .

Caveat ID Number	Description
CSCvs19789	LC CDMAN reload happens after RPD replacement with ~64 DLM enabled.
CSCvs24850	Cisco cBR sometimes writes to incorrect indexes at CcapCoreIdentity table.
CSCvp87476	Modems are all no-show when booting a brand new 2x2-RPD in LCHA mode.
CSCvq10457	The Cisco cBR-8 roter may keep multicast streams active while no listeners.
CSCvr87889	Missing entries under docsIf3MdNodeStatusMdUsSgId when multiple fiber-nodes per mac-domains.
CSCvs40419	D31 UMP: Prof Mgmt Downgrade IUC may skip next IUC when IUC-Override configured.
CSCvs42402	Timing offset cable map-advance dynamic 600 600.
CSCvs70808	Cisco cBR-8 Replication Queue - Recycle Queue Tail Drops DSG Tunnel Traffic.
CSCvs80572	Cisco cBR-8 Vecima 2x2 pilot tone configuration issue.
CSCvs94899	NDF/NDR pseudowire stale MAC address.
CSCvs97976	RPHY US spectrum using SNMP - ccsSpectrumRequestIfIndex doesn't accept IfType 129 for RPHY upstreams.
CSCvo88232	Cisco cBR-8 - static LB - modification of primary DS channel change movement with RCC template.

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1x

Caveat ID Number	Description
CSCvk46772	Cisco cBR-8: show cable modem select impusare empty.
CSCvo19397	Cisco cBR-8: CLC Repeatedly Logging "kernel: set_reg_configuration: write max6654 register at 09 failed".
CSCvp46033	docsRphyRpdDevCoresConnectedCoreFunction incorrect values - could not return all "1" for video.
CSCvq86980	Modems are partial online on OFDMA upstream.
CSCvq98653	EAE not working when First Mac-Domain of the Linecard is in shutdown mode.
CSCvr13326	"cable primary-sflow-qos11 keep all"- secondary Sf active and create time not reset after stop record.
CSCvr29799	Disabled cm-status messages are re-enabled after reload.
CSCvr32596	No Packet flow for 2x2 RPD in docsRphyStatsRpdDsOfdm mib.

Caveat ID Number	Description
CSCvr57471	Cisco cBR-8 drops PTP Sync and Delay_Request packets which leads to HOLDOVER.
CSCvr70940	Cisco cBR-8 Supervisor reloads after receiving DHCP relay packet.
CSCvr72915	Cisco cBR-8 behavior enhancement when running APM (alternate provision Mode) and tftp v6 fails.
CSCvr86232	D31-UMP: When RPD is connected with an IPv6 CIN network and VCs are used, Probes/PNMs may be dropped.
CSCvr95661	Secondary SUP getting reloaded by removing static-pseudowire config.
CSCvs22036	Cisco cBR-8 TLV memory leak.
CSCvs29461	Cisco cBR-8 with CBR-LC-8D31-16U31 line card rejects VoD UDP stream with source port 0.

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1w

Caveat ID Number	Description
CSCvp59007	DPIC ping fails after SUPHA and plug in LC.
CSCvp62500	sh cable signal-quality cable x/y/z upstream x cmts cannot show CNiR.
CSCvp95298	RPHY D31 - OFDM utilization goes over 100% in CLI output.
CSCvq13279	Cisco cBR unexpectedly reloads after configuring DPIC interface with port-channel configuration and SUPHA.
CSCvq16616	DPIC link redundancy does not send correct trap when link down for 40G DPIC.
CSCvq17199	ExporterHandle and SessionHandle corrupted when IPDR was denied in global config mode.
CSCvq40960	Cisco cBR-8/VIDEO: ECM cache not flushed after last video session terminates.
CSCvq49963	Mismatch in serial numbers after linecard replacement.
CSCvq68404	Cisco cBR-8 displays incorrect QAM utilization.
CSCvq83903	RBG interface missing AC record when using OPS and controller profiles.
CSCvq87493	Cisco cBR-8 unexpected reload while execution subcarrier-spacing command
CSCvq91116	BADTXOFFSET message floods log file.
CSCvr11404	IOSD unexpected reload when configuring cable video.
CSCvr15367	Cable upstream-sharing config does not match startup config when upgrading from 16.12.1 CCO.

Caveat ID Number	Description
CSCvr20992	16.12.1 show cable modem select is not wokring, returnrs SQL statement syntax Error.

Resolved Caveats for Cisco IOS XE Gibraltar 16.12.1

Caveat ID Number	Description
CSCvk59521	IPC performance downgrade will increase the voice ctrl pkt latency
CSCvn24876	docsis-channel-id change failed
CSCvn75830	iomd reload @ iomd_ipc_send
CSCve39451	Adding warning message to avoid cpp stuck
CSCvj20713	PHY43.31(CMTS OFDMA Burst Receiver Input Signal Minislot Parameters) Failed for QPSK and 2K FFT Size
CSCvk56103	D31: CLI show rpd config downstream remote fails
CSCvk68830	RPHY modem not back online after re-config FN/MD/WB/profile etc unless reset RPD
CSCvm69126	CPUHOG in DOCSIS LCHA Process
CSCvm91723	Only one CM with UGS-AD with 20 grants per interval allowed per US when minislot=1
CSCvn72716	LC switch to protect card and corefile generated
CSCvo02514	docsIf31CmtsUsOfdmaChanSubcarrierSpacing returns value in Hz instead of KHz
CSCvo35498	Cannot specify preferred PCR-pid for primary-secondary clock recovery mode
CSCvo72165	After reconfig of IP address of CA on LC, old IP address stays in routing table
CSCvp00524	cable modem change-frequency commands not working properly
CSCvp57491	CBR8 SUP/PIC \"Failed Identification Test\" Error after OIR/Replacement
CSCvp69412	sub-carrier bit loading calculated incorrectly at threshold
CSCvq41213	RPHY: CM hard to get online, LC IPC msg tdl_msg_type 23 takes long time in average
CSCvk39135	DPIC100G: 40G-SR SFP can't be recognized

Cisco Bug Search

Use the [Cisco Bug Search Tool](#) to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.

Save Search Load Saved Search Clear Search Email Current Search

Search For: Examples: CSCId10124, router crash, etc...

Product: Series/Model Select from list

Releases: Affecting or Fixed in these Releas Enter release number

368025

You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.

Save Search Load Saved Search Clear Search Email Current Search

Search For: Examples: CSCId10124, router crash, etc...

Product: Series/Model Select from list

Releases: Affecting or Fixed in these Releas

Filter: Modified Date: Status: Severity: Rating: Support Cases: Bug Type: Customer Visible

Viewing 1 - 25 of 132 results Sort by Export Results to Excel

368026

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see [What's New in Cisco Product Documentation](#).

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the [What's New in Cisco Product Documentation RSS feed](#). The RSS feeds are a free service.