

# **Upgrading the ROMMON Versions**

The ROMMON image upgrade from Cisco IOS XE 3.x to Cisco IOS XE Everest 16.5.1 is *not* mandatory. We recommend a ROMMON upgrade for effective utilization of the new features delivered in Cisco IOS XE Everest 16.5.1 and later releases.



Note

We recommend you to reload the router two times for successful ROMMON and software image upgrade.



Note

You cannot expand the Cisco IOS XE 16.x image into the Cisco IOS XE 3.x images. The bin. file may be used to reload the image.

- Upgrading the ROMMON, page 1
- Upgrading the ROMMON on the RSP3 Module, page 4

## **Upgrading the ROMMON**

The router has two ROMMON regions (ROM0 and ROM1). We recommend that the upgrade is performed on both the regions.



Caution

To avoid actions that might make your system unable to boot, read this entire section before starting the upgrade.

Step 1 Check the RSP bootup ROMMON region (ROM0 or ROM1). The example, shows the RSP boots up from ROM0 region.

### **Example:**

System Bootstrap, Version 15.2(1r)S1, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 2011 by cisco Systems, Inc.

```
Compiled Wed 07-Dec-11 07:33 by tinhuang Current image running: Boot {\tt ROM0}
```

**Step 2** Copy the ROMMON image to the bootflash on the active and standby RSP.

#### Example:

```
copy bootflash:rsp2_15_6_15r_s_rommon.pkg
```

- Step 3 Use the upgrade rom-monitor filename rsp2 15 6 15r s rommon.pkg R0 command to upgrade the version.
  - R0 represents RSP in slot0 of the chassis. Step 3 upgrades the ROMMON region of the RSP that is not used (ROM1 region) as ROM 0 region is used (in this procedure) in Step 1 to boot up the RSP.
- **Step 4** Reload the router.

### **Example:**

```
System Bootstrap, Version 15.6(12r)S, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 2016 by cisco Systems, Inc.
Compiled Sun 29-May-16 08:45 by sabind
Starting Initialization of FMANO
Loading ucode for FMANO, size: 31424, ver: 106.04.14
fixup address:7ffff278 contentsoffixup:7ffff000
DCFG CCSR PORSR1(cfg 0 9 pins):22FB7F7F
RC Vendor ID[0x8241957]
PEX up stream Vendor ID[0x860910b5]
PEX down stream vendor ID [0x860910b5]
FPGA vendor ID[0x5f1137]
PCI Configuration done.
IOFPGA version[16040627]
Current image running: Boot ROMO
Last reset cause: RSP-Board
Rommon upgrade requested
Flash upgrade reset 1 in progress
.....BootPage Setting Done - Next DDR-init
System Bootstrap, Version 15.6(14r)S, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 2017 by cisco Systems, Inc.
Compiled Sat 07-Jan-17 10:23 by sabind
Starting Initialization of FMANO
Loading ucode for FMANO, size: 31424, ver: 106.04.14
fixup address:7fffff278 contentsoffixup:7fffff000
DCFG CCSR PORSR1(cfg 0 9 pins):22FB7F7F
RC Vendor ID[0x8241957]
PEX up stream Vendor ID[0x860910b5]
PEX down stream vendor ID [0x860910b5]
FPGA vendor ID[0x5f1137]
PCI Configuration done..
IOFPGA version[16040627]
Current image running: *Upgrade in progress* Boot ROM1
Last reset cause: BootRomUpgrade
Configuring zarlink...
We're coming up from a flash upgrade reset cookie
C-Inlet temp 32C
ARAD-0 temp 44C
UEA platform with 3670016 Kbytes of main memory
We're coming up from a flash upgrade reset cookie
```

System Bootstrap, Version 15.6(14r)S, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport

```
Copyright (c) 2017 by cisco Systems, Inc. Compiled Sat 07-Jan-17 10:23 by sabind
Starting Initialization of FMAN0
Loading ucode for FMANO, size: 31424, ver: 106.04.14
fixup address:7ffff278 contentsoffixup:7ffff000
DCFG CCSR_PORSR1(cfg_0_9 pins):22FB7F7F
RC Vendor ID[0x8241957]
PEX up stream Vendor ID[0x860910b5]
PEX down stream vendor ID [0x860910b5]
FPGA vendor ID[0x5f1137]
PCI Configuration done.
IOFPGA version[16040627]
Current image running: *Upgrade in progress* Boot ROM1
Last reset cause: BootRomUpgrade
Configuring zarlink...
We're coming up from a flash upgrade reset cookie
C-Inlet temp 32C
ARAD-0 temp 44C
UEA platform with 3670016 Kbytes of main memory
```

**Step 5** Reload the router again to confirm bootup from upgraded ROMMON region ROM1.

### **Example:**

```
System Bootstrap, Version 15.6(14r)S, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 2017 by cisco Systems, Inc. Compiled Sat 07-Jan-17 10:23 by sabind
```

Current image running: Boot ROM1

Step 6 Repeat Step 3 to Step 6 to update the other region on the RSP (ROM0) region in this procedure.

Note We recommend that both region ROM0 and ROM1 are upgraded.

### **Example: Verifying ROMMON Upgrade on the RSP2 Module**

Use the show platform command to verify the ROMMON upgrade.

Router# show platform Chassis type: ASR-903

Slot	Туре	State	Insert time (ago)
0/1 0/2 0/3 0/4 R0	A900-IMA8T A900-RSP2A-128 A900-RSP2A-128	ok booting booting ok ok ok, active init, standby init, active init, standby ok	00:00:47 00:00:47 00:00:47 00:00:47 00:00:47 00:03:11 00:03:11 00:03:11 00:03:11 00:02:29 never
P2	A903-FAN	ok	00:02:26
Slot	CPLD Version	Firmware Version	
R0 R1 F0 F1	16032304	15.6(15r)S 15.6(15r)S 15.6(15r)S 15.6(15r)S	

## **Upgrading the ROMMON on the RSP3 Module**

The router has two ROMMON regions (ROM0 and ROM1). We recommend that the upgrade is performed on both the regions.



To avoid actions that might make your system unable to boot, read this entire section before starting the upgrade.

**Step 1** Check the RSP bootup ROMMON region (ROM0 or ROM1). The example, shows the RSP boots up from ROM0 region.

### **Example:**

```
System Bootstrap, Version 15.2(1r)S1, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 2011 by cisco Systems, Inc. Compiled Wed 07-Dec-11 07:33 by tinhuang Current image running: Boot ROMO
```

**Step 2** Copy the ROMMON image to the bootflash on the active and standby RSP.

#### **Example:**

```
copy bootflash:rsp3 15 6 14r s rommon.pkg
```

- Step 3 Use the upgrade rom-monitor filename rsp3\_15\_6\_14r\_s\_rommon.pkg R0 command to upgrade the version.
  - **Note** R0 represents RSP in slot0 of the chassis. Step 3 upgrades the ROMMON region of the RSP that is not used (ROM1 region) as ROM 0 region is used (in this procedure) in Step 1 to boot up the RSP.
- Step 4 Upgrade the ROMMON on the Standby RSP (for High Availability) using upgrade rom-monitor filename bootflash:rsp3\_15\_6\_14r\_s\_rommon.pkg R1 command.
  - Note R1 represents the RSP in slot1 of the chassis. Step 4 upgrades the ROMMON region of the RSP that is not used (ROM 0 region)
- **Step 5** Reload the router.

#### **Example:**

```
System Bootstrap, Version 15.6(12r)S, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 2016 by cisco Systems, Inc.
Compiled Sun 29-May-16 08:45 by sabind
Starting Initialization of FMAN0
Loading ucode for FMANO, size: 31424, ver: 106.04.14
fixup address:7fffff278 contentsoffixup:7fffff000
DCFG_CCSR_PORSR1(cfg_0_9 pins):22FB7F7FRC Vendor ID[0x8241957]
PEX up stream Vendor ID[0x860910b5]
PEX down stream vendor ID [0x860910b5]
FPGA vendor ID[0x5f1137]
PCI Configuration done.
IOFPGA version[16040627]
Current image running: Boot ROMO
Last reset cause: RSP-Board
Rommon upgrade requested
Flash upgrade reset 1 in progress
.....BootPage Setting Done - Next DDR-init
```

```
System Bootstrap, Version 15.6(14r)S, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 2017 by cisco Systems, Inc.
Compiled Sat 07-Jan-17 10:23 by sabind
Starting Initialization of FMANO
Loading ucode for FMANO, size: 31424, ver: 106.04.14
fixup address:7fffff278 contentsoffixup:7fffff000
DCFG CCSR PORSR1(cfg 0 9 pins):22FB7F7F
RC Vendor ID[0x8241957]
PEX up stream Vendor ID[0x860910b5]
PEX down stream vendor ID [0x860910b5]
FPGA vendor ID[0x5f1137]
PCI Configuration done.
IOFPGA version[16040627]
Current image running: *Upgrade in progress* Boot ROM1
Last reset cause: BootRomUpgrade
Configuring zarlink...
We're coming up from a flash upgrade reset cookie
C-Inlet temp 32C
ARAD-0 temp 44C
UEA platform with 3670016 Kbytes of main memory
We're coming up from a flash upgrade reset cookie
```

```
System Bootstrap, Version 15.6(14r)S, RELEASE SOFTWARE (fc1)
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 2017 by cisco Systems, Inc. Compiled Sat 07-Jan-17 10:23 by sabind
Starting Initialization of FMANO
Loading ucode for FMANO, size: 31424, ver: 106.04.14
fixup address:7ffff278 contentsoffixup:7ffff000
DCFG CCSR PORSR1(cfg_0_9 pins):22FB7F7F
RC Vendor ID[0x8241957]
PEX up stream Vendor ID[0x860910b5]
PEX down stream vendor ID [0x860910b5]
FPGA vendor ID[0x5f1137]
PCI Configuration done.
IOFPGA version[16040627]
Current image running: *Upgrade in progress* Boot ROM1
Last reset cause: BootRomUpgrade
Configuring zarlink...
We're coming up from a flash upgrade reset cookie
C-Inlet temp 32C
ARAD-0 temp 44C
UEA platform with 3670016 Kbytes of main memory
```

### **Step 6** Reload the router again to confirm bootup from upgraded ROMMON region ROM1.

### **Example:**

```
System Bootstrap, Version 15.6(14r)S, RELEASE SOFTWARE (fc1) Technical Support: http://www.cisco.com/techsupport Copyright (c) 2017 by cisco Systems, Inc. Compiled Sat 07-Jan-17 10:23 by sabind
```

Current image running: Boot ROM1

Repeat Step 3 to Step 6 to update the other region on the RSP (ROM0) region in this procedure.Note We recommend that both region ROM0 and ROM1 are upgraded.

### **Example: Verifying ROMMON Upgrade on the RSP3 Module**

Use the show platform command to verify the ROMMON upgrade.

Router# show platform Chassis type: ASR-903

Slot	Type	State	Insert time (ago)
0/1 0/2 0/3 0/4	A900-IMA1X A900-IMA8S A900-IMA8S1Z A900-IMA2Z A900-IMA8Z A900-IMA8T	ok ok ok ok	18:23:52 18:23:52 18:22:19 18:21:43 18:23:52 18:23:52
R0 R1 F0 F1 P0	A900-PWR550-A A900-PWR550-D A903-FAN	ok, active unknown ok, active unknown ok	18:25:38 18:25:38 18:25:38 18:25:38 18:25:38 18:24:54 18:24:52
Slot	CPLD Version	Firmware Version	
R0 R1 F0 F1	16040627	15.6(14r)S 15.6(14r)S 15.6(14r)S 15.6(14r)S	