



New and Changed Information

- [New and Changed Information](#), on page 1

New and Changed Information

The table below summarizes the new and changed features for this document and shows the releases in which each feature is supported. Your software release might not support all the features in this document. For the latest caveats and feature information, see the Bug Search Tool and the release notes for your software release.

Table 1: New and Changed Information

Feature	Description	Changed in Release
Supervisor-to-Supervisor EOBC Link Redundancy	This feature provides redundancy for EOBC communication between the active and standby supervisors by enabling the secondary redundant EOBC link in case the primary EOBC link fails and vice-versa.	8.4(1)
Internal CRC Error Detection and Isolation	This feature enables the switches to detect CRC errors that occur internally within a switch and isolate the source of these errors when the configured threshold value is reached.	8.4(1)
Message and Transaction Service	The System Message Logging contains new logs that indicates the highest MTS memory users. Additionally, detailed memory usage stats with timestamps are collected per application.	8.0(1)

