



Known issues

- [Known issues in Release 6.0\(1.260006\)](#) — None, on page 1
- [Known issues in Release 6.0\(2.260045\)](#), on page 1
- [Known issues in Release 6.0\(1.260003\)](#) — None, on page 1

Known issues in Release 6.0(1.260006) — None

Known issues in Release 6.0(2.260045)

This section provides a brief description of the known issues.

Defect ID	Description	Workaround	First Version Affected
CSCwr50750	On Cisco UCS Fabric Interconnects Series 6600, 6500, 6400, and X-Series Direct Fabric Interconnects, when the management interface is configured with IPv6, a syslog message is displayed if the device receives a Router Advertisement (RA) packet containing an ICMPv6 MTU option greater than 1500 bytes. This message indicates an MTU mismatch but does not impact functionality.	No workaround is required; the syslog message can be safely ignored.	6.0(1.250223)

Known issues in Release 6.0(1.260003) — None

