

## **Resolved** issues

• Resolved issues in Cisco UCS C-Series M8, M7, and M6 6.0(1.250127) Server Firmware Release, on page 1

## Resolved issues in Cisco UCS C-Series M8, M7, and M6 6.0(1.250127) Server Firmware Release

This section provides a brief description of the resolved issues.



Note

This software release may contain bug fixes first introduced in other releases. To see additional information, click the bug ID to access the Cisco Bug Search Tool.

Defect ID	Description	First Version Affected	Resolved in Release
CSCwn99720	On Cisco UCS C-Series M8 servers with Intel processors and an R1S CPU configured in a single-CPU setup on the 2-socket platform, Intel SGX remains disabled even after being enabled in the BIOS. This issue does not occur with a dual CPU configuration.	4.3(6.250039)	6.0(1.250127) 4.3(6.250044)

Resolved issues in Cisco UCS C-Series M8, M7, and M6 6.0(1.250127) Server Firmware Release