



## Information Relocated - Multi-Lingual Support Feature Module

Revised: April 15, 2008

For the latest information on this Cisco BTS 10200 Softswitch feature, see:

Information	Link to Information in the Standard Documentation Set	Document Name
Media servers compatibility	<a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/release/note/BTSRN_50x.html#wp2356260">http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/release/note/BTSRN_50x.html#wp2356260</a>	<i>Release Notes</i>
Description of feature, feature interactions, MLS announcements	<a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1052163">Feature descriptions - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1052163</a> <a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1051663">MLS with ThinkEngine or IPUnity - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1051663</a> <a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1051674">MLS with IOS - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1051674</a> <a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1051728">Announcements - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5050iv.html#wp1051728</a>	<i>Network and Subscriber Feature Descriptions</i>
Provisioning procedures	<a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/command/guide/feature.html#wp1582403">http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/command/guide/feature.html#wp1582403</a>	<i>Provisioning Guide</i>
MLS counters	<a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/maintenance/guide/Trfc1.html#wp1172226">http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/maintenance/guide/Trfc1.html#wp1172226</a>	<i>Operations and Maintenance Guide</i>
MLS alarms and corrective procedures	<a href="http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/troubleshooting/guide/06tg01.html#wp1299827">http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/troubleshooting/guide/06tg01.html#wp1299827</a>	<i>Troubleshooting Guide</i>



**Americas Headquarters:**  
**Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA**

© 2007 Cisco Systems, Inc. All rights reserved.

