

# Cisco Unified Communications Device Package 15.0(1.13014-1) Release Notes

First Published: 2025-02-27

## Introduction

Cisco Unified Communications Manager Device Package Release 15.0(1.13014-1) provides database and firmware updates for Cisco Unified Communications Manager 15.

For information about all released Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Compatibility Matrix](#).

For information about how to install Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Installation Guide](#).



**Caution** Installing the Device Package on the Publisher causes all of the device XML data to be reloaded into the database. This can cause high CPU on the Subscribers while these changes are being processed. It is recommended that Device Package installations occur during a maintenance window to minimize the impact of the database updates.

## Cisco Unified Communications Device Package 15



**Caution** After applying the device package COP file, make sure that any future full upgrades are to a version that contains the device package fixes natively. Otherwise, some of the functionality added by the device package may be lost following the upgrade. If an upgrade to a version that does not contain the fixes natively is necessary, install the appropriate device package COP file to restore functionality.

The Cisco Unified Communications Manager Device Package 15.0(1.13014-1) filename and MD5 are in the following table.

Table 1: Cisco Options Package Filename and MD5

File	MD5
cmterm-devicepack15.0.1.13014-1.cop.sha512	e36684e43a9dde5178606efcf50edac7

Use the information in the following table to determine if you must install this device package.

Table 2: Cisco Unified Communications Manager Device Package Release 15.0(1.13014-1)

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
IP Phone 6901	CSCwn90249	6901 ip phone fails to upgrade to 9.3(1)SR3 when using COP file	No	Yes	For more information, see <a href="https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwn90249">https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwn90249</a> .
Desk Phone 9800 Series / Cisco Video Phone 8875	CSCwn60280	checkin PhoneOS 3.3(1) QED files	Yes	No	For more information, see <a href="https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwn60280">https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwn60280</a> .
Cisco Headsets	CSCwn61488	HS 3.3.1.1 Release COP file checkin to cucm branches	No	Yes	For more information, see <a href="https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwn61488">https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwn61488</a> .

## Firmware Table

The Cisco Unified Communications Manager Device Package Release 15.0(1.13014-1) contains loads for the following device releases.



**Note** The device package also contains configuration files for many Cisco Webex models. If there are any new configuration files for these models, they are listed in the previous table: [Cisco Unified Communications Device Package 15, on page 1](#). You can get the latest firmware for these models from the [Download Software](#) page.



**Note** Starting with the PhoneOS 3.2(1) release, the Video Phone 8875 now shares the same firmware files as the Desk Phone 9800 Series endpoints. There is no longer a standalone 8875 firmware file included in the Device Packs.

### Firmware Versions in this Release

Device type	Load name	Version
3905	3905.9-4-1SR4-2	9.4 (1SR4.2)
6901-sccp	6901-sccp.9-3-1-SR3-2.k4	9.3 (1.0)
6901-sip	6901-sip.9-3-1-SR3-2.k4	9.3 (1.0)
7832-sip.14	7832-sip.14-3-1-0001-60.k4	3.1 (0001.60)
78xx.14	78xx.14-3-1-0001-60.k4	3.1 (0001.60)
8821-sip	8821-sip.11-0-6SR5-5.k4	11.0 (6SR5.5)
8832-sip.14	8832-sip.14-3-1-0001-60.k4	3.1 (0001.60)
8845_65-sip.14	8845_65-sip.14-3-1-0001-60.k4	3.1 (0001.60)
88xx-sip.14	88xx-sip.14-3-1-0001-60.k4	3.1 (0001.60)
ATA191.12	ATA191.12-0-2-0001-011	0.2 (0001.11)
headset-builtin	headset-builtin.3-3-0001-1.k4	3.3 (0001.1)

