

Cisco Unified Communications Device Package 15.0(1.13010-1) Release Notes

First Published: 2024-11-21

Introduction

Cisco Unified Communications Manager Device Package Release 15.0(1.13010-1) provides database and firmware updates for Cisco Unified Communications Manager 15.

For information about all released Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Compatibility Matrix](#).

For information about how to install Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Installation Guide](#).



Caution Installing the Device Package on the Publisher causes all of the device XML data to be reloaded into the database. This can cause high CPU on the Subscribers while these changes are being processed. It is recommended that Device Package installations occur during a maintenance window to minimize the impact of the database updates.

Cisco Unified Communications Device Package 15



Caution After applying the device package COP file, make sure that any future full upgrades are to a version that contains the device package fixes natively. Otherwise, some of the functionality added by the device package may be lost following the upgrade. If an upgrade to a version that does not contain the fixes natively is necessary, install the appropriate device package COP file to restore functionality.

The Cisco Unified Communications Manager Device Package 15.0(1.13010-1) filename and MD5 are in the following table.

Table 1: Cisco Options Package Filename and MD5

File	MD5
cmterm-devicepack15.0.1.13010-1.cop.sha512	48c47ab8272100222dbe5b8d91601648

Use the information in the following table to determine if you must install this device package.

Table 2: Cisco Unified Communications Manager Device Package Release 15.0(1.13010-1)

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
IP Phone 7800/8800 Series	CSCwm36024	14.3(1) SIP phone loads firmware for 7800 and 8800 IP Phones	No	Yes	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwm36024 .
Desk Phone 9800 Series	CSCwm67785	PhoneOS Release 3.2(1) QED files	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwm67785 .
Desk Phone 9800 Series	CSCwm04901	ALL: CUCM: Typo in source string '9800_KEM'	Yes	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwm04901 .
Desk Phone 9800 Series	CSCwm84657	remove 8875 firmware	No	No	For more information, see https://bst.cloudapps.cisco.com/bugsearch/bug/CSCwm84657 .

Firmware Table

The Cisco Unified Communications Manager Device Package Release 15.0(1.13010-1) contains loads for the following device releases.



Note The device package also contains configuration files for many Cisco Webex models. If there are any new configuration files for these models, they are listed in the previous table: [Cisco Unified Communications Device Package 15, on page 1](#). You can get the latest firmware for these models from the [Download Software](#) page.



Note Starting with the PhoneOS 3.2(1) release, the Video Phone 8875 now shares the same firmware files as the Desk Phone 9800 Series endpoints. There is no longer a standalone 8875 firmware file included in the Device Packs.

Firmware Versions in this Release

Device type	Load name	Version
3905	3905.9-4-1SR4-2	9.4 (1SR4.2)
6901-sccp	6901-sccp.9-3-1-SR3-1	9.3 (1.0)
6901-sip	6901-sip.9-3-1-SR3-1	9.3 (1.0)
7832-sip	7832-sip.14-3-1-0001-60.k4	14.3.1 (0001.60)
78xx	78xx.14-3-1-0001-60.k4	14.3.1 (0001.60)
8821-sip	8821-sip.11-0-6SR5-5.k4	11.0 (6SR5.5)
8832-sip	8832-sip.14-3-1-0001-60.k4	14.3.1 (0001.60)
8845_65-sip	8845_65-sip.14-3-1-0001-60.k4	14.3.1 (0001.60)
88xx-sip	88xx-sip.14-3-1-0001-60.k4	14.3.1 (0001.60)

ATA191	ATA191.12-0-2-0001-011	12.0.2 (0001.11)
headset-builtin	headset-builtin.3-2-0001-1.k4	3.2 (0001.1)

