

Release Notes for Cisco Embedded Wireless Controller on Catalyst Access Points, Cisco IOS XE Bengaluru 17.5.x

First Published: 2021-03-31

Release Notes for Cisco Embedded Wireless Controller on Catalyst Access Points, Cisco IOS XE Bengaluru 17.5.x



Note

The documentation set for this product strives to use bias-free language. For purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on standards documentation, or language that is used by a referenced third-party product.

Introduction to Cisco Embedded Wireless Controller on Catalyst Access Points

The Cisco Embedded Wireless Controller on Catalyst Access Points is a version of the Cisco IOS XE-based controller software on Catalyst access points. In this solution, a Catalyst access point (AP) that is running the Cisco Embedded Wireless Controller on Catalyst Access Points software, is designated as the primary AP. Other APs, referred to as subordinate APs, associate to this primary AP.

The Cisco Embedded Wireless Controller on Catalyst Access Points provides enterprise-level WLAN features while maintaining operational simplicity and affordability. This solution is targeted at small and medium-sized business (SMB) customers or distributed enterprises, and can be run at single site deployments.

- The controllers come with high availability (HA) and seamless software updates. This keeps your services on always, both during planned and unplanned events.
- The deployment can be managed using a mobile application, Cisco Digital Network Architecture (DNA) Center, Netconf/Restconf, web-based GUI, or CLI.

What's New in Cisco Embedded Wireless Controller on Catalyst Access Points, Cisco IOS XE Bengaluru 17.5.x

Feature Name	Description and Documentation Link	
Enable or Disable 11ax Features per SSID	From this release onwards, a 11ax configuration knob, per VAP, is introduced under the WLAN profile. When 11ax is enabled per radio, the 11ac clients can scan or connect to the SSID, if the beacon has 11ax information elements.	
	For more information, see the 802.11ax Per Virtual Access Point chapter.	
Track AP CPU Usage for AP Health	From this release, you can track the CPU utilization and the memory usage of an AP, and monitor the health of the AP by generating real-time AP statistics.	
	The following commands were introduced:	
	• statistics ap-system-monitoring enable	
	 statistics ap-system-monitoring sampling-interval 	
	• statistics ap-system-monitoring stats-interval	
	• statistics ap-system-monitoring alarm-enable	
	 statistics ap-system-monitoring alarm-hold-time 	
	 statistics ap-system-monitoring alarm-retransmit-time 	
	• statistics ap-system-monitoring cpu-threshold	
	 statistics ap-system-monitoring mem-threshold 	
	• trapflags ap ap-stats	
	For more information, see the Access Points Real-Time Statistics chapter.	

Table 1: New and Modified Software Features

Feature Name	Description and Documentation Link	
Support for both MIC and LSC APs to Join the Same Controller	From this release, the new authorization policy configuration allows MIC access points (APs) to join the LSC-deployed controller, so that the LSC and MIC APs can co-exist in the controller, at the same time.	
	The following commands were introduced:	
	• ap auth-list ap-cert-policy allow-mic-ap trustpoint	
	• ap auth-list ap-cert-policy {mac-address H.H.H serial-number serial-number-ap} policy-type mic	
	For more information, see the Locally Significant Certificates chapter.	
Intermediate CA Support for AP Authentication	This feature is an extension support to the existing Locally Significant Certificates (LSC) feature.	
	If your Locally Significant Certificate has been issued by an Intermediate CA, you must import the complete chain of CA certificates into the Trustpool. Otherwise, you will not be able to provision the APs without the complete chain being present on the controller. This is not required if the certificate has been issued by a Root CA.	
	The following commands were introduced:	
	• crypto pki trustpoint	
	• crypto pki trust pool import terminal	
	• crypto pki trustpool clean	
	For more information, see the Locally Significant Certificates chapter.	

Table 2: New and Modified GUI Features

I

Feature Name	GUI Path
AP Real-Time Statistics	 Configuration > AP Join > Add Window > AP Tab > AP Statistics Tab
Enable or Disable 11ax Features per SSID	Configuration > Tags & Profiles > WLANs
Intermediate CA Support for AP Authentication	Configuration > Security > PKI Management

Feature Name	GUI Path
Support for both MIC and LSC APs to Join the Same Controller	• Configuration >Wireless > Access Points

Behavior Changes

- From this release, the list of ASCII characters supported for the SSID, AP name, tags, and profiles are modified as follows:
 - SSID: ASCII characters from 32 to 126, with leading and trailing spaces.
 - AP Name: ASCII characters from 33 to 126, without leading and trailing spaces.
 - Tags and Profiles: ASCII characters from 32 to 126, without leading and trailing spaces.

To see the list of ASCII characters, go to the following URL: ASCII Character Set and Hexadecimal Values

- If the RP and RMI links are down, the HA setup breaks into two active controllers. This leads to IP conflict in the network. The HA setup forms again when the RP link comes up. Depending on the state of the external switch at this time, the ARP table may or may not be updated to point to the Active controller. That is, the switch may fail to process the GARP packets from the controller. As a best practice, it is recommended to keep the ARP cache timeout to a lower value for faster recovery from multiple fault scenarios. You need to select a value that does not impact the network traffic, for instance, 30 minutes.
- Standby detects the presence of the Active over the RMI link and avoids switchover when the RP link goes down. In such a case, the standby goes to recovery mode. This mode is represented through suffix **rp-rec-mode** in the hostname. The standby in recovery mode reloads when the RP link comes up. Single faults are gracefully handled in the system.
- Spectrum Intelligence is supported on Cisco Catalyst 9105AX Series Access Points.

Supported Cisco Access Point Platforms

The following Cisco access points are supported in the Cisco Embedded Wireless Controller on Catalyst Access Points network. Note that the APs listed as primary APs can also function as subordinate APs.

P	rimary AP	Subordinate AP
C	isco Catalyst 9115 Series	Cisco Aironet 1540 Series
C	isco Catalyst 9117 Series	Cisco Aironet 1560 Series
C	isco Catalyst 9120 Series	Cisco Aironet 1815i
C	isco Catalyst 9130 Series	Cisco Aironet 1815w
C	isco Catalyst 9105AXI	Cisco Aironet 1830 Series
		Cisco Aironet 1840 Series
		Cisco Aironet 1850 Series
		Cisco Aironet 2800 Series
		Cisco Aironet 3800 Series
		Cisco Aironet 4800 Series
		Cisco Catalyst 9115 Series
		Cisco Catalyst 9117 Series
		Cisco Catalyst 9120 Series
		Cisco Catalyst 9130 Series
		Cisco Catalyst 9105AXW
		Cisco Catalyst 9105AXI
		Cisco Catalyst Industrial Wireless 6300 Heavy Duty Series Access Points
		Cisco 6300 Series Embedded Services Access Points

Table 3: Cisco APs Supported in Cisco Embedded Wireless Controller on Catalyst Access Points

Table 4: Image Types and Supported APs in Cisco Embedded Wireless Controller on Catalyst Access Points

Image Type	Supported APs
ap1g4	Cisco Aironet 1810 Series
	Cisco Aironet 1830 Series
	Cisco Aironet 1850 Series
ap1g5	Cisco Aironet 1815i
	Cisco Aironet 1815w
	Cisco Aironet 1540 Series
	Cisco Aironet 1850 Series
ap1g6	Cisco Catalyst 9117 Series
ap1g6a	Cisco Catalyst 9130 Series

Image Type	Supported APs
ap1g7	Cisco Catalyst 9115 Series
	Cisco Catalyst 9120 Series
ap1g8	Cisco Catalyst 9105 Series
ap3g3	Cisco Aironet 2800 Series
	Cisco Aironet 3800 Series
	Cisco Aironet 4800 Series
	Cisco Aironet 1560 Series
	Cisco Catalyst Industrial Wireless 6300 Heavy Duty Series Access Points
	Cisco 6300 Series Embedded Services Access Points

Maximum APs and Clients Supported

Table 5: Scale Supported in Cisco EWC Network

Primary AP Model	Maximum APs Supported	Maximum Clients Supported
Cisco Catalyst 9105 AWI	50	1000
Cisco Catalyst 9115 Series	50	1000
Cisco Catalyst 9117 Series	50	1000
Cisco Catalyst 9120 Series	100	2000
Cisco Catalyst 9130 Series	100	2000

Note

If 25 to 100 APs have joined the EWC network, the maximum clients on the EWC internal AP is limited to 20.

Compatibility Matrix

The following table provides software compatibility information:

Cisco Embedded Wireless Controller on Catalyst Access Points	Cisco ISE	Cisco CMX	Cisco DNA Center
Bengaluru 17.5.x	3.0	10.6.3	2.2.2
	2.7	10.6.2	2.2.1
	2.6	10.6	2.1.260
	2.4	10.5.1	
	2.3		

Table 6: Compatibility Information

Supported Browsers and Operating Systems for Web UI

•	

Note The following list of Supported Browsers and Operating Systems is not comprehensive at the time of writing this document and the behavior of various browser for accessing the GUI of the EWC is as listed below.

Browser	Version	Operating System	Status	Workaround
Google Chrome	77.0.3865.120	macOS Mojave Version 10.14.6	Works	Proceed through the browser warning.
Safari	13.0.2 (14608.2.40.1.3)	macOS Mojave Version 10.14.6	Works	Proceed through the browser warning.
Mozilla Firefox	69.0.1	macOS Mojave Version 10.14.6	Works only if exception is added.	Set the exception.
Mozilla Firefox	69.0.3	macOS Mojave Version 10.14.6	Works only if exception is added.	Set the exception.
Google Chrome	77.0.3865.90	Windows 10 Version 1903 (OS Build 18362.267)	Works	Proceed through the browser warning.
Microsoft Edge	44.18362.267.0	Windows 10 Version 1903 (OS Build 18362.267)	Works	Proceed through the browser warning.
Mozilla Firefox	68.0.2	Windows 10 Version 1903 (OS Build 18362.267)	Works	Proceed through the browser warning.
Mozilla Firefox	69.0.3	Windows 10 Version 1903 (OS Build 18362.267)	Works only if exception is added.	Set the exception.

Table 7: Supported Browsers and Operating Systems

Browser	Version	Operating System	Status	Workaround
Google Chrome	78.0.3904.108	macOS Catalina 10.15.1	Does not work	NA

Upgrading the Controller Software

This section covers the various aspects of upgrading the controller software.

Note Before converting from CAPWAP to embedded wireless controller (EWC), ensure that you upgrade the corresponding AP with the CAPWAP image in Cisco AireOS Release 8.10.105.0. If this upgrade is not performed, the conversion will fail.

Finding the Software Version

The following table lists the Cisco IOS XE 17.5.x software for Cisco Embedded Wireless Controller on Catalyst Access Points.

Choose the appropriate AP software based on the following:

- Cisco Embedded Wireless Controller on Catalyst Access Points software to be used for converting the AP from an unified wireless network CAPWAP lightweight AP to a Cisco Embedded Wireless Controller on Catalyst Access Points-capable AP (primary AP)
- AP software image bundle to be used either for upgrading the Cisco Embedded Wireless Controller on Catalyst Access Points software on the primary AP or for updating the software on the subordinate APs or both

Prior to ordering Cisco APs, see the corresponding ordering guide for your Catalyst or Aironet access point.

Table 8: Cisco Embedded Wireless Controller on C	Catalyst Access Points Software
--	---------------------------------

Primary AP	AP Software for Conversion from CAPWAP to Cisco EWC	AP Software Image Bundle for Upgrade	AP Software in the Bundle
Cisco Catalyst 9115 Series	C9800-AP-universalk9.17.05.01.zip	C9800-AP-universalk9.17.05.01.zip	ap1g7
Cisco Catalyst 9117 Series	C9800-AP-universalk9.17.05.01.zip	C9800-AP-universalk9.17.05.01.zip	ap1g6
Cisco Catalyst 9120 Series	C9800-AP-universalk9.17.05.01.zip	C9800-AP-universalk9.17.05.01.zip	ap1g7
Cisco Catalyst 9130 Series	C9800-AP-universalk9.17.05.01.zip	C9800-AP-universalk9.17.05.01.zip	ар1дба

Internet Group Management Protocol (IGMP)v3 is not supported on Cisco Aironet Wave 2 APs.

Embedded Wireless Controller SNMP configuration is supported in DNAC.

High memory usage on AP running Embedded Wireless Controller. Enabling crash kernel on the AP consumes additional memory on the AP. Hence, if crash kernel is enabled, the overall memory usage of the device will increase and will impact the scale numbers. On Cisco Catalyst 9130 Series Access Points, the memory consumption is a high of 128 MB.

Hardware or Software Type

Interoperability with Clients

This section describes the interoperability of the controller software with client devices.

The following table describes the configurations used for testing client devices.

Table 9: Test Configuration for Interoperability

Hardware or Software Parameter

Cisco IOS XE Bengaluru 17.5.1
Cisco Aironet Series Access Points
• 1540
• 1560
• 1815i
• 1815w
• 1830
• 1840
• 1850
• 2800
• 3800
• 4800
Cisco Catalyst 9115AX Access Points
Cisco Catalyst 9117AX Access Points
Cisco Catalyst 9120AX Access Points
Cisco Catalyst 9130AX Access Points

Hardware or Software Parameter	Hardware or Software Type
Radio	• 802.11ax
	• 802.11ac
	• 802.11a
	• 802.11g
	• 802.11n (2.4 GHz or 5 GHz)
Security	Open, PSK (WPA2-AES), 802.1X (WPA2-AES) (EAP-FAST, EAP-TLS), WPA3.
Cisco ISE	See Compatibility Matrix, on page 6.
Types of tests	Connectivity, traffic (ICMP), and roaming between two APs

The following table lists the client types on which the tests were conducted. Client types included laptops, hand-held devices, phones, and printers.

Table 10: Client Types

Client Type and Name	Driver / Software Version	
Wi-Fi 6 Devices (Mobile Phone and Laptop)		
Apple iPhone 11	iOS 14.1	
Apple iPhone SE 2020	iOS 14.1	
Dell Intel AX1650w	Windows 10 (21.90.2.1)	
DELL LATITUDE 5491 (Intel AX200)	Windows 10 Pro (21.40.2)	
Samsung S20	Android 10	
Samsung S10 (SM-G973U1)	Android 9.0 (One UI 1.1)	
Samsung S10e (SM-G970U1)	Android 9.0 (One UI 1.1)	
Samsung Galaxy S10+	Android 9.0	
Samsung Galaxy Fold 2	Android 10	
Samsung Galaxy Flip Z	Android 10	
Samsung Note 20	Android 10	
Laptops		
Acer Aspire E 15 E5-573-3870 (Qualcomm Atheros QCA9377)	Windows 10 Pro (12.0.0.832)	
Apple Macbook Air 11 inch	OS Sierra 10.12.6	
Apple Macbook Air 13 inch	OS Catalina 10.15.4	

Client Type and Name	Driver / Software Version
Apple Macbook Air 13 inch	OS High Sierra 10.13.4
Macbook Pro Retina	OS Mojave 10.14.3
Macbook Pro Retina 13 inch early 2015	OS Mojave 10.14.3
Dell Inspiron 2020 Chromebook	Chrome OS 75.0.3770.129
Google Pixelbook Go	Chrome OS 84.0.4147.136
HP chromebook 11a	Chrome OS 76.0.3809.136
Samsung Chromebook 4+	Chrome OS 77.0.3865.105
DELL Latitude 3480 (Qualcomm DELL wireless 1820)	Win 10 Pro (12.0.0.242)
DELL Inspiron 15-7569 (Intel Dual Band Wireless-AC 3165)	Windows 10 Home (18.32.0.5)
DELL Latitude E5540 (Intel Dual Band Wireless AC7260)	Windows 7 Professional (21.10.1)
DELL XPS 12 v9250 (Intel Dual Band Wireless AC 8260)	Windows 10 (19.50.1.6)
DELL Latitude 5491 (Intel AX200)	Windows 10 Pro (21.40.2)
DELL XPS Latitude12 9250 (Intel Dual Band Wireless AC 8260)	Windows 10 Home (21.40.0)
Lenovo Yoga C630 Snapdragon 850 (Qualcomm AC 2x2 Svc)	Windows 10(1.0.10440.0)
Lenovo Thinkpad Yoga 460 (Intel Dual Band Wireless-AC 9260)	Windows 10 Pro (21.40.0)
Note For clients using Intel wireless cards, we redrivers if advertised SSIDs are not visible.	ecommend you to update to the latest Intel wireless
Tablets	
Apple iPad Pro	iOS 13.5
Apple iPad Air2 MGLW2LL/A	iOS 12.4.1
Apple iPad Mini 4 9.0.1 MK872LL/A	iOS 11.4.1
Apple iPad Mini 2 ME279LL/A	iOS 12.0
Microsoft Surface Pro 3 – 11ac	Qualcomm Atheros QCA61x4A
Microsoft Surface Pro 3 – 11ax	Intel AX201 chipset. Driver v21.40.1.3
Microsoft Surface Pro 7 – 11ax	Intel Wi-Fi chip (HarrisonPeak AX201) (11ax, WPA3)
Microsoft Surface Pro X – 11ac & WPA3	WCN3998 Wi-Fi Chip (11ac, WPA3)

Client Type and Name	Driver / Software Version
Mobile Phones	
Apple iPhone 5	iOS 12.4.1
Apple iPhone 6s	iOS 13.5
Apple iPhone 8	iOS 13.5
Apple iPhone X MQA52LL/A	iOS 13.5
Apple iPhone 11	iOS 14.1
Apple iPhone SE MLY12LL/A	iOS 11.3
ASCOM SH1 Myco2	Build 2.1
ASCOM SH1 Myco2	Build 4.5
ASCOM Myco 3 v1.2.3	Android 8.1
Drager Delta	VG9.0.2
Drager M300.3	VG2.4
Drager M300.4	VG2.4
Drager M540	DG6.0.2 (1.2.6)
Google Pixel 2	Android 10
Google Pixel 3	Android 11
Google Pixel 3a	Android 11
Google Pixel 4	Android 11
Huawei Mate 20 pro	Android 9.0
Huawei P20 Pro	Android 9.0
Huawei P40	Android 10
LG v40 ThinQ	Android 9.0
One Plus 8	Android 10
Oppo Find X2	Android 10
Redmi K20 Pro	Android 10
Samsung Galaxy S7	Andriod 6.0.1
Samsung Galaxy S7 SM - G930F	Android 8.0
Samsung Galaxy S8	Android 8.0
Samsung Galaxy S9+ - G965U1	Android 9.0
Samsung Galaxy SM - G950U	Android 7.0
Sony Experia 1 ii	Android 10

I

Client Type and Name	Driver / Software Version
Sony Experia xz3	Android 9.0
Xiaomi Mi10	Android 10
Spectralink 8744	Android 5.1.1
Spectralink Versity Phones 9540	Android 8.1
Vocera Badges B3000n	4.3.2.5
Vocera Smart Badges V5000	5.0.4.30
Zebra MC40	Android 5.0
Zebra MC40N0	Android Ver: 4.1.1
Zebra MC92N0	Android Ver: 4.4.4
Zebra TC51	Android 7.1.2
Zebra TC52	Android 8.1.0
Zebra TC55	Android 8.1.0
Zebra TC57	Android 8.1.0
Zebra TC70	Android 6.1
Zebra TC75	Android 6.1.1
Printers	· · · · ·
Zebra QLn320 Printer	LINK OS 6.3
Zebra ZT230 Printer	LINK OS 6.3
Zebra ZQ310 Printer	LINK OS 6.3
Zebra ZD410 Printer	LINK OS 6.3
Zebra ZT410 Printer	LINK OS 6.3
Zebra ZQ610 Printer	LINK OS 6.3
Zebra ZQ620 Printer	LINK OS 6.3
Wireless Module	
Intel 11ax 200	Driver v22.20.0
Intel AC 9260	Driver v21.40.0
Intel Dual Band Wireless AC 8260	Driver v19.50.1.6

Caveats

Caveats describe unexpected behavior in Cisco IOS releases. Caveats that are listed as Open in a prior release are carried forward to the next release as either Open or Resolved.



Note All incremental releases will cover fixes from the current release.

Cisco Bug Search Tool

The Cisco Bug Search Tool (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click the corresponding identifier.

Open Caveats for Cisco IOS XE Bengaluru 17.5.1

Caveat ID	Description
CSCvx76433	EWC experiences CPUHOG Tracebacks causing downtime (Both Active and Standby went down).

Resolved Caveats for Cisco IOS XE Bengaluru 17.5.1

Caveat ID	Description
CSCvw37272	NMSP process held down while upgrading EWC High Availability via install mode.

Troubleshooting

For the most up-to-date, detailed troubleshooting information, visit the Cisco TAC website at:

https://www.cisco.com/en/US/support/index.html

Go to **Product Support** and select your product from the list, or enter the name of your product. Look under **Troubleshoot and Alerts** to find information about the problem that you are experiencing.

Related Documentation

Information about Cisco IOS XE 16 is available at:

https://www.cisco.com/c/en/us/products/ios-nx-os-software/ios-xe/index.html

All the support documentation for Cisco Catalyst 9100 Access Points are available at: https://www.cisco.com/ c/en/us/support/wireless/catalyst-9100ax-access-points/tsd-products-support-series-home.html

Cisco Validated Designs documents are available at:

https://www.cisco.com/go/designzone

Cisco Embedded Wireless Controller on Catalyst Access Points

For support information, see the following documents:

- Cisco Wireless Solutions Software Compatibility Matrix
- Cisco Embedded Wireless Controller on Catalyst Access Points Online Help
- Cisco Embedded Wireless Controller on Catalyst Access Points Software Configuration Guide
- Cisco Embedded Wireless Controller on Catalyst Access Points Command Reference Guide

Installation guides for Catalyst Access Points are available at:

https://www.cisco.com/c/en/us/support/wireless/catalyst-9100ax-access-points/ products-installation-guides-list.html

For all Cisco Wireless Controller software-related documentation, see:

https://www.cisco.com/c/en/us/support/wireless/catalyst-9800-series-wireless-controllers/tsd-products-support-series-home.html

Wireless Products Comparison

• Use this tool to compare the specifications of Cisco wireless APs and controllers:

https://www.cisco.com/c/en/us/products/wireless/wireless-lan-controller/product-comparison.html

Product Approval Status:

https://prdapp.cloudapps.cisco.com/cse/prdapp/jsp/ externalsearch.do?action=externalsearch&page=EXTERNAL_SEARCH

Wireless LAN Compliance Lookup:

https://www.cisco.com/c/dam/assets/prod/wireless/wireless-compliance-tool/index.html

Cisco Connected Mobile Experiences

Cisco Connected Mobile Experiences Documentation

Cisco DNA Center

Cisco DNA Center Documentation

Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at Cisco Profile Manager.
- To get the business impact you're looking for with the technologies that matter, visit Cisco Services.
- To submit a service request, visit Cisco Support.
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit Cisco Marketplace.
- To obtain general networking, training, and certification titles, visit Cisco Press.

• To find warranty information for a specific product or product family, access Cisco Warranty Finder.

Cisco Bug Search Tool

Cisco Bug Search Tool (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/c/en/us/about/legal/trademarks.html. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2021 Cisco Systems, Inc. All rights reserved.