


Cisco Firepower Device

Manager(FDM) Denial of Service (DoS) Vulnerability



CVE-2021-1489

2021-04-28 16:00

Final

CVSS: 4.9

No workarounds available

Cisco ID: CSCvt11547 CSCvx30735

Denial of Service (DoS) vulnerability in Cisco Firepower Manager (FDM) versions 1.0 through 1.1.1.1. An attacker can exploit this vulnerability to cause a denial of service condition on the device.

Impact

Cisco Firepower Device

Manager(FDM) versions 1.0 through 1.1.1.1. An attacker can exploit this vulnerability to cause a denial of service condition on the device.

The vulnerability is located in the FDM application. An attacker can exploit this vulnerability to cause a denial of service condition on the device.

The vulnerability is located in the FDM application. An attacker can exploit this vulnerability to cause a denial of service condition on the device.

For more information, see the following link:

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-fdm-dos-nFES8xTN>

References

Denial of Service (DoS) vulnerability in Cisco Firepower Manager (FDM) versions 1.0 through 1.1.1.1.

2021-04-28 16:00

Final

- Firepower 1000 series, versions 1.0 through 1.1.1.1.
- Firepower 2100 series, versions 1.0 through 1.1.1.1.
- Firepower 4100 series, versions 1.0 through 1.1.1.1.
- Firepower 9300 series, versions 1.0 through 1.1.1.1.

2021-04-28 16:00

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。