New and Changed Information

- New and Changed Information, on page 1

New and Changed Information

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.1.

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.1(1a)

Feature	Description	Where Documented
Cisco UCS 64108 Fabric Interconnect	This release introduces Cisco UCS 64108 Fabric Interconnects that support 96 10/25 Gigabit ports in the fabric with 12 40/100 Gigabit uplink ports.	Cisco UCS 64108 Fabric Interconnect