Release Notes for Cisco Configuration Assistant 3.1(1)

Revised on August 12, 2011 for CCA 3.1(1)

Release 3.1(1) of CCA is a minor maintenance release that resolves the following issues found in CCA 3.1.

Reference No.	Description
CSCtr84220	After applying configuration changes from the **Telephony** > **Users and Extensions** > **Voicemail** window, CCA reconfigured CUE DTMF to RFC 2833 (rtp-nte). However, existing IOS/CME dial-peers were still configured with sip-notify. This mismatch caused DTMF to fail for calls to CUE.
CSCtr80941	The copyright date on the About Cisco Configuration Assistant page for CCA 3.1 only displayed the years 2007-2010. This was corrected to display the current year (2011).

No other changes were made in this release.

For complete release information, see the *Release Notes for Cisco Configuration Assistant 3.1*, available on Cisco.com at the following URL:

www.cisco.com/en/US/products/ps7287/prod_release_notes_list.html

Document Number: OL-24327-02