Release Notes For Cisco Business CBW150AX and CBW151AXM, Firmware Version, 10.6.2.0 - 10.0.2.0

Release Notes for Cisco Business CBW150AX and CBW151AXM, Firmware Version, 10.6.2.0

October 2023

These release notes describe the resolved issues and known issues in the Cisco Business CBW150AX Access Points and CBW151AXM Mesh Extenders, Firmware Version 10.6.2.0.

What's New

Added support for Cisco Business Dashboard online/offline connection.

Resolved Issues

This section describes the resolved issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.6.2.0.

Table 1: Resolved Issues

Number	Description
CSCwe75371	Cisco Access Point Software Uncontrolled Resource Consumption Vulnerability.
CSCwf69827	Guest portal page appears twice when connect to guest SSID created by Cisco Business Dashboard.
CSCwf62026	COS Access Point vulnerability of booting up an unsigned image.
CSCwh00028	Access Point is crashing when a particular crafted packet from the client is sent.

Release Notes for Cisco Business CBW150AX and CBW151AXM, Firmware Version, 10.5.2.0

July 2023

These release notes describe the resolved issues and known issues in the Cisco Business CBW150AX Access Points and CBW151AXM Mesh Extenders, Firmware Version 10.5.2.0.

Resolved Issues

This section describes the resolved issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.5.2.0.

Table 2: Resolved Issues

Number	Description
CSCwf87322	Address incorrectly identified bad blocks.
CSCwc61122	Cisco Access Point software denial-of-service (DoS) vulnerability.
CSCwc70131	Cisco Access Point software command injection vulnerability.
CSCwe22253	CBW150AX: Certificate installed from the Cisco Business Dashboard is not visible.

Release Notes for Cisco Business CBW150AX and CBW151AXM, Firmware Version, 10.4.2.0

March 2023

These release notes describe the resolved issues and known issues in the Cisco Business CBW150AX Access Points and CBW151AXM Mesh Extenders, Firmware Version 10.4.2.0.

What's New

This section details new features and modifications available on this firmware release.

Social Media Login has been Re-enabled

The Social Login Authentication method was temporarily disabled in firmware version 10.3.2.0 but has been re-enabled in firmware version 10.4.2.0 with Google and Facebook.

Resolved Issues

This section describes the resolved issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.4.2.0.

Table 3: Resolved Issues

Number	Description
CSCwd07949	Cisco Business Wireless APs Social Login Guest User Authentication Bypass Vulnerability.
CSCwd83507	Cheetah AP IPv6 RFC compliance all ipv6 traffic.

Release Notes for Cisco Business CBW150AX and CBW151AXM, Firmware Version, 10.3.2.0

November 2022

These release notes describe the resolved issues and known issues in the Cisco Business CBW150AX Access Points and CBW151AXM Mesh Extenders, Firmware Version 10.3.2.0.

What's New

This section details new features and modifications available on this firmware release.

- Ability to factory default all devices simultaneously via GUI

- Packet capture capabilities via GUI

- Ability to configure per AP logging to Syslog Server via GUI

- Ability to view installed certificates

Removal of the Social Media Login

The Guest Network Social Login Authentication method was temporarily disabled in firmware version 10.3.2.0 because of an issue causing inconsistent and abnormal behavior.

If the Guest network Social Login authentication was enabled on a guest network before the update, the authentication method will be changed from Social Login to Username and Password.

Users will need to switch this authentication to Web Consent, Email Authentication, or will need to create usernames and passwords for guest users for this feature.

Resolved Issues

This section describes the resolved issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.3.2.0.

Table 4: Resolved Issues

Number	Description
CSCwb09243	Attempting to change password of WLAN user generates mismatch error.
CSCwb40665	MAX_OUI_EXCEEDED message when trying to load OUIs.
CSCwb67264	Logging level change.
CSCwc07729	Remove OSAPI-4-TIME_SHIFT_DETECTED messages in log.
CSCwc41633	Set automatic transmit power for either radio in non-mesh mode.

Release Notes for Cisco Business CBW150AX, CBW151AXM, Firmware Version, 10.2.2.0

July 2022

These release notes describe the resolved issues and known issues in the Cisco Business CBW150AX Access Points, and CBW151AXM Mesh Extenders, Firmware Version, 10.2.2.0.

What's New

- Support for automated software update through Cisco.com.

- Support for Japanese Web UI.

Known Issues

This section describes the known issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.2.2.0.

Table 5: Known Issues

Number	Description
CSCvy45638	The operating systems recognize the iPhone as workstation. **Workaround** N/A

Resolved Issues

This section describes the resolved issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.2.2.0.

Table 6: Resolved Issues

Number	Description
CSCvz12033	Toggle selection issue.
CSCwb73150	OLH update for version 10.2.2.0.
CSCwa57538	The guest network cannot access normally with a Facebook account.
CSCvy38869	Disable Interferer detection does not seem to work.

Where to Find Support

For current support information, visit the following URLs:

Table 7: Where to Find Support

Cisco Small Business Support Resources	
Cisco Small Business Support Community	http://www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	http://www.cisco.com/go/smallbizhelp
Phone Support Contacts	http://www.cisco.com/go/sbsc

Release Notes for Cisco Business CBW150AX, CBW151AXM, Firmware Version, 10.0.2.0

July 2022

These release notes describe the resolved issues and known issues in the Cisco Business CBW150AX Access Points, CBW151AXM Mesh Extender Firmware Version, 10.0.2.0.

Known Issues

This section describes the known issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.0.2.0.

Table 8: Known Issues

Number	Description
CSCvz12033	Toggle selection issue. **Workaround** N/A
CSCvy45638	The operating systems recognize the iPhone as workstation. **Workaround** N/A
CSCwa57538	The guest network cannot access normally with a Facebook account. **Workaround** N/A

Resolved Issues

This section describes the resolved issues for the Cisco Business CBW150AX, CBW151AXM, Firmware Version 10.0.2.0.

Where to Find Support

For current support information, visit the following URLs:

Table 9: Where to Find Support

Cisco Small Business Support Resources	
Cisco Small Business Support Community	http://www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	http://www.cisco.com/go/smallbizhelp
Phone Support Contacts	http://www.cisco.com/go/sbsc