Release Notes for the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version 1.1.3.2

Contents

This document includes the following topics:

Cisco WAP150-361 Wireless-N Dual Radio Access Points Firmware Version 1.1.3.2

May 2021

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.1.3.2.

Known Issues

Ref Number	Description
CSCvs12955	**Symptom:** Sometimes cannot connect to WAP150 and needs to reboot.
CSCvy09603	**Symptom:** WAP remote packet captures work abnormally.

Resolved Issues

The following issues have been fixed in the firmware version 1.1.3.2

Ref Number	Description
CSCvu90590	**Symptom:** Email alerts were not received successfully when the Internet based SMTP server was used.
CSCvv07070	**Symptom:** A fast roaming R1 Key holder does not reflect the correct vap MAC.
CSCvw59995	**Symptom:** Cisco Small Business WAP Series Wireless Access Information Disclosure Vulnerability.
CSCvw59997	**Symptom:** Cisco Small Business WAP Series Wireless Access Point Command Injection Vulnerability.
CSCvx26683	**Symptom:** WAP150 reboots after receiving a SNMP bulkget request.

Cisco WAP150-361 Wireless-N Dual Radio Access Points Firmware Version 1.1.2.4

April 2020

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.1.2.4.

New Features and Enhancements

- New GUI Style

- Support for External Captive Portal (Purple WIFI)

- Support PnP function

- Mobile setup wizard

- Website filtering using Cisco Umbrella

- Packet capture with Cloudshark

- Captive portal login with Windows Active Directory Domain Services (ADDS)

- Captive portal login with Facebook and Google

Limitations

Currently, only English Online help (OLH) supports the External Captive Portal and PnP feature.

Known Issues

Ref Number	Description
CSCvs57889	The Captive Portal page doesn't display when a wireless client tries to open HSTS website using a browser that supports HSTS. **Workaround** Cisco recommends to use a non-HSTS website in order to trigger the captive portal feature properly.

Resolved Issues

The following issues have been fixed in the firmware version 1.1.2.4

Ref Number	Description
CSCvg69584	**Symptom:** WAP150: Static gateway value does not stand across reboot.

Ref Number	Description
CSCvh05688	**Symptom:** WAP150: Wireless with PoE Missing Clickjacking X-Frame-Options.
CSCvi67208	**Symptom:** WAP361: Clients disconnected when error msg print "wl0: wlc_reset: !!!BIG-hammer!!!".
CSCvj49063	**Symptom:** WAP361: Single point setup error.
CSCvn03036	**Symptom:** "0 "is an invalid network address in last network address segment.
CSCvn79645	**Symptom:** WAP361/150: AP hung connection is unstable.
CSCvp73554	**Symptom:** WAP150: RADIUS authentication fails after rebooting the device.
CSCvq31961	**Symptom:** Evaluation of WAP150/361 for TCP SAK vulnerabilities.
CSCvq75662	**Symptom:** Email alerts are not sending out emails.
CSCvs46511	**Symptom:** WAP150: Radio mode is different from what is shown on client PC.
CSCvs57903	**Symptom:** WAP361: Configured SSIDs are lost if Captive Portal is configured in the Setup Wizard.
CSCvs65482	**Symptom:** WAP150: Frequent authentication failure.
CSCvs67516	**Symptom:** System Time is synchronized to UTC+0 time zone after a reboot.
CSCvs87877	**Symptom:** Evaluation of torreypine for Kr00k attack - CVE-2019-15126.
CSCvt00832	**Symptom:** WAP150: Disable QoS mode by default to improve performance.

Cisco WAP150-361 Wireless-N Dual Radio Access Points Firmware Version 1.1.0.9

December 2017

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.1.0.9.

Resolved Issues

The following issue has been fixed in the firmware version 1.1.0.9

Ref Number	Description
CSCvf96803	**Symptom:** WAP150 - Key Reinstallation attacks against WPA protocol.

Cisco WAP150-361 Wireless-N Dual Radio Access Points Firmware Version 1.1.0.7

July 2017

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.1.0.7.

Resolved Issues

The following issue has been fixed in the firmware version 1.1.0.7

Ref Number	Description
CSCve57076	**Symptom:** WAP150: Security Vulnerability "Cross-Site Scripting Attack".

Cisco WAP150-361 Wireless-N Dual Radio Access Points Firmware Version 1.1.0.5

March 2017

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.1.0.5.

New Features and Enhancements

- Support of Cisco FindIt Network Management

- Support Russia SKU

- DHCP Auto Configuration Option (option 66/67) support

Resolved Issues

The following issue has been fixed in the firmware version 1.1.0.5

Ref Number	Description
CSCvb89458	**Symptom:** WAP150: WAP stops broadcasting when 3 SSIDs are enabled.
CSCvc54523	**Symptom:** WAP361: Android DCHP client doesn't get IP.

Known Issues

The following table lists the known issue in firmware version 1.1.0.5

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly. **Workaround** None

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/sbsc
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	www.cisco.com/go/ smallbiz_opensource_request
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco WAP131 and WAP351	www.cisco.com/go/100_wap_resources www.cisco.com/go/300_wap_resources
Regulatory Compliance and Safety Information	www.cisco.com/c/dam/en/us/td/docs/wireless/ access_point/csbap/wap150_361/RCSI/ WAP150_WAP361_ClassB_RCSI.pdf
Warranty Information	www.cisco.com/go/warranty