



The bridge to possible

Product bulletin

Cisco public

End of Support for the H.323 in Cisco Expressway



Contents

Overview 3

Product migration options 3

For more information 3

Overview

Cisco announces the End of Support for H.323 in Cisco Expressway.

Cisco Expressway has provided H.323 support since the 2010 acquisition of Tandberg. Now that most customers use Session Initiation Protocol (SIP) for call routing, there is minimal demand for H.323 functionality.

In acknowledgement of this reduced demand, the Cisco Expressway X15.5.3 release will be the last to provide support for H.323 features. No support for H.323 features will be provided in subsequent releases.

No patches, security fixes or maintenance releases will be provided for H.323 features on 15.5.3 and lower.

Product migration options

Customers are encouraged to migrate to use SIP using the extensive feature set offered in Cisco Expressway.

For more information

For more information about the Cisco End-of-Life Policy, go to:

https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)