# Caveats

# Open Caveats in Cisco Smart PHY 21.3

The following caveats are found in the Cisco Smart PHY application:

| Caveat ID Number | Description |
| --- | --- |
| CSCwa16318 | Cluster details are not listing in the **Container KPI Detail** and **Container KPI Overview** Grafana dashboards. |
| CSCwa44158 | Installation of signed Cisco Smart PHY 21.3 image fails. |
| CSCwa22340 | Smart PHY 21.3 auto deployer mandates `private-key-file` tag in day 0. |
| CSCwa31101 | Sample Inventory and RPD Association CSV templates are broken. |

# Resolved Caveats in Cisco Smart PHY 21.3

The following caveats are resolved in the Cisco Smart PHY 21.3 release:

| Caveat ID Number | Description |
| --- | --- |
| CSCvx76464 | Redis leader election failure - Cisco Smart PHY UI and APIs are affected. |
| CSCvz12369 | Existing Cisco cBR-8 router inventory parameters are not getting updated when the inventory CSV file is used. |
| CSCvz73292 | Cisco Smart PHY shows `ConfigurePushError` when RPD is edited with MD split enabled. |
| CSCvz77840 | `devel.log` and `audit.log` files are not rotating properly. |

# Cisco Bug Search

Use the Cisco Bug Search Tool to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.



You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.