Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats.

The *Open Caveats* section lists open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.

> **Note** The *Caveats* section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

Cisco Bug Search

Use the Cisco Bug Search Tool to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.

You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.

Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 6.1

Caveat ID Number	Description
CSCvn33389	RPHY: Support GCP TLV15, TLV40, TLV100 read from different processes
CSCvn58527	RPHY: General Error rsp for tlv read of CrashDataFileCtrl

Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 6.1

Caveat ID Number	Description
CSCvn21620	When 2nd OFDM and OOB enabled, SCQAM channel not work on 621MHz
CSCvn29690	TLV 100.2 is not working for readcount type
CSCvn13400	US channel PRE-EQ default value violate spec