



New and Changed

This chapter contains the following section:

- [New and Changed Information, on page 1](#)

New and Changed Information

The following table provides an overview of the significant changes to this guide for this release. The table does not provide an exhaustive list of all changes made to the guide or of the new features up to this release.

Table 1: New Features and Changed Information for Cisco APIC 5.1(4)

Feature	Description	Where Documented
N/A	This document has no changes from the previous release.	N/A

Table 2: New Features and Changed Information for Cisco APIC 5.1(3)

Feature	Description	Where Documented
Additional switches support uplink and downlink conversion	The Cisco N9K-C93180YC-FX3 and N9K-C93108TC-FX3P switches support uplink and downlink conversion.	Configuring Port Profiles

Table 3: New Features and Changed Information for Cisco APIC 5.1(2)

Feature	Description	Where Documented
N/A	This document has no changes from the previous release.	N/A

Table 4: New Features and Changed Information for Cisco APIC 5.1(1)

Feature	Description	Where Documented
First release of this guide	This document has no changes from the previous release.	N/A