



Additional References

This appendix contains additional information related to implementing QoS on the Cisco NX-OS device. This appendix includes the following sections:

- [RFCs, on page 1](#)

RFCs

RFCs	Title
RFC 2474	<i>Differentiated Services Field</i>
RFC 2475	<i>Architecture for Differentiated Services</i>
RFC 2697	<i>A Single Rate Three Color Marker</i>
RFC 2698	<i>A Dual Rate Three Color Marker</i>
RFC 3289	<i>Management Information Base for the Differentiated Services Architecture</i>

