New and Changed Information

This chapter provides release-specific information for each new and changed feature in the Cisco Nexus 9000 Series NX-OS High Availability and Redundancy Guide, Release 9.2(x).

New and Changed Information

This table summarizes the new and changed features for the *Cisco Nexus 9000 Series NX-OS High Availability and Redundancy Guide, Release 9.2(x)* and tells you where they are documented.

Table 1: New and Changed Features for Cisco NX-OS Release 9.x

Feature	Description	Changed in Release	Where Documented
N9K-C9332C	Introduced this switch.	9.2 (3)	Physical Redundancy
Cisco Nexus X9732C-FX and X96136YC-R line cards	Introduced these line cards.	9.2 (1)	System-Level High Availability
N9K-C9504-FM-R N9K-C9508-FM-E2 and N9K-C9516-FM-E2	Introduced these Fabric modules.	9.2 (1)	System-Level High Availability
• NXA-PDC-1100W-PE • NXA-PHV-1100W-PE	Added support for these high-voltage DC power supplies for the Cisco Nexus 93240YC-FX switch.	9.2 (1)	System-Level High Availability
NXA-PDC-440W-PI	Added support for these high-voltage DC power supplies for the Cisco Nexus 9348GC-FXP switch.	9.2 (1)	System-Level High Availability
Supervisor B+	Added support for Cisco Nexus X9600-R line cards.	9.2 (1)	System-Level High Availability