New and Changed Information

-

New and Changed Information

New and Changed Information in Cisco UCS Manager, Release 4.1(1a)

This section provides information on new feature and changed behavior in Cisco UCS Manager, Release 4.1(1a).

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.1(1a)

Feature	Description	Where Documented
Cisco UCS 64108 Fabric Interconnect	This release introduces Cisco UCS 64108 Fabric Interconnects to the Cisco UCS 6400 Series Fabric Interconnects. These Fabric Interconnects support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	Cisco UCS S3260 System Architectural Overview