New and Changed Information

- New and Changed Information for This Release, on page 1

New and Changed Information for This Release

The following table provides an overview of the significant changes to this guide for Cisco UCS Manager, Release 4.1.

Table 1: New Features and Changed Behavior in Cisco UCS Manager

Feature	Description	Where Documented
Migrating Cisco UCS 6400 Series Fabric Interconnects with UCS Central	Cisco UCS Manager supports migration of UCS 6200 Series Fabric Interconnects to Cisco UCS 6400 Series Fabric Interconnects with UCS Central.	• Considerations for migrating Cisco UCS 6200 Series Fabric Interconnects to Cisco UCS 6400 Series Fabric Interconnects with Cisco UCS Central • Migrating from UCS 6200 Series Fabric Interconnects to UCS 6400 Series Fabric Interconnects

Table 2: New Features and Changed Behavior in Cisco UCS Manager

Feature	Description	Where Documented
Migrating Cisco UCS 6400 Series Fabric Interconnects with UCS Central	Cisco UCS Manager supports migration of UCS 6454 Fabric Interconnects to Cisco UCS 64108 Fabric Interconnects with UCS Central.	• Considerations for migrating Cisco UCS 6454 Fabric Interconnects to Cisco UCS 64108 Fabric Interconnects with Cisco UCS Central • Migrating from UCS 6454 Fabric Interconnects to UCS 64108 Fabric Interconnects

Table 3: New Features and Changed Behavior in Cisco UCS Manager, Release 4.1(1)

Feature	Description	Where Documented
Cisco UCS 64108 Fabric Interconnect	This release introduces Cisco UCS 64108 Fabric Interconnects that support 10/25 Gigabit ports in the fabric with 40/100 Gigabit uplink ports.	Cisco UCS 64108 Fabric Interconnect