New and Changed Information

- New and Changed Information, on page 1

New and Changed Information

This section provides information on new features and changed behaviors in Cisco UCS Manager, Release 4.3.

Table 1: New Features and Changed Behavior in Cisco UCS Manager, Release 4.3(2c)

Feature	Description	Where Documented
Support Cisco UCS X-Series M7 servers	Cisco UCS Manager now supports Cisco UCS X410c M7 Compute Node. Cisco UCS X-Series servers support Intelligent Fabric Modules (IFM), which function similarly to the Input/Output Module (IOM) in Cisco UCS B-Series servers.	—
Support Cisco UCS VIC	Cisco UCS Manager now supports following VIC cards: • Cisco UCS VIC 15230 • Cisco UCS VIC 15427 • Cisco UCS VIC 15237 MLOM	—

Table 2: New Features and Changed Behavior in Cisco UCS Manager, Release 4.3(3a)

Feature	Description	Where Documented
Support Cisco UCS C-Series M7 servers	Cisco UCS Manager now supports Cisco UCS C220 M7 Server and Cisco UCS C240 M7 Server.	—

Feature	Description	Where Documented
Support Cisco UCS X-Series M6 and M7 servers	Cisco UCS Manager now supports Cisco UCS X210c M6 Compute Node and Cisco UCS X210c M7 Compute Node.	—
Support for Power Capping and Power Management for Cisco UCSX-9508 Chassis	Cisco UCS Manager now supports Power Capping and Power Management for Cisco UCSX-9508 Chassis.	Power Capping in Cisco UCS
Deprecated support for Cisco UCS M4 servers.	Cisco UCS Manager support for Cisco UCS M4 servers are deprecated.	—
Deprecated support for Cisco UCS 6200 series Fabric Interconnect.	Cisco UCS Manager support for Cisco UCS 6200 Series Fabric Interconnect is deprecated.	—