Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.10(1)

First Published: 2023-10-30

Last Modified: 2024-02-27

Cisco Wireless Phone 840 and 860 Release Notes for Firmware Release 1.10(1)

These release notes support the Cisco Wireless Phone 840 and 860 software release 1.10(1). These wireless smartphones require:

- **Call Control**
  - Cisco Unified Communications Manager
    - Minimum: 11.5(1)
    - Recommended: 12.5(1), 14.0(1), or higher)
  - Webex Calling
- **Wireless LAN Controller and Access Points**
- See the *Cisco Wireless Phone 840 and 860 Deployment Guide* for supported solutions.

What's New in This Release?

This release contains no new or changed features.

Note With the 1.10(1) release, the OS version will show as 1.9.1.2908 for the Cisco Wireless Phone 840 and as 1.9.0.2409 for the Cisco Wireless Phone 860; however the Apps bundle version will show as 1.10.1.2284 for the Cisco Wireless Phone 840 and as 1.10.1.2697 for the Wireless Phone 860.

Installation

Refer to the following documents for installation instructions.

840 - https://www.cisco.com/web/software/282074288/166430/cmterm-840.1-10-1-2284-83049-readme.html

860 - https://www.cisco.com/web/software/282074288/166430/cmterm-860.1-10-1-2697-83049-readme.html

Open Bugs

Bug number	Description
CSCwc20252	860–840 Bluetooth Pairing Mode Confusion vulnerability.
CSCwd73349	Conference not recorded when a user creates a conference with a call on hold.

Resolved Bugs

Bug number	Description
CSCwh97778	840/860 phones stop ringing after few hours of use, but will vibrate and present UI.

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see **Bug Search Tool Help**.

- View **All Caveats**
- View **Open Caveats**
- View **Resolved Caveats**

Americas Headquarters	Asia pacific Headquarters	Europe Headquarters
Cisco Systems, Inc. San Jose, CA	Cisco Systems (USA) Pte. Ltd. Singapore	Cisco Systems International BV Amsterdam, The Netharlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnershiprelationship between Cisco and any other company. (1110R)

© 2024 Cisco Systems, Inc. All rights reserved.