Cisco Wireless Phone 860 Release Notes for Firmware Release 2.3(1)

First Published: 2026-01-22

Cisco Wireless Phone 860 Release Notes for Firmware Release 2.3(1)

These release notes support the Cisco Wireless Phone 860 software release 2.3(1). These wireless smartphone require:

- **Call Control**
  - Cisco Unified Communications Manager
    - Minimum: 11.5(1)
    - Recommended: 12.5(1), 14.0(1), or higher
  - Webex Calling
- **Wireless LAN Controller and Access Points**
- See the *Cisco Wireless Phone 840 and 860 Deployment Guide* for supported solutions.

What's New in This Release

The Firmware release 2.3(1) is a maintenance release that includes bug fixes only. No new features are introduced in this release.

Installation

Refer to the following document for installation instructions.

860 - https://www.cisco.com/web/software/282074288/173967/cmterm-860.2-3-1-4143-89941-readme.html.

Open Bugs

Bug number	Description
CSCwr21722	CP-860 Phones not presenting DHCP Option 12 to send hostname info after upgrading to Android 13.
CSCws06155	CP-860 Phones presenting android-dhcp-13 for DHCP Option 60 after upgrading to Android 13.

Resolved Bugs

Bug number	Description
CSCwr74341	860 phones running FW 2.1.0 or later keep losing registration with CUCM.

Bug Search Tool

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see Bug Search Tool Help.

- View All Caveats
- View Open Caveats
- View Resolved Caveats

Americas Headquarters	Asia pacific Headquarters	Europe Headquarters
Cisco Systems, Inc. San Jose, CA	Cisco Systems (USA) Pte. Ltd. Singapore	Cisco Systems International BV Amsterdam, The Netharlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnershiprelationship between Cisco and any other company. (1110R)

© 2026 Cisco Systems, Inc. All rights reserved.