Release Notes for Cisco Business Mobile App, Version 1.8.0

First Published: 2024-01-31

What's New in Cisco Business Mobile App Version 1.8.0

Cisco Business Mobile app version 1.8.0 introduces the following new features and changes:

- Naming connected clients - You can now assign custom names to connected clients for easier identification and management. This feature allows for a more personalized and organized network overview.

- Find management IP of Cisco Business Wireless primary AP - Quickly and easily locate the management IP address of your Cisco Business Wireless (CBW) Primary Access Point.

- Client and SSID speed limits - Introducing new controls for managing bandwidth. You can now set speed limits for clients and SSIDs, ensuring optimal bandwidth distribution and network performance.

- LED indicator guide - Understand and diagnose common network issues easily with the device LED indicator guide.

- Wired connection mode - Wired Connection Mode enables you to configure and manage your network switches directly through a wired connection. This is particularly useful in environments where wireless access is limited or non-existent.

- Optimized site creation process - Creating a new site is now more streamlined and intuitive. We've refined the process to make it quicker and more user-friendly, saving you time and effort.

- Blink switch LED - Locate your network switches easily with our new LED blinking feature. This function allows you to identify specific switches in crowded or complex network environments.

- Portuguese language support - The app now supports Portuguese, offering an enhanced and localized experience for Portuguese-speaking users.

Caveats for Release 1.8.0

Resolved Caveats

Release Date: February 2024

No new caveats have been resolved in this release.

System Requirements for Cisco Business Mobile app

The Cisco Business Mobile app is supported for Apple iOS-based devices running iOS version 13.0 and above. The following devices can be managed by the Cisco Business Mobile app:

- Cisco Business 220 Series Smart Switches

- Cisco Business 250 Series Smart Switches

- Cisco Business 350 Series Managed Switches

- Cisco Business 100 Series Access Points

- Cisco Business 100 Series Mesh Extenders

- Cisco Business 200 Series Access Points

- Cisco Catalyst 1200 and 1300 Series switches.

Note   Cisco Business 350 Series switches with 10Gb Ethernet switch ports and a dedicated out of band (OOB) management port must be on version 3.1.1.7 or above to be installed and configured using the app. Affected models include: CBS350-8XT, CBS350-12XT, CBS350-24XT, CBS350-48XT-4X, CBS350-12XS, CBS350-24XS, CBS350-16XTS, and CBS350-24XTS.

Limitations and Restrictions

The Cisco Business Mobile app is subject to the following limitations and restrictions:

- Cisco Business and Catalyst 1200/1300 series switches need to connect to an existing Wi-Fi network to be managed by Cisco Business mobile app. Please refer to the quick start guide that comes with the switches for detailed instructions.

- The Cisco Business Mobile app is not currently optimized for the iPad. The app may be used with an iPad, but will operate in iPhone compatibility mode.

Caveats for Release 1.6.x

Resolved Caveats

Release Date: August 2023

No new caveats have been resolved in this release.

Caveats for Release 1.5.1

Resolved Caveats

Release Date: May 2023

No new caveats have been resolved in this release.

Caveats for Release 1.4.3

Release Date: December 2022

Table 1: Resolved Caveats

Caveat ID Number	Headline
CSCwc63099	A precise failure info was displayed when the password didn't comply with the complexity rules.
CSCwc66836	App displayed site summary page if killing the app when adding the remaining devices.

Caveats for Release 1.3.2

Open Caveats

Release Date: August 2022

Table 2: Open Caveats

Caveat ID Number	Headline
CSCwc63099	Should display the precise failure info when the password doesn't comply to the complexity rules. **Workaround** None
CSCwc66836	App displays site summary page if killing the app when adding the remaining devices. **Workaround** Click the Add Devices button on the site summary page, to display the devices that were scanned but did not add successfully. The app will guide you through the process of adding the missing devices to the list.

Caveats for Release 1.2.3

Resolved Caveats

Release Date: July 2022

No new caveats have been resolved in this release.

Caveats for Release 1.2.1

Open Caveats

Release Date: March 2022

The following table lists the new open caveats for Cisco Business Mobile app version 1.2.1.

Caveat ID Number	Headline
CSCwa77709	Optimize error message when applying network config failed in day-n.
CSCwa67331	View error page cannot scroll down to the bottom.
CSCwa57554	Should support select Facebook or Google Login when config social login SSID.
CSCwa57540	When adding master ap failed then close and reopen the same job, there is a small probability that the job info will be lost.

Caveats for Release 1.1.3

Resolved Caveats

Release Date: October 2021

No new caveats have been resolved in this release.

Caveats for Release 1.0.24

Resolved Caveats

Release Date: July 2021

The following table lists caveats that have been resolved in Cisco Business Mobile app1.0.24.

Table 3: Resolved Caveats

Caveat ID Number	Headline
CSCvy87281	IOS should not prompt a new version upgrade when the app is the latest version.

Caveats for Release 1.0

Open Caveats

Release Date: June 2021

The following table lists the open caveats for Cisco Business Mobile app version 1.0

Table 4: Open Caveats

Caveat ID Number	Headline
CSCvx98426	Diagnostic messages are hidden on smaller phones. **Workaround** Scroll up to view the messages.
CSCvy11159	Keyboard covers buttons on the backup page. **Workaround** Touch outside the keyboard area to dismiss the keyboard.
CSCvy11187	Interferer detection is disabled. **Workaround** Manually enable interferer detection in the CBW web UI.
CSCvy27136	Sometimes the app displays the loading icon when refreshing the site summary page. **Workaround** Pull down to refresh the page.
CSCvy40606	The app shows the switch reboot is taking longer than necessary. **Workaround** None
CSCvy45626	The invalid password message is blocked by the keyboard when typing, so it might not be seen. **Workaround** Dismiss the keyboard to see the message.
CSCvy49186	Exiting the add devices workflow is not obvious. **Workaround** Use the **Back** button at the top left to exit the workflow.
CSCvy56045	Retry config saves automatically when already it is in progress on CBW. **Workaround** Click the **Retry** link to manually repeat the save operation.
CSCvy62737	Device firmware version does not update after upgrade. **Workaround** Return to the site view and refresh the site information.

Resolved Caveats

This is the initial product version.

Where to Find Support

For current support information, visit the following URLs:

Table 5: Where to Find Support

Cisco Small Business Support Resources	
Cisco Small Business Support Community	http://www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	http://www.cisco.com/go/smallbizhelp
Phone Support Contacts	http://www.cisco.com/go/sbsc