

Compatible Systems Tech Notes: USRobotics ISDN Courier I–Everything

Document ID: 17655

Contents – Knowledge Base Article C000211

Introduction

Prerequisites

Requirements

Components Used

Conventions

USRobotics ISDN Courier I–Everything

Summary

Affected Products

Affected Versions

More Information

Related Information

Introduction

This document discusses USRobotics ISDN Courier I–Everything.

Prerequisites

Requirements

There are no specific requirements for this document.

Components Used

This document is not restricted to specific software and hardware versions.

Conventions

Refer to Cisco Technical Tips Conventions for more information on document conventions.

USRobotics ISDN Courier I–Everything

Summary

Correct dip switch settings and a chat script example.

Affected Products

900i	2200R
------	-------

1200i	2220R
1220i	2250R
1250i	2270R
1270i	3500R
2600i	3800R
2900i	VSR-2
	VSR-8

Affected Versions

All Versions

More Information

Dip switches 1 and 2 must be ON (DOWN) for the Modem. These are supposed to be the defaults, but we've found that some of the documentation diagrams on the modem are incorrect. These two switches enable AT commands and Loading data from NVRAM.

Here is a chat script that has worked:

```
send at*D0=1
send at*V2=5
send at*p=3
send atd xxxxxx ----PID#
```

Related Information

- [Technical Support & Documentation – Cisco Systems](#)

All contents are Copyright © 2006–2007 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

Updated: Mar 14, 2007

Document ID: 17655
