

End-of-Sale and End-of-Life Announcement for the Cisco MDS 9222i Multiservice Modular Switch

EOL9902

Cisco announces the end-of-sale and end-of life dates for the Cisco MDS 9222i Multiservice Modular Switch. The last day to order the affected product(s) is April 22, 2015. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9222i Multiservice Modular Switch

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 22, 2014
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 22, 2015
Last Ship Date: App. SW, HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 21, 2015
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	April 21, 2016
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	April 21, 2016
End of New Service Attachment Date: App. SW, HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 21, 2016
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	July 18, 2017
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 18, 2019
Last Date of Support: App. SW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2018
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2020

HW = Hardware OS SW = Operating System Software App. SW = Application Software

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
DS-2SLOT-FAN=	MDS 9216 Fan Tray, Spare	There is currently no replacement product available for this product.		
DS-9200-KIT-CCO	MDS 9200 Accessory Kit for Cisco	DS-9250I-KITCCO	MDS 9250i Accessory Kit for Cisco	
DS-9200-KIT-CCO=	MDS 9200 Accessory Kit, spare	DS-9250I-KITCCO=	MDS 9250i Accessory Kit, Spare	
DS-9200-KIT-DM	MDS 9200 Accessory Kit for Demo	There is currently no replacement product available for this product.		
DS-9200-KIT-EMC	MDS 9200 Accessory Kit for EMC	DS-9250I-KITEMC	MDS 9250i Accessory Kit for EMC	
DS-9200-KIT-HDS	MDS 9200 Accessory Kit for HDS	DS-9250I-KITHDS	MDS 9250i Accessory Kit for HDS	
DS-9200-KIT-HP	MDS 9200 Accessory Kit for HP	DS-9250I-KITHP	MDS 9250i Accessory Kit for HP	
DS-9200-KIT-IBM	MDS 9200 Accessory Kit for IBM	DS-9250I-KITIBM	MDS 9250i Accessory Kit for IBM	
DS-9200-KIT-NPE	MDS 9222i Accessory Kit for NPE	There is currently no replacement product available for this product.		
DS-9200-KIT-SUN	MDS 9200 Accessory Kit for SUN	There is currently no replacement product available for this product.		
DS-C9222I-HK9	MDS 9222i 18-port FC, 4- port GE Switch for HP with Service	DS-C9250IH-K9	MDS 9250i 50 port switch HP config (20xFC, 8xFCoE, 2xFCIP)	
DS-C9222I-K9	MDS 9222i 18-port FC and 4-port GE + 1-slot Modular Switch	DS-C9250I-K9	MDS 9250i 50 port switch base config (20xFC, 8xFCoE, 2xFCIP)	
DS-C9222I-NAK9	MDS 9222i 18-port FC + 4- port GE + 1-slot modular for NetApp	DS-C9250I-K9	MDS 9250i 50 port switch base config (20xFC, 8xFCoE, 2xFCIP)	
DS-C9222IEVBDL-K9	MDS 9222i Eval Bundle Component for bundle Nexus 5K - PL PID	DS-C9250I-K9	MDS 9250i 50 port switch base config (20xFC, 8xFCoE, 2xFCIP)	
DS-CAC-845W	MDS 9216 845W AC Power Supply, RESTRICTED PRODUCT	There is currently no replacement product available for this product.		
DS-CAC-845W/2	MDS 9216 845W AC Power Supply, Redundant, RESTRICTED PRODUCT	There is currently no replacement product available for this product.		
DS-CAC-845W=	MDS 9216 845W AC Power Supply, Spare, RESTRICTED PRODUCT	There is currently no replacement product available for this product.		
DS-X9222I-K9	18-port FC and 4-port GE Module for MDS 9222i	There is currently no replacement product available for this product.		
DS-X9304-18HK9=	18-port FC and 4-port GE Module for HP with Service, Spare	DS-X9316-SSNHK9=	16-Port Storage Services Node for HP with Service, Spare	
DS-X9304-18K9	MDS 9000 18-port FC and 4-port GE Module	DS-X9316-SSNK9	MDS 9000 16-Port GE Storage Services Node	
DS-X9304-18K9=	MDS 9000 18-port FC and 4-port GE Module, Spare	DS-X9316-SSNK9=	MDS 9000 16-Port GE Storage Services Node, Spare	

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
L-M9222ISSE1K9=	Storage Services Enabler on MDS 9222i	There is currently no replacement product available for this product.		
M9222ISSE1HK9=	Storage Services Enabler on MDS 9222i, HP Spare	There is currently no replacement product available for this product.		
M9222ISSE1K9	Storage Services Enabler for MDS 9222i base switch	There is currently no replacement product available for this product.		
M9222ISSE1K9=	Cisco Storage Services Enabler on MDS 9222i	There is currently no replacement product available for this product.		
MDS-9222I-75-PPT	MDS-9222I-75-PPT	There is currently no replacement product available for this product.		
MDS-9222I-FREE-SW	9222i SMB Free Software Package Promotion	There is currently no replacement product available for this product.		

Product Migration Options

Customers are encouraged to migrate to the Cisco MDS 9250i Multiservice Fabric Switch. Information about this product can be found at:

http://www.cisco.com/c/en/us/products/storage-networking/mds-9250i-multiservice-fabric-switch/index.html.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html

Customers may be able to continue to purchase Cisco MDS 9222i Multiservice Modular Switch through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: http://www.cisco.com/go/eos

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco MDS 9250i Multiservice Fabric Switch, visit http://www.cisco.com/c/en/us/products/storage-networking/mds-9250i-multiservice-fabric-switch/index.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-733131-00 10/14