



Cisco IP Phone 7800 Series with Multiplatform Firmware

- [Cisco Headset 320 Series, on page 1](#)
- [Cisco Headset 520 Series, on page 2](#)
- [Cisco Headset 530 Series, on page 2](#)
- [Cisco Headset 560 Series, on page 3](#)
- [Cisco Headset 720 Series, on page 5](#)
- [Cisco Headset 730, on page 5](#)
- [Bang & Olufsen Cisco 950, on page 5](#)
- [Bang & Olufsen Cisco 980, on page 5](#)
- [Related Documentation, on page 5](#)

Cisco Headset 320 Series

The Cisco Headset 320 Series can connect to the Cisco IP Phone 7800 Series through the RJ-9 port.

There is no minimum recommended firmware for the Cisco Headset 320 Series on the Cisco IP Phone 7800 Series.

On-premises and multiplatform headset serviceability features are unavailable through an RJ-9 connection.

Table 1: Cisco IP Phone 7800 Series

Model	Minimum Firmware	Recommended Firmware	Connection
Cisco IP Phone 7811	N/A	N/A	N/A
Cisco IP Phone 7821	N/A	N/A	RJ-9
Cisco IP Phone 7832	N/A	N/A	N/A
Cisco IP Phone 7841	N/A	N/A	RJ-9

Model	Minimum Firmware	Recommended Firmware	Connection
Cisco IP Phone 7861	N/A	N/A	RJ-9

The following table lists the available headset features on the Cisco IP Phone 7800 Series with Multiplatform Firmware.

Table 2: Cisco Headset 320 Series Features

Feature	RJ-9
Answer and end calls	No
Hold/resume calls	No
Mute/unmute calls	No
Volume control	No
Adjust sidetone	No
Adjust microphone gain	No
Adjust equalizer	No
Reset settings	No
Headset upgrades	No

Cisco Headset 520 Series

The Cisco Headset 520 Series isn't compatible with the Cisco IP Phone 7800 Series.

Cisco Headset 530 Series

The Cisco Headset 530 Series can connect to the Cisco IP Phone 7800 Series through the RJ-9 port.

There is no minimum recommended firmware for the Cisco Headset 530 Series on the Cisco IP Phone 7800 Series.

On-premises and multiplatform headset serviceability features are unavailable through an RJ-9 connection.

Table 3: Cisco IP Phone 7800 Series

Model	Minimum Firmware	Recommended Firmware	Connection
Cisco IP Phone 7811	N/A	N/A	N/A

Model	Minimum Firmware	Recommended Firmware	Connection
Cisco IP Phone 7821	N/A	N/A	RJ-9
Cisco IP Phone 7832	N/A	N/A	N/A
Cisco IP Phone 7841	N/A	N/A	RJ-9
Cisco IP Phone 7861	N/A	N/A	RJ-9

The following table lists the available headset features on the Cisco IP Phone 7800 Series.

Table 4: Cisco Headset 530 Series Features

Feature	RJ-9
Answer and end calls	No
Hold/resume calls	No
Mute/unmute calls	No
Volume control	No
Adjust sidetone	No
Adjust microphone gain	No
Adjust equalizer	No
Reset settings	No
Headset upgrades	No

Cisco Headset 560 Series

The Cisco Headset 560 Series can connect to the Cisco IP Phone 7800 Series with the Y-Cable included with the headset.



Important The Cisco Headset 560 Series Multibase is incompatible with Cisco IP Phone 7800 Series phones using Power over Ethernet (PoE). Use the external power supply if you intend to connect the multibase.

The following table contains information on which phone firmware versions are compatible with the Cisco Headset 560 Series.

Not all phone release versions may be available at the same time. For latest product version availability, see individual product support pages at [Support and Downloads](#).

Table 5: Minimum Headset Firmware

Headset Model	Minimum Firmware
Cisco Headset 560 Series	Headset Firmware 2.1(1) or later

Table 6: Cisco IP Phone 7800 Series

Model	Minimum Firmware	Recommended Firmware	Connection
Cisco IP Phone 7811	N/A	N/A	N/A
Cisco IP Phone 7821	Multiplatform firmware 11.3.(3) or later	Multiplatform firmware 11.3.(3) or later	Y-Cable
Cisco IP Phone 7832	N/A	N/A	N/A
Cisco IP Phone 7841	Multiplatform firmware 11.3.(3) or later	Multiplatform firmware 11.3.(3) or later	Y-Cable
Cisco IP Phone 7861	Multiplatform firmware 11.3.(3) or later	Multiplatform firmware 11.3.(3) or later	Y-Cable

The following table lists the available headset features on the Cisco IP Phone 7800 Series.

Table 7: Cisco Headset 560 Series Features

Feature	Y-Cable
Answer and end calls	Yes
Hold/resume calls	Yes
Mute calls	Yes
Volume control	Yes
Adjust sidetone	No
Adjust microphone gain	No
Adjust equalizer	No
Reset settings	No
Headset upgrades	Yes

Cisco Headset 720 Series

The Cisco Headset 720 Series isn't compatible with the Cisco IP Phone 7800 Series.

Cisco Headset 730

The Cisco Headset 730 isn't compatible with the Cisco IP Phone 7800 Series.

Bang & Olufsen Cisco 950

The Bang & Olufsen Cisco 950 isn't compatible with the Cisco IP Phone 7800 Series.

Bang & Olufsen Cisco 980

The Bang & Olufsen Cisco 980 isn't compatible with the Cisco IP Phone 7800 Series.

Related Documentation

Use the following sections to obtain related information.

Cisco IP Phone 7800 Series Documentation

Find documentation specific to your language, phone model, and call control system on the [product support](#) page for the Cisco IP Phone 7800 Series.

Cisco IP Phone 7800 Series Multiplatform Phones Documentation

Refer to publications that are specific to your language and phone model. Navigate from the following documentation URL:

<http://www.cisco.com/c/en/us/support/collaboration-endpoints/ip-phone-7800-series-multiplatform-firmware/tsd-products-support-series-home.html>

