



Release Notes for Cisco TrustSec 2.0 General Deployability 2011 Release

Published: November 30, 2011

The most current version of this document is available on Cisco.com at the following URL:
http://www.cisco.com/en/US/docs/switches/lan/trustsec/release/notes/rn_cts_crossplat.html

Contents

This document contains the following sections:

- [New Features, Supported Hardware and Software, page 1](#)
- [Cisco Validated Design Documents, page 2](#)
- [Caveats - TrustSec 2.0 General Availability 2011 Release, page 2](#)
- [Related Documentation, page 6](#)

New Features, Supported Hardware and Software

For a complete table of features, platforms, IOS images, and servers included in the TrustSec 2.0 release, see the *Cisco TrustSec 2.0 Product Bulletin* at the following URL:

http://www.cisco.com/en/US/netsol/ns1051/networking_solution_solution_overview_list.html



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

Cisco Validated Design Documents

For TrustSec 2.0 validated deployment and configuration scenarios, see the *Cisco TrustSec 2.0 Design and Implementation Guide* at the following URL:

http://www.cisco.com/en/US/netsol/ns1090/networking_solutions_design_guidances_list.html

Find all Cisco TrustSec CVD documents at the following URL:

http://www.cisco.com/en/US/solutions/ns340/ns414/ns742/ns744/landing_DesignZone_TrustSec.html

Find CVD documents of other Cisco solutions at the following URL:

<http://www.cisco.com/go/designzone>

Caveats - TrustSec 2.0 General Availability 2011 Release

Open Caveats

Cisco AnyConnect

Release notes for Cisco AnyConnect VPN Client:

http://www.cisco.com/en/US/products/ps8411/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCto05313	Network Access Manager	3.0	EAP-FAST:user authorization PAC issue anyconnect nam

Cisco ASR 1000 Router Series

Release notes for the Cisco ASR 1000 Series Aggregation Services Routers:

http://www.cisco.com/en/US/products/ps9343/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCtr29831	CTS	15.1(03)S	ASR1000-WATCHDOG: Process = SXP CORE when adding 1k sxp connection

Cisco Secure Access Control System (Cisco ACS)

Release notes for Cisco Secure Access Control System :
http://www.cisco.com/en/US/products/ps9911/prod_release_notes_list.html



Note

Open and resolved caveats are referred to as Known and Resolved Issues in Cisco ACS release notes.

There are no caveats reported in TrustSec General Availability Release 2.0 for the Cisco Secure Access Control System.

Cisco Identity Services Engine (Cisco ISE)

Release notes for the Cisco Identity Services Engine (ISE):
http://www.cisco.com/en/US/products/ps11640/prod_release_notes_list.html



Note

Cisco TrustSec is referred to as SGA, and CTS in Cisco ISE release notes.

Identifier	Technology	Software Release	Description
CSCtt22863	TrustSec	1.1	ISE 1.1: Issues with SGACL Addition with Internet Explorer -8

Cisco Catalyst 3500 Series Switches

Release notes for Catalyst 3750-X, 3750-E, 3560-X, 3560-E, 3750, 3560, 2960-S, and 2960 switches:
http://www.cisco.com/en/US/products/ps10144/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCti32286	ACLs	12.2(53)SE2	Failed to apply DACL on member port if it has more than 64ACEs

Cisco Catalyst 4500 Series Switches

Release notes for Catalyst 4500 Series switches:
http://www.cisco.com/en/US/products/hw/switches/ps4324/prod_release_notes_list.html

There are no caveats reported in TrustSec General Availability Release 2.0 for the Cisco Catalyst 4500 Series switches.

Cisco Catalyst 6500 Series Switches

Release notes for Catalyst 6500 Series switches:
http://www.cisco.com/en/US/products/hw/switches/ps708/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCto47606	Dot1x	12.2(33)SXI6	port-security does not work with dot1x cat6000
CSCto68925	Dot1x	12.2(33)SXI6	Dot1X Multi-AUTH- Subsequent Authz failed when addtl dACL added.
CSCtr54445	CTS	12.2(50)SY	Ping fails when cts manual is configured between C2K and C4K

Cisco Nexus 7000 Series Switches

Release notes for Nexus 7000 Series switches:
http://www.cisco.com/en/US/products/ps9402/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCtt06094	CTS	5.2	cts links bundled into L3 port channel, the port will reauthen every 30s

Resolved and Closed Caveats

CiscoWorks LAN Management Solution Server

Release notes for the CiscoWorks LAN Management Solution:
http://www.cisco.com/en/US/products/ps11200/prod_release_notes_list.html

Identifier	Technology	Software Release	Description (Closed or Resolved)
CSCtj59501	Identity	4.0	When Selecting Low impact, you can not change the host mode
CSCtj64984	Identity	4.0	LMS doesnt allow to modify the AAA RADIUS configure if AAA already set lms
CSCtj65188	Identity	4.0	Identity Readiness Assessment does not show all devices

Cisco Secure Access Control System (Cisco ACS)

Release notes for Cisco Secure Access Control System:
http://www.cisco.com/en/US/products/ps9911/prod_release_notes_list.html



Note Open and resolved caveats are referred to as Known and Resolved Issues in Cisco ACS release notes.



Note Cisco TrustSec is referred to as Security Group Access (SGA) and CTS in Cisco ACS release notes.

There are no caveats reported in TrustSec General Availability Release 2.0 for the Cisco Secure Access Control System.

Cisco Identity Services Engine (Cisco ISE)

Release notes for the Cisco Identity Services Engine:
http://www.cisco.com/en/US/products/ps11640/prod_release_notes_list.html



Note

Cisco TrustSec is referred to as Security Group Access (SGA) and CTS in Cisco ISE release notes.

Identifier	Technology	Software Release	Description
CSCtn40585	Profiler	1.0	Poor GUI response time for listing of default Profiling Policies
CSCtn99145	Authorization	1.1	multi match authorization (authz) does not match on state (access-accept
CSCtq66518	CTS	1.1	Deleting the SGACL mapping from ISE does not clear the downloaded policy
CSCtq76895	TrustSec	1.1	ISE: Cannot create RBACL list with 110 entries positron
CSCtr92353	TrustSec	1.1	ISE : Positron sending wrong SGT during AUTHEN phase positron
CSCtt10180	TrustSec	1.1	ISE292: Environment data lifetime not updated with Device Changes-CoA positron

Cisco Catalyst 3500 Series Switches

Release notes for Catalyst 3750-X, 3750-E, 3560-X, 3560-E, 3750, 3560, 2960-S, and 2960 switches:
http://www.cisco.com/en/US/products/ps10144/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCtt05256	MACsec	15.0(1)SE1	No traffic is passing through btw 3k-7k link when sap mode null is set
CSCtt06233	CTS	15.0(1)SE1	ping traffic failed to pass through ndac link btw 3k-7k on some config

Cisco Catalyst 4500 Series Switches

Release notes for Catalyst 4500 Series switches:
http://www.cisco.com/en/US/products/hw/switches/ps4324/prod_release_notes_list.html

There are no caveats reported in TrustSec General Availability Release 2.0 for the Cisco Catalyst 4500 Series switches.

Cisco Catalyst 6500 Series Switches

Release notes for Catalyst 6500 Series switches:
http://www.cisco.com/en/US/products/hw/switches/ps708/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCtk84193	CTS	12.2(50)SY	Seeing "TCP-6-BADAUTH: No MD5 digest" msg although sxp connection is on

Identifier	Technology	Software Release	Description
CSCto03011	Dot1x	12.2(33)SX15	dACLs not always applied to interface
CSCto56787	Dot1x	12.2(33)SX16	CWA environment does not apply ACL in EPM 6503
CSCtr54445	CTS	12.2(50)SY	Ping fails when cts manual is configured between C2K and C4K
CSCtr92862	CTS	12.2(50)SY	Switch failed to download RBACL policy associating to static SGT

Cisco Nexus 7000 Series Switches

Release notes for Nexus 7000 Series switches:

http://www.cisco.com/en/US/products/ps9402/prod_release_notes_list.html

Identifier	Technology	Software Release	Description
CSCtr95105	CTS	5.2	When sxp default passwd is set, N7k will disable & reenable sxp feature
CSCts33115	CTS	5.2	Unable to ping across CTS link between N7k and ASR

Related Documentation

Document Title	TrustSec Topics
Cisco TrustSec Switch Configuration Guide	<ul style="list-style-type: none"> TrustSec feature configurations for Cisco Catalyst series switches System error messages
Cisco Secure Access Control System	
Cisco Secure Access Control System Release Notes	Open and resolved caveats, referred to as Known and Resolved issues in Cisco ACS documentation
Cisco Secure Access Control System End-User Guides	Cisco Security Group Access configurations for Cisco ACS 5.1 and more recent releases
Cisco Identity Services Engine	
Release Notes for Cisco Identity Services Engine	Open and resolved caveats
Cisco Identity Services Engine User Guide	Configuring Cisco Security Group Access policies
Catalyst 3000 Series Switches	
Release Notes for Catalyst 3560 and 3750 Switches	Open and resolved caveats
Catalyst 3560 Software Configuration Guides	802.1x configuration procedures
Catalyst 3750 Switch Software Configuration Guides	

Document Title	TrustSec Topics
Catalyst 3750-X Switch Software Configuration Guides	<ul style="list-style-type: none"> • 802.1x configuration procedures • SXP • MACsec
Catalyst 4500 Series Switches	
Release Note for the Catalyst 4500 Series Switch	Open and resolved caveats
Catalyst 4500 Series Switch Software Configuration Guides	802.1x configuration procedures
Catalyst 6500 Series Switches	
Catalyst 6500 Series Release Notes	Open and resolved caveats
Catalyst 6500 Series Software Configuration Guides	802.1x and TrustSec configuration procedures
Nexus 7000 Series Switches	
Cisco Nexus 7000 Series Switches Release Notes	Open and resolved caveats
Cisco Nexus 7000 Series Switches Configuration Guides	<ul style="list-style-type: none"> • TrustSec feature configurations for Cisco Nexus 7000 Series switches, Release 4.1 and more recent releases • 802.1x configuration procedures

Cisco IOS Software Documentation

Cisco IOS Document Title	TrustSec Topics
Cisco TrustSec Configuration Guide Cisco IOS XE Release 3S	Router-based SXP configuration
Cisco IOS Master Command List, All Releases	802.1x; SXP

