
Release Notes for WIP310 Firmware Version 5.0.13

February 2011

These Release Notes describe the known issues in WIP310 firmware version 5.0.13.

NOTE New Wi-Fi package from chip maker has been integrated into the WIP310 and Wi-Fi stability improved.

Contents

This document includes the following topics:

- [Resolved Issues In WIP310 Firmware Version 5.0.13](#)
- [Related Information](#)

Resolved Issues In WIP310 Firmware Version 5.0.13

The following problems were fixed:

- WIP310 registration issue. The WIP310 no longer sends registration request.
- The SIP T1 timer needs to be set to 2 seconds and the Retry Reg RSC in the SIP tab needs to be set to 401.
- If the day light saving rule is not correct, the WIP310 hangs.
- Shared call appearance fails with Broadsoft R15.
- Cannot disable factory reset by setting **protect ivr factory reset** to yes.
- User-downloaded ringtones do not work.
- Time offset fails.
- Ringtone inconsistency when the headset is connected.
- Ringing is also routed to the headset.
- WIP310 fails to register to the trixbox.

Related Information

Support	
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/go/sbsc
Cisco Small Business Firmware Downloads	<p>www.cisco.com/go/smallbizfirmware</p> <p>Select a link to download firmware for Cisco Small Business Products. No login is required.</p> <p>Downloads for all other Cisco Small Business products, including Network Storage Systems, are available in the Download area on Cisco.com at www.cisco.com/go/software (registration/login required).</p>
Product Documentation	
Cisco WIP310	www.cisco.com/en/US/products/ps10033/tsd_products_support_series_home.html
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco, Cisco Systems, the Cisco logo, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0705R)

© 2011 Cisco Systems, Inc. All rights reserved.

OL-18493-01