

## Change in Product Part Number Announcement for the Cisco 12000 40C12

EOL6160

Cisco® announces a change in product part numbers for the Cisco 12000 40C12. This is a product part number change only announcement. Customers will experience no change in functionality when using the new product IDs. The new product IDs are designed to simplify the customer ordering process. The last day to order the affected product using the current product IDs is April 1, 2001. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until otherwise specified in the end-of-life announcement for the new product ID(s). Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

The Cisco 12000 40C12/STM-4 line card provides a unique combination of performance and class-of-service (CoS) features for delivering advanced end-to-end networking features.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 12000 40C12

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 29, 2000
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 1, 2001
<b>End of Service Contract Renewal Date</b> HW	The last date to extend or renew a service contract for the product.	January 31, 2005
<b>Last Date of Support:</b> HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 31, 2006

HW = Hardware OS SW = Operating System Software App. SW = Application Software

### End of Sales for Cisco 12000 40C12E/POS-XX-SC (Non-B) Versions

The non-B parts will be orderable for up to three weeks starting from the release of this announcement. Thereafter, the non-B parts will be orderable only as spares. Full orderability will end on April 1, 2001.

### End of Support

These products will no longer be supported by Cisco after January 31, 2006.

A detailed description of the problem can be found in Field Notice 12889 at:

[http://www-tac.cisco.com/Support\\_Library/field\\_alerts/fn12889.html](http://www-tac.cisco.com/Support_Library/field_alerts/fn12889.html)

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
4OC12E/POS-IR-SC	4 Port OC-12/STM-4 SONET/SDH Single Mode IR with SC	4OC12/POS-IR-SC-B	NA
4OC12E/POS-IR-SC=	4 port OC-12/STM4 SONET/SDH Single-Mode IR with SC=	4OC12/POS-IR-SC-B=	NA
4OC12E/POS-MM-SC	4 Port OC-12/STM-4 SONET/SDH Multi-mode with SC	4OC12/POS-MM-SC-B	NA
4OC12E/POS-MM-SC=	4 port OC-12/STM4 SONET/SDH Multi-Mode with SC=	4OC12/POS-MM-SC-B=	NA

### Product Migration Options

The part number change is due to design optimizations on the current interface card.

These optimizations have led to the need for a new version of Cisco IOS® Software (12.0(10)S or greater and 11.2(19)GS5 or greater).

The new B parts will not change any functionality or performance in the 4OC-12/STM-4 interface module. Both the existing version of 4OC-12/STM-4 and the new "B" version of 4OC-12/STM-4 interfaces are the same in form fit and function when running with Cisco IOS image 12.0(10)S or higher or Cisco IOS image 11.2(19)GS5 or higher.

Cisco strongly recommends that all existing 4OC-12/STM-4 orders that have not been shipped be converted to reflect the new B part number.

### Upgrade

Customers wishing to upgrade from existing non-B versioned 4OC-12/STM-4 line cards to new B versioned 4OC-12/STM-4 line cards should follow the technology migration plan guidelines located at: <http://www.cisco.com/web/partners/pr11/incentive/index.html>

Calculations for credits/trade-in values can be found by using the Technology Migration Plan (TMP) Calculator found under: <http://www.cisco.com/go/tradein>

**Table 3.** Summary of Cisco IOS version requirements on the Packet over SONET (POS) interface card

Product Part Number	Cisco IOS 12.XX	Cisco IOS 11.XX
4OC12E/POS—Non B	12.0(6)S or greater	11.2(18)GS2 or greater
4OC12/POS—B version	12.0(10)S or greater	11.2(19)GS5 or greater

The new 4OC12/POS B versions will have the same prices as the existing 4OC12E/POS non-B versions:

4OC12/POS-IR-SC-B	\$80,000
4OC12/POS-MM-B	\$70,000

## For More Information

For more information about the 4012E/POS B versions, visit <http://www.cisco.com/en/US/products/hw/routers/ps167/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

Note EOL6160 is a reposting of previous Product Bulletin #1247, with minor updates that do not have an impact on dates or support terms.



Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 535-4000  
800 352-1337  
Fax: 408 535-4000

Asia Pacific Headquarters  
Cisco Systems, Inc.  
150 Robinson Road  
#23-01, Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6517 7777  
Fax: +65 6517 7750

Europe Headquarters  
Cisco Systems International BV  
Haslerbergweg 13-18  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: +31 20 900 026 0101  
Fax: +31 20 900 057 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Altran, BPX, Catalyst, CCDA, CCDP, CCE, CCR, CCNA, CCRP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IPPhone, IPTV, IQ Expertise, the IQ logo, iQ Net Readiness Scorecard, iQuickStudy, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PDK, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0701R)