



END-OF-LIFE NOTICE, NO. 2407

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 3631

Cisco Systems® announces the End-of-Life of the Cisco® 3631. The last day to order the Cisco 3631 is August 2, 2004. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until August 2, 2009. Table 1 describes the End-of-Life milestones, definitions, and dates for the Cisco 3631.

Customers are encouraged to migrate to the Cisco 2691 or Cisco 3725, which offers greater module support and additional software features. Information about these products can be found at <http://www.cisco.com/go/3700demo>. Table 4 provides relevant information for migrating from the Cisco 3631 to the Cisco 2691 or Cisco 3725.

Table 1. End-of-Life Milestones and Dates for the Cisco 3631

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the End-of-Sale and End-of-Life of a product is distributed to the general public.	February 2, 2004
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 2, 2004
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead-time.	November 2, 2004
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	August 2, 2006
End of Routine Failure Analysis Date	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	August 2, 2005
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 2, 2005
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	May 2, 2009
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 2, 2009

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
CISCO3631-CO-AC	Cisco 3631-CO with AC Power Supply
CISCO3631-CO-DC-U	3631 Router w/Universal Power Supply, 24/48 volts
CISCO3631-CO-DC	Cisco 3631-CO with DC Power Supply
MEM3631-128D=	128-MB DIMM DRAM for the Cisco 3631
MEM3631-32U128CF	32- to 128-MB Compact Flash factory upgrade for the Cisco 3631
MEM3631-32U64CF	32- to 64-MB Compact Flash factory upgrade for the Cisco 3631
MEM3631-64D=	64-MB DIMM DRAM for the Cisco 3631
MEM3631-64U128D	64- to 128-MB DIMM DRAM factory upgrade for the Cisco 3631
MEM3631-64U256D	64- to 256-MB DIMM DRAM factory upgrade for the Cisco 3631
All 3631 IOS Software Products	All IOS Software SKUs for the 3631 (IOS updates will be available for SMARTnet® customers on http://www.cisco.com/ until March 31, 2006)

Note: Customers who require memory upgrades after the End-of-Sale date for the Cisco 3631 can order Cisco 2691 memory upgrade parts.

PRODUCT MIGRATION OPTIONS


The recommended replacements for the Cisco 3631 are the Cisco 2691 and Cisco 3725. The comparable product numbers are shown in Table 3. Comparisons between the products are shown in Table 4.

Table 3. Replacement Product Numbers

3631 Product Number	2691 Product Number	3725 Product Number
CISCO3631-CO-AC	CISCO2691	CISCO3725
CISCO3631-CO-DC	CISCO2691-DC-U	CISCO3725-DC-U
CISCO3631-CO-DC-U	CISCO2691-DC-U	CISCO3725-DC-U

Table 4. Product Comparisons

Feature	Cisco 3631	Cisco 2691	Cisco 3725
Chassis Depth	Less than 12 inches (300 mm)	Less than 12 inches (300 mm)	14.7 inches (375 mm)
Integrated 10/100 Ethernet Ports	1	2	2
Network Module Slots	2	1	2
WIC Slots	2	3	3
AIM Slots	1	2	2
Module Support	Limited Network Module, AIM, and WIC support	Full Network Module, AIM, and WIC support	Full Network Module, AIM, and WIC support
Software Support	Telco, Telco Plus, and Telco Plus IPSec	Full IOS feature set support	Full IOS feature set support
Power Input	AC, -48 VDC, or universal DC (24-72V)	AC, external redundant AC, or universal DC (24-72V)	AC, external redundant AC, or universal DC (24-72V)



Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

ADDITIONAL INFORMATION

For more information about Cisco products, please contact your Cisco account manager or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive EoL/EoS information, please go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

